Dur. 4

MASTER

WASH 1192(Par.)

OPERATIONAL

ACCIDENTS

and RADIATION EXPOSURE EXPERIENCE

Within the

UNITED STATES
ATOMIC ENERGY
COMMISSION

1943-1975

DIVISION OF OPERATIONAL SAFETY

NOTICE

This report was prepared as an account of work sponsored by the United States Government. Neither the United States nor the United States Energy Research and Development Administration, nor any of their employees, nor any of their contractors, subcontractors, or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infringe privately owned rights.

Available from:

National Technical Information Service (NTIS)

U.S. Department of Commerce

5285 Port Royal Road

Springfield, Virginia 22161

Price:

Printed Copy: \$6.75 Microfiche: \$ 2.25

iteroffene: \$ 2.2

DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency Thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

DISCLAIMER


Portions of this document may be illegible in electronic image products. Images are produced from the best available original document.

OPERATIONAL

ACCIDENTS

and RADIATION EXPOSURE EXPERIENCE

Within the



This report was prepared as an account of work sponsored by the United States Government Neither the United States nor the United States Energy Research and Development Administration, nor any of their contractors, or any of their contractors, or their employees, makes any legal lability or responsibility for the accuracy, completeness or usefulness of any information, apparatus, product or process disclosed, or represents that its use would not infinge privately owned rights

UNITED STATES ATOMIC ENERGY COMMISSION

DIVISION OF OPERATIONAL SAFETY WASHINGTON, D. C. 20545

ISSUED FALL 1975



TABLE OF CONTENTS

	Pag
PREFACE	1
PART I—ORGANIZATION	2
PART II—DEFINITIONS	3
PART III—AEC EXPERIENCE—PERSONNEL	5
Section 1—General	5
Chart I—Death Rates AEC-NSC 1943-1974	6
Chart II—Causes of Fatalities in AEC Programs 1943-1975	6
Chart III—Disabling Work Injuries (Operations) 1943–1975	7
Frequency	8 8
Severity	9
Chart V—Injury Severity Rates AEC-NSC 1943-1974	9
Section 2—Radiation Exposures	10
Chart VI-Radiation Exposure of AEC and AEC Contractor Personnel to Whole-	
Body Penetrating Radiation	10 11
Chart VII—Radiation Accidents Resulting in Lost-time Injuries	12
Chart IX—Time Lost from Radiation Injuries AEC Operations 1943–1975	14
PART IV—AEC EXPERIENCE—PROPERTY DAMAGE	15
Section 1—General	15
Chart X-AEC Incidents Causing Over \$50,000 Property Loss or Damage	17
Chart XI—AEC Property Damage Ratios 1947-1974	18
Chart XII—AEC Fire Loss Ratios 1947–1974	19
Chart XIII—Causes of AEC Property Damage by Contamination 1955–1974	20
Chart XIV—Summary of All Incidents Causing Over \$50,000 Property Damage or Loss in the History of the AEC—1943–1975	21
Section 2—Criticality Accidents	29
·	
Chart XV—Criticality Accidents in USAEC Facilities	30
PART V—BEST NO-INJURY RECORDS KNOWN IN AEC ACTIVITIES	39
APPENDIX A—FATALITIES	40
APPENDIX B—RADIATION EXPOSURES OVER 15 REM	53
APPENDIX C—REPORTABLE ACCIDENTS, INCIDENTS, AND RADIATION EXPOSURES 1959–1975	59
APPENDIX D—CRITERIA FOR REPORTABLE INCIDENTS	147

PREFACE

The protection of persons and property against potential hazards in Atomic Energy Commission (AEC) activities was a fundamental concern of the AEC from the earliest developments in the use of atomic energy. The AEC evolved a new technology and a safety program adapted to its special purposes. The agency's goal was to develop and utilize this vital national resource to the maximum extent consistent with a high degree of safety.

The Atomic Energy Act of 1954, as amended, clearly demonstrates vital concern with the health and safety of the worker and the public. For example, in section 161(i) of the Act, Congress stipulated that, in the performance of its functions, the AEC was authorized to:

"prescribe such regulations or orders as it may deem necessary...(3) to govern any activity authorized pursuant to this Act, including standards and restrictions governing the design, location, and operation of facilities used in the conduct of such activity, in order to protect health and to minimize danger to life or property..."

Other examples include section 31(d) (Research Assistance):

"The arrangements made pursuant to this section shall contain such provisions (1) to protect health, (2) to minimize danger to life or property . . . as the Commission may determine."

and section 41(b) (Production Facilities):

"... Any contract entered into under this section shall contain provisions . . . obligating the contractor . . . to comply with all safety and security regulations which may be prescribed by the Commission . . ."

In 1965 we gathered available information, descriptions, and statistics regarding disabling injuries, radiation exposures, contaminations, criticalities, fatalities, and property damage accidents, and presented these and other relevant data under one cover entitled, "Operational Ac-

cidents and Radiation Exposure Experience within the United States Atomic Energy Commission 1943–1964." The present publication represents the third time that the original has been revised on a three-year basis. It is hoped that this information will (1) assist in answering the numerous requests regarding the accident record of the AEC and (2) provide an historical summary of this experience.

As in any industrial organization, the AEC's accident experience fell into two major classifications: (1) that which resulted in harm to people and (2) that which resulted in damage of property. However, because of the unique nature of the atomic industry, both of these classifications must be subdivided into: (1) those occurrences which are not atomic energy-connected and (2) those occurrences which are atomic energy-connected

In a 1956 publication, covering the period 1945–55, it was stated: "By far the most numerous (accidents) are those in no way related to atomic energy. Falls, electrocutions, motor vehicle accidents, and construction equipment accidents comprise the majority of accidents." This was not a surprising statement at that time, since so much construction work was in progress 'during those years. However, it is interesting to note that it was still true in 1975, although in the 20 years since 1955, while construction decreased, the use of atomic energy greatly increased, as did the number of employees in occupations involving potential radiation exposure.

In summary, because of the AEC's singular involvement in radiation hazards, people were prone to emphasize those occurrences resulting in exposures, contaminations, and criticalities. Actually these occurrences were in the minority in the overall picture and by far the majority of the occurrences within the AEC were comparable, in kind, to those occurring within any industrial organization.

PART I

ORGANIZATION

From the establishment of the Atomic Energy Commission (AEC) by the Atomic Energy Act of 1946 until the abolition of the Commission by the Energy Reorganization Act of 1974, the AEC was responsible for the management of a complex of Government-owned nuclear energy facilities. Their design, construction, and operation was by contract with industrial, academic, and nonprofit organizations, rather than directly by Government employees. The operations at these facilities included the production and processing of special nuclear and radioactive materials, the development of nuclear reactors, the development of nuclear explosives, and research in the physical and biological sciences. The total investment in these facilities was over twelve billion dollars.

A major part of the AEC's research was conducted at several national laboratories and three weapons development laboratories. Various production facilities were operated for the AEC and included nuclear feed materials plants, three uranium gaseous diffusion plants for producing enriched uranium, and two plutonium production complexes. Weapons testing was conducted at the Nevada Test Site. Similarly, various contractors operated test facilities at the National Reactor Testing Station in Idaho and at the Nuclear Rocket Development Station in Nevada.

The 1954 revision of the Atomic Energy Act established a comprehensive system of regula-

tory control over the private use of nuclear and radioactive by-product materials.

To implement these responsibilities of operation and regulation, there was a dual organization in which the regulatory activities were separated from promotional and developmental activities. The General Manager, with operational and promotional staffs, administered and directed operations being conducted for the AEC; the Director of Regulation, with his staff, carried out the regulatory program for licensed activities and assisted the General Manager in the technical review of certain reactor proposals.

The AEC had field offices near its major sites to assist the General Manager in conducting the AEC's operations. Each office administered contracts within its area of jurisdiction with organizations operating the facilities or otherwise under contract with the AEC. The Director of Regulation established regional offices in various parts of the United States from which licensee inspections and compliance activities were conducted. Through these contractual and regulatory systems, AEC maintained Governmental control and direction in the areas of health and safety.

The material included herein covers the experience of operational activities (not regulatory) during the period 1943-75, incorporating both information pertaining to the Manhattan Engineer District, predecessor to the AEC, as well as that of the AEC itself.

PART II

DEFINITIONS

Explanations of Terms Used in This Publication

- ACCIDENT (INCIDENT)—The unexpected occurrence in a sequence of events which produces death, injury, radiation exposure, or property damage.
- AEC-Atomic Energy Commission.
- AEC CONSTRUCTION—Includes lump-sum, cost-plus, and architect-engineering contractors.
- AEC FIELD OFFICES—See names and abbreviations listed in appendix A, page 52.
- AEC OPERATIONAL ACTIVITIES—Includes AEC and AEC contractor personnel engaged in AEC operations and AEC construction.
- AEC OPERATIONS—Includes production, research, and services contractors.
- ANSI—American National Standards Institute. ANSI Z16.1—Method of Recording and Measuring Work Injury Experience. Standard used by the AEC.
- BODY BURDEN—The amount of radioactive material present in the body of man or animals.
- CHAIN REACTION—A reaction that stimulates its own repetition. In a fission chain reaction, a fissionable nucleus absorbs a neutron and fissions, releasing more than one additional neutron. These in turn can be absorbed by other fissionable nuclei, releasing more neutrons. A fission chain reaction is self-sustaining when the number of neutrons released in a given time interval equals or exceeds the number of neutrons absorbed.
- CONTAMINATION—The presence of unwanted radioactive particulate matter.
- CRITICAL MASS—The smallest mass of fissionable materials that will support a self-sustaining chain reaction under stated conditions.

- DEATH RATE—The number of deaths per 100,000 workers.
- DISABLING (LOST-TIME) INJURY—A work injury which results in death, permanent total disability, permanent partial disability, or temporary total disability as defined in ANSI Z16.1.
- FIRE LOSS RATIO—Cents loss per \$100 of AEC property.
- FISSIONABLE MATERIALS—Isotopes capable of being fissioned by neutrons.
- FREQUENCY RATE—The number of disabling injuries per 1,000,000 man-hours worked.
- GLOVEBOX (DRYBOX)—A sealed box in which workers, using gloves attached to and passing through openings in the box, can handle radioactive materials safely.
- MAN-DAY—The equivalent of one man working one eight-hour day.
- MAN-HOUR—The equivalent of one man working one hour.
- MED—Manhattan Engineer District.
- NSC-National Safety Council.
- NUCLEAR CRITICALITY—The state in which the effective neutron multiplication constant (k_{eff}) of a system of fissionable material equals or exceeds unity.
- NUCLEAR SAFETY (Bimonthly Technical Progress Review)—Available from Superintendent of Documents, U.S. Government Printing Office, Washington, D.C. 20402.
- PROPERTY DAMAGE RATIO—Cents loss per \$100 of AEC property.
- REM—Roentgen equivalent man. A unit of absorbed dose in biological matter. It is equal to the absorbed dose in rads multiplied by the relative biological effectiveness of the radiation on the part of the body of concern.
- ROENTGEN-A unit of exposure dose of ion-

izing radiation. It is that amount of gamma or X-rays required to produce ions carrying one electrostatic unit of electrical charge in one cubic centimeter of dry air under standard conditions.

SEVERITY RATE—The number of days charged per 1,000,000 man-hours worked.

TID (Technical Information Document)—
Available from Clearinghouse for Federal
Scientific and Technical Information, National Bureau of Standards, U.S. Department

of Commerce, Springfield, Va. 22151. (Note: TID-5360, Suppl. 6. Available from Superintendent of Documents, U.S. Government Printing Office, Washington, D.C. 20402.)

USAEC HEALTH & SAFETY INFORMATION ISSUE

USAEC SERIOUS ACCIDENTS ISSUE Available (if not out of print) from Division of Operational Safety, U.S. Atomic Energy Commission, Washington, D.C. 20545.

PART III

AEC EXPERIENCE—PERSONNEL

Section 1

GENERAL

The occupational injury and fatality experience, through 32 years of the development of the atomic energy industry under the guidance and direction of the Atomic Energy Commission (AEC) and its predecessor, the Manhattan Engineer District, demonstrated that when management vigorously promotes accident prevention programs, aimed at a specific type of injury, the occurrence of the injury can be practically eliminated.

The early unknown qualities and effects of nuclear energy provided the incentive to develop the most effective specialized injury prevention program ever devised, with the result that, during 32 years, there were only six deaths attributable to nuclear causes. Three of these occurred at Los Alamos (August 21, 1945, May 21, 1946, December 30, 1958) and were a direct result of exposure to a massive dose of nuclear radiation. The immediate causes of death in the three additional fatalities were the physical effects (i.e., blast, flying missiles, etc.) associated with the SL-1 reactor excursion of January 3, 1961; however, the radiation levels associated with that accident were extremely high and probably would have been fatal. It is also significant that during these 32 years there were only 38 workers involved in lost-time radiation nonfatal accidents.

¹On July 24, 1964, the first nuclear fatality in a licensed operation occurred as a result of a nuclear criticality accident at a recovery plant for enriched uranium scrap near Charleston, R.I.

These accidents, producing ionizing radiation exposures, were caused by human error, faulty manipulation of controls, deviation from standard operating procedures, faulty mechanical equipment, and other causes such as may be encountered in any other industry.

Fatalities from all causes totaled 321 during the 32-year period (see Charts I and II). Of this number, 184 occurred in construction, 121 in AEC operations (production, research and services), and 16 in Government functions. A list of fatalities occurring in AEC operational activities appear in Appendix A.

During this period, there were 19,225 losttime injuries (as defined in ANSI Z16.1) attributable to all accidental causes. This gives a 32-year frequency rate (number of injuries per million man-hours) of 2.75. Of the lost-time injuries 52% (10.086) occurred in AEC operations. This was the experience of 874,662,810 man-days of potential accident exposure, which produced nearly seven billion man-hours of work and a 32-year frequency rate of 2.01. As indicated above, only 41 of the 10,086 lost-time injuries, four-tenths of one percent (0.4%), were caused by nuclear radiation. This is equivalent to a frequency rate of 0.01. A list of radiation injuries occurring in AEC operations appears in Chart VIII.




Chart I
DEATH RATES AEC — NSC 1943 TO 1974




Chart II
TYPES OF FATALITIES IN AEC PROGRAMS
1943 TO 1975

In the AEC's construction activities, there were 8,210 injuries, resulting in a 32-year frequency rate of 5.24. This rate compares very favorably with the average frequency rate of the National Safety Council (NSC) of 16.8 for construction (1943–1974).

The 32-year Government (Federal employees) frequency rate was 2.25 (938 lost-time injuries). AEC Government experience won the President's Award, covering accident prevention among Federal employees, in 1957, 1959, 1960, 1962, 1970, and 1973. The AEC earned these awards in the small-agency category.

The AEC's overall industrial accident experience has always been lower than the all-industry rate reported by 41 industries in the United States to the NSC. The average NSC 32-year rate of all industry is 8.8 compared to the 32-year AEC frequency rate of 2.8.

	BODY AREA	PERCENT
	EYES	3
17	HEAD	6
	ARMS	8
The Royal Brown	TRUNK	25
A N D	HANDS	6
	FINGERS	21
	LEGS	11
	FEET	5
NIII I	TOES	3
H	GENERAL	12

* 121 DEATHS

Chart III
DISABLING WORK INJURIES
(Operations) 1943 TO 1975
10,086*

Frequency

In 1945, and prior thereto, the pressures of war, such as heavy construction work, urgency, and shortages, all combined to produce relatively high accident frequency rates in AEC operations, although they were always below NSC rates. By 1950, the rate for work in operation had dropped to about 3.0 injuries per million man-hours. From then on, operation frequency rates were low by comparison with other industries. In 1947 through 1949, a renewed heavy construction program produced a construction injury rate of about 10.0. This

held the overall frequency rates of the AEC up in those years. A vigorous program concentrating on control of accidents in construction brought the frequency down again, and since 1958, the total frequency for all activities has been 2.2 or less. The proportion of construction work thereafter was small enough to be ineffective, in the overall, even though the construction rate was up in 1959. It is notable that the trend of AEC's injury frequency (see Chart IV) in all its operations throughout the years is roughly parallel to the national average, but from a fourth to a third of the national rate.




Chart IV


INJURY FREQUENCY RATES AEC - NSC 1943 TO 1974

Severity

As stated regarding the AEC frequency rate, the AEC severity rate was affected adversely by the large amount of construction work during its early years.

In 1951, the AEC severity rate and the NSC severity rate were the same. Both have declined over the years; however, that of the AEC shows a greater decrease (see Chart V).

It is to be noted that a severity rate may fluctuate markedly from year to year, depending upon the fatalities and types of disabilities occurring. Whereas the actual calendar days lost are charged for temporary total injuries, charges are based on 6,000 days for a death or permanent disability, with proportionately fewer days being charged for permanent partial disabilities of varying degrees of seriousness. Thus, fatalities and certain types of injuries can result in decided peaks in a severity rate.



* NUMBER OF DAYS CHARGED PER MILLION MAN-HOURS

Chart V
INJURY SEVERITY RATES AEC — NSC 1943 TO 1974

Section 2

RADIATION EXPOSURES

In accordance with its health and safety responsibilities, the AEC conducted its activities in such a manner as to assure that employee radiation exposures were reduced to the lowest practical levels within established limits. To carry out this responsibility, it was necessary for the AEC and its contractors to monitor routinely all employees who might receive a significant radiation dose.

AEC and AEC contractor employee exposures for the past 28 years are summarized in Chart VI. This chart shows that during this 28-year period over 99.8% of the employees monitored received an annual dose of less than 5 rem and that over 94.8% received one rem or less.


The majority of exposures in excess of five rem in a year resulted from accidental situations. The more significant (15 rem and over) of these accidental exposures are briefly summarized in Appendix B.

During the 32 years of operation of the AEC and its predecessor, radiation resulted in a very small percentage (0.4) of the total lost-time injuries from all causes as indicated in Chart VII. These specific radiation exposures were classified as lost-time injuries as defined in the American National Standards Institute methods for reporting work injuries, ANSI Z16.1–1967 (Rev. of Z16.1–1954) and AEC directives.

CHART VI
RADIATION EXPOSURE OF AEC AND AEC CONTRACTOR PERSONNEL
TO WHOLE-BODY PENETRATING RADIATION

YEARS			REM DOSE		
IEANS	0-1	1-5	5-10	10-15	>15
1947-54	130,128	5,311	284	32	(
1955	56,708	3,157	285	41	
1956	38,225	2,312	100	4	3
1957	45,510	2,424	83	5	1
1958	59,455	6,271	159	10	12
1959	71,600	3,912	66	2	1
1960	77,522	4,629	41	2	1
1961	90,651	5,174	40	3	8
1962	122,437	5,707	113	0	8
1963	107,786	5,472	80	0	1
1964	122,711	6,157	86	11	(
965	128,360	6,671	175	8	(
1966*	131,522	6,242	167	0	2
1967*	102,510	5,767	108	1	(
1968	103,206	4,776	4	0	(
1969	98,625	4,288	4	1	(
1970	92,185	4,464	12	0	(
1971	90,640	3,661	12	1	1
1972	86,077	3,373	10	0	(
1973	89,071	2,903	3	0	(
1974	73,845	2,318	3	0	
TOTAL	1,918,774	94,989	1,835	121	45

^{*} Totals for 1966 and 1967 differ from those shown in previous editions of this publication, due to the discovery of an error in the radiation exposure records of one major contractor.



* 3 FATALITIES AT SL-1 (Caused by explosion) NOT INCLUDED

Chart VII RADIATION INJURIES 1943 TO 1975 AEC Operations

Of the 41 workers involved in lost-time radiation accidents, 3 died, 26 showed clinical manifestations attributable to radiation, and 12 were without evidence of radiation effects. Of the second group, 3 received permanent partial disabilities due to radiation, 3 required removal of a digit because of deposition of plutonium in tissue, and one other required removal of a digit because of direct X-ray damage.

Eleven persons listed as having "lost-time injuries" actually had no evidence of clinical radiation effects but were classified as lost-time injuries because they were removed from work and hospitalized for diagnostic tests. Such tests

were negative in these cases but loss of time was charged according to ANSI standards for hospitalizations. The other person also had no evidence of clinical radiation effects but was away from work as a result of efforts to remove plutonium from his lungs by lavage.

Additional information on these injuries concerning date and location of accident and nature and extent of injury are found on Chart VIII. Chart IX provides a comparison of total time lost from injuries due to radiation and to other causes. It is evident from the chart that radiation exposure was responsible for only a small part of the time lost due to injuries.

Chart VIII RADIATION ACCIDENTS RESULTING IN LOST-TIME INJURIES

(As defined in American National Standards Institute Method of Recording and Measuring Work Injury Experience—ANSI Z16 1-1967 (Revision of Z16.1-1964) and AEC Directives)

Date	Location	Number Involved	Source of Injury	Nature of Injury	Expo	sure	Days Lost
	and the program of the control of th				80 KV X-Ray	GAMMA RAY	
8/21/45	Los Alamos	Two	Chain reaction in experi mental critical assembly	(1) Fatality (2) No clinically diagnosed injury	(1) 480 r (2) 31 r	110 r 1 r	6000 60
					80 KV X-Ray	GAMMA RAY	
5/21/46	Los Alamos	Eight	Chain reaction in experi mental critical assembly	(1) Fatality (2) Skin rash, loss of hair and other symptoms	(1) 930 r (2) 390 r	114 r 26 r	6000 70
				(3) Skin rash and other	(3) NA	NA	1/
				symptoms (4) No clinically	(4) 185 r	10 7 r	14
				diagnosed injury (5) No clinically	(5) 140 r	87 r	18
				diagnosed injury (6) No clinically	(6) 55 r	44 r	4
				diagnosed injury (7) No clinically	(7) 43 r	3 r	4
				diagnosed injury (8) No clinically diagnosed injury	(8) 33 r	2 41 r	4
5/14/48	Eniwetok Proving Ground	Four	Improper handling of fission sample	Beta ray burns to hand	1 7 r ² / 4 5 r ² / 5 5 r ² / 17 r ² /		36 36 36 36
9/7/48	Los Alamos	One	Unpacking radioactive material	Beta ray burns to ankle	NA3/		36
6/2/52	Chicago	Four	Manual withdrawal of control rod from critical assembly	No clinically diagnosed injury	190 rem 160 rem 70 rem 12 rem		23 23 34 23
7/9/52	Los Alamos	One	Handling radioactive material with torn glove	Beta burns to hands	NA4/		3
3/1/55	Nevada Test	One	Entering exclusion area during test	No clinically diagnosed injury	39 r		19
7/27/55	National Reactor Testing Station	One	Radioactive particle entering ear canal	Partial loss of hearing	Not detecta	ible	12
4/30/56	Los Alamos	One	Handling radioactive material with torn glove	Beta burns to hands	NA5/		14
6/18/56	Hanford	One	Escape of plutonium solution into control room	Contamination of exposed skin surfaces No clinically diagnosed injury	0 4 μ/c Pu		4
6/14/57	Rocky Flats	One	Explosion in "dry box"	Plutonium lodged in finger, necessitating partial amputation	32 μg Pu (6	0 2 μ/c)	50
6/16/58	Oak Ridge (Y 12 Plant)	Eight	Criticality incident caused by draining enriched uranium in drum of water	<u>6</u> /	461 rem 341 rem 428 rem 413 rem 298 rem 86 rem 86 rem 29 rem		83 83 83 83 83 34 65 41

Chart VIII (cont'd)

RADIATION ACCIDENTS RESULTING IN LOST-TIME INJURIES

(As defined in American National Standards Institute Method of Recording and Measuring Work Injury Experience—ANSI Z16.1-1967 (Revision of Z16.1-1964) and AEC Directives)

Date	Location	Number Involved	Source of Injury	Nature of Injury	Exposure	Days Lost
12/30/58	Los Alamos	One	Criticality accident	Fatality	12000 ± 50% rem	6000
11/8/60	Albuquerque Sandia Base	One	Exposure from electronic beam	Multiple radiation burns middle section of face, abdomen and both hand hands	<i>1</i> /	10
6/12/64	Rocky Flats	One	Explosion in "drybox"	Pu lodged in finger and thumb, necessitating amputation at proximal joint	1/	1000
7/7/65	Livermore	One	Changed materials in X-ray unit unaware it was operating	2nd degree burns right hand	1000 rem	12
9/15/65	Richland	One	Wiped moisture from chamber of emission spectro- meter	Amputation of distal phalanx of index finger	80000 rem	100
2/4/71	Oak Ridge	One	CO-60 sources	Nausea, vomiting, leukocyte depression	260 rem	66
8/22/71	Rocky Flats	One	Inhalation of Pu when some Pu in a can spontaneously ignited	No clinically diagnosed injury	208 μCi Pu-239 (lung) 20.4 μCι Pu-239 (systematic)	148/
2/18/74	N.Y. HASL	One	X-ray spectrometer	Severe injuries to left hand including amputation of distal phalanx of index finger and some tissue atrophy and some loss of function of other fingers	2400-4800 rad	10

¹ Information Not Available.

^{2/} Exposure refers to whole body gamma radiation. Injury caused by beta ray dose, amount of which exposure not available.

^{3/} Amount of beta ray dose not available. Total gamma ray exposure during week in which accident occurred was 0.27 rem.

^{4/} Amount of beta ray dose not available. Total gamma ray exposure during week in which accident occurred was 1.8 rem.

^{5/} Amount of beta ray dose not available. Total gamma ray exposure during week in which accident occurred was 2.0 rem.

^{6/} Three employees not requiring prolonged hospital care exhibited mild changes in blood elements but showed no symptoms of injury. The five employees requiring longer hospitalization showed significant decreases in blood elements and other clinical and laboratory findings characteristic of more severe radiation damage such as mild nausea and vomiting, and indications of possible hemorrhagic complications, although no bleeding actually occurred.

Employee was not wearing his film badge. However an indirect measurement was made by placing a film badge at the 33 cm distance and exposing it under simulated conditions. Calibration was interpreted as 760 rads incident dose to the face at 33 cm.

By Days lost as a result of efforts to remove Pu from lungs by lavage.




Chart IX
TIME LOST FROM RADIATION INJURIES 1943 TO 1975
AEC Operations

PART IV

AEC EXPERIENCE—PROPERTY DAMAGE

Section 1

GENERAL

During the 32-year history of the Atomic Energy Commission (AEC) and its predecessor, the Manhattan Engineer District (MED), property damage accidents caused just over \$85 million loss. A single incident, the Rocky Flats fire (described below) of May 11, 1969, accounts for 53% of the total.

Only a few incidents per year (typically from 3 to 4) exceed \$50,000 in total damage; however, these have accounted for 90% of the total dollar loss. The seven incidents described below are all of those that exceed \$1 million in total loss. Collectively, they account for 69% of all losses.

Almost 75% of all losses are the result of fire. Reactor-associated losses (including fires in reactors or associated areas) represent about 10% of the total (none of which caused injury or damage to the public). The remaining 15% is almost equally divided between acts of nature, explosions, and miscellaneous causes.

Chart XIV provides a listing and brief description of each accident causing \$50,000 or more loss. The incidents are listed in decreasing order of loss magnitude, e.g., incident #7 caused the seventh largest accidental loss in AEC's 28-year history. Incident numbers given in the listing correspond with those given on the charts covering AEC property damage.

1. FIRE—ROCKY FLATS
Golden, Colorado, May 11, 1969 \$45,000,000
The AEC's costliest fire, and largest property loss incident, occurred at a plant which produces plutonium parts for nuclear weap-

ons. The parts are made within a complex system of gloveboxes, which provide a means for working safely with plutonium while separating the operator from this potentially hazardous radioactive material. The available evidence indicates that the fire originated on the lower shelf of a storage cabinet in one of the gloveboxes. Plutonium briquettes and some loose scrap metal were stored in uncovered cans in the storage cabinet. The exact cause of ignition is unknown; however, plutonium in the form of chips or lathe turnings is a pyrophoric material. The heat from the burning plutonium metal evidently caused the storage cabinet, which was constructed mostly of cellulosic laminate material and plastic, to char and generate flammable gases which could have been ignited by burning plutonium. The heat of the burning gases could ignite other briquettes and initiate a slow burning of the storage cabinet materials, particularly in the cracks between the joined sections of the cellulosic materials. The financial loss for the damage to buildings and contents includes the cost of decontamination. There were no lost-time injuries to personnel. (See USAEC SERIOUS ACCIDENTS Issue #306, 12-1-69).

- 2. SL-1 REACTOR EXCURSION Idaho Falls, Idaho, Jan. 3, 1961 \$4,350,000 (See description on page 30.)
- 3. CHEMICAL EXPLOSION AND FIRE

Paducah, Ky., Dec. 13, 1962 \$2,900,000 An explosion, followed by an intense, violent, local, chemical reaction-type fire within a gaseous diffusion cell, caused heavy damage to adjacent physical facilities. Water from overhead sprinklers was rapidly converted into high-temperature steam which actuated most of the 2,341 sprinkler heads that operated during the fire. The automatic fire sprinkler systems were successful in confining fire damage within the \$162,-000,000 building.

There were no injuries to personnel. (See USAEC SERIOUS ACCIDENTS Issues #194, 1-3-63; #203, 4-29-63; #215, 1-17-64).

4. ROOF DECK FIRE

Paducah, Ky., Nov. 11, 1956 \$2,100,000 Failure of a process gas compressor seal permitted some of the leaking gas to escape, to impinge on, and to ignite oil in an adjacent drip pan and on flexible tygon tubing carrying oil to the compressor load bearings. The resulting intense, localized fire caused rupture of the lube oil supply line, thereby allowing additional fuel to feed the fire. The fire spread throughout the tar-treated built-up composition roof of the 70,000 sq. ft., nonsprinklered, two-story building constructed of unprotected steel frame with sheet asbestos siding and a metal roof deck. The roofing material consisted of a layer of tar which served both as a vapor barrier and to bind fiberglass insulation to the metal roof deck. The roofing was topped by a layer of tar binding the outer layer of gravel to the thermal insulation below.

One firefighter was seriously injured in a fall during efforts to escape from the intense heat. (See USAEC SERIOUS ACCIDENTS Issue #115, 2-11-57.)

5. ACT OF NATURE

Amarillo, Tex., Sept. 3, 1967 \$1,872,000 Winds, up to 106 miles per hour, rain, and hail caused major widespread damage to roofs, glass, doors, and walls of numerous buildings, and general damage and destruc-

tion to various segments of the electrical power distribution system, the steam condensate return, and compressed air distribution systems. Extensive flooding and water damage were experienced inside the buildings partially or wholly demolished by the cyclonic winds. Of 120 vehicles, 92 sustained damage.

6. EXPLOSION AND FIRE

Cambridge, Mass., July 5, 1965 \$1,453,000 An explosion and fire occurred in the experimental hall of an accelerator complex following the sudden release of 500 liters of liquid hydrogen. The incident was caused by the sequential failure of the inner and outer beryllium windows of a liquid hydrogen bubble chamber. During the next three hours, the initial blaze slowly spread to involve propane cylinders, the contents of which burned intensely in a secondary fire which, in turn, accentuated combustion in the explosion-fragmented roof. Eight persons were injured, one fatally. (See TID-5360, Suppl. 6, p. 42; TID-22594.)

7. REACTOR MELTDOWN


Idaho Falls, Idaho, Nov. 18, 1958 \$1,100,000 To permit initial very low-level power testing of an experimental nuclear reactor aircraft engine, it was found necessary to modify instrumentation power supplies so as to reduce interference from extraneous electrical "noise" effects. However, these changes had the subsequent net effect of causing erroneously low-level power indications as the actual reactor power levels were subsequently increased. The instrumentation error (due to saturation) gave false security as the actual reactor power level was slowly increased far beyond that which the reactor was capable of safely withstanding. In addition to severe reactor damage due to overheating, small amounts of radioactive fission product activity was released within the test facility. There were no injuries. (See 1959 NUCLEAR SAFETY, Vol. 1, #2, p. 57.)

Chart X affords a broad view of the 1943–1975 accident experience broken down into five categories, which include "reactors" and four types of "loss cause." If the causes of the accidental losses associated with the nuclear reactor incidents had been distributed between the four loss causes shown on Chart X (i.e., fire, ex-

plosion, act of nature, and miscellaneous), the type of relative magnitude of AEC loss causes would be found to parallel closely those of private industry. Stated differently, fire, explosion, and acts of nature are the principal causes of property damage in both AEC and private industry.

Chart X

AEC INCIDENTS CAUSING OVER \$50,000 PROPERTY LOSS OR DAMAGE
1943 - 1975



NUMBERS CORRESPOND WITH CHART XIV

Chart XI shows a breakdown of the AEC 1947–1974 property damage experience and reflects an average annual loss rate of approximately $2.45 \ensuremath{\phi}/\$100$ of AEC-owned property. The 28-year record for all losses (regardless of cause and including decontamination costs) is about

equal to the private insurance industry record for fire losses alone in the best class of insured properties. The wide deviations in the AEC annual loss experience shown on Chart XI are the result of a few high-loss incidents.




CHART XI
AEC PROPERTY DAMAGE RATIOS*... 1947 - 1974

LOSS FROM FIRE

As indicated on Chart X, fire accounted for three quarters of the total AEC loss experience. The May 11, 1969, fire at Rocky Flats (see page 15) more than tripled the AEC's cumulative fire loss ratio up to that time. Since 1969, intensified fire protection programs combined to make the 5 years since 1969 the 5 best years in AEC history. Even with the \$45,000,000 Rocky Flats

restoration included, the cumulative AEC loss ratio of 1.7 is well below the average for the best protected class of insured properties. In fact, if AEC loss ratios were equal to those of the better class of insured properties, the AEC would have suffered an additional \$45 million in fire losses over its history.





Chart XII
AEC FIRE LOSS RATIOS 1947 – 1974

LOSS FROM CONTAMINATION

Chart XIII presents a breakdown by years of AEC property damage from contamination. As noted in the chart, AEC experienced its largest loss due to contamination in 1969 when a fire occurred in a plutonium processing facility at Rocky Flats, Colorado, on May 11. Personnel exposures were within normal ad-

ministrative limits and no appreciable radioactivity was released to the environment. The cost of the incident was \$45,000,000, of which approximately \$9,600,000 was based on the expense for cleanup of radioactive contamination in the facility. Since 1955 the cost of contamination cleanup constituted about 17% of the total losses from all causes.



*INCLUDES LOSSES FROM ALL CAUSES

Chart XIII
CAUSES OF CONTAMINATION DAMAGE TO AEC PROPERTY
1955-1974

CHART XIV

SUMMARY OF ALL INCIDENTS CAUSING OVER \$50,000 PROPERTY DAMAGE OR LOSS IN THE HISTORY OF THE AEC-1943-1975

Throughout the history of the AEC, an average of about four incidents each year resulted in a loss exceeding \$50,000. These few incidents, however, account for 90% of the total dollar loss. All such incidents are listed below in decreasing order.

Inci- dent No.	Date	Field Office 1—Contractor	Remarks	AEC Property Damage
1	51169	AL—Dow Chemical Co	Fire, starting in glovebox storage cabinet, resulted in widespread damage to, and contamination of, building and contents. (See USAEC SERIOUS ACCIDENTS Issue #306, 12-1-69)	\$45,000,000
2	1- 3-61	ID—Combustion Engineering	Reactor excursion. (See TID-5360, Suppl. 4, p. 8; 1962 NUCLEAR SAFETY, Vol. 3, #3, p. 64.)	4,350,000
3	12-13-62	OR—Union Carbide Corp	Explosion and fire in gaseous diffusion cell. (See USAEC SERIOUS ACCIDENTS Issues #194, 1-3-63; #203, 4-29-63; #215, 1-17-64.)	2,900,000
4	11–11–56	OR—Union Carbide Corp	Intense localized fire from lube oil-process gas reaction spread to metal deck roof where fire got out of control due to combustible vapor barrier in roof deck. Damage limited to upper story of building. (See USAEC SERIOUS ACCIDENTS Issue #115, 2-11-57.)	2,100,000
5	9- 3-67	AL-Mason & Hanger-Silas Mason Co.	Wind and hailstorm damage	1,872,000
6	7- 5-65	NY—Harvard University; Massachusetts Institute of Technology.	Fire and explosion damage in experimental area ensued following beryllium window failure on liquid hydrogen bubble chamber. Eight people were injured, one fatally. (See TID-5360, Suppl. 6, p. 42; TID-22594.)	1,453,000
7	11–18–58	LAR—General Electric Co	Reactor fuel element meltdown resulted from radiation monitoring power system deficiency. (See 1959 NUCLEAR SAFETY, Vol. 1, #2, p. 57.)	1,100,000
8	9-29-65	RL—Battelle Northwest	Test reactor zirconium tube failure permitted gross contamination of reactor core and interior of containment shell. (See TID-5360, Suppl. 6, p. 27; 1965 NUCLEAR SAFETY, Vol. 7, #2, p. 242.)	895,000
9	9–11–57	AL—Dow Chemical Co	Spontaneous metallic plutonium fire in production drybox line spread to flammable plastic drybox window through ventilating system to main filter bank. Much of damage due to spread of plutonium contamination during the fire. (See TID-5360, Suppl. 2, p. 23; USAEC SERIOUS ACCIDENTS Issue #130, 11-27-57.)	818,600
10	10-20-73	OR—Union Carbide Corp	Failure of mounts on an experimental centrifuge resulted in <i>mechanical damage</i> to several units and experimental equipment.	600,000
11	1- 5-55	RL—General Electric Co	Partial meltdown of reactor during startup. Principal loss resulted from need to remove and replace part of reactor core. (See 1962 NUCLEAR SAFETY, Vol. 4, #1, p. 104.)	550,000
12	11 9-70	SR—E. I. du Pont de Nemours & Co.	Antimony-beryllium source rod separated, causing widespread contamination to the reactor room. No overexposures.	511,883
See footno	tes at end of t	able.	ito overexposures.	

SUMMARY OF ALL INCIDENTS CAUSING OVER \$50,000 PROPERTY DAMAGE OR LOSS IN THE HISTORY OF THE AEC-1943-1975

13 14	1-10-56			Damage
14		OR—Union Carbide Corp	Large process pressure vessel rupture from fatigue.	480,134
	5-19-71	OR-Goodyear Atomic Corp	A 100-pound propane cylinder being used by a construction contractor developed a leak which ignited. A subsequent rupture and <i>explosion</i> caused considerable building damage.	460,000
15	9-13-61	AL—Bendix Corp	Flood damage, attributed to effects of hurricane Carla, which caused adjoining creek to rise to record high of 44.5 feet.	449,200
16	10-61	SR—E. I. du Pont de Nemours & Co.	Dislocation and fracture of <i>sluiceways</i> in reactor effluent canals.	400,000
17	11- 6-63	RL—General Electric Co	Explosion and fire in plutonium purification facility. (See TID-5360, Suppl. 5, p. 23; USAEC SERIOUS ACCIDENTS Issue #237, 12-4-64).	397,000
18	1- 7-73	SR—Government	A heavy sleet-ice <i>storm</i> damaged pine trees over a 40,000 acre area.	393,000
19	1–73	SAN—Lawrence Berkeley Laboratory	Earth slides resulting from heavy rains over a 6-week period caused extensive damage to a combined office-storage space sciences laboratory.	370,000
20	11–20–59	OR-Union Carbide Corp	Chemical <i>explosion</i> occurred in processing vessel during cleanout and decontamination procedure. (See TID-5360, Suppl. 3, p. 15; USAEC SERIOUS ACCIDENTS Issue #162, 3-30-60.)	350,000
21	11- 3-64	RL—General Electric Co	Roof fire severely damaged aquatic laboratory building.	316,900
22	2-14-66	OR—National Lead Co	Inadvertent release of uranium hexafluoride. No significant radiation exposures. (See TID-5360, Suppl. 6, p. 32.)	294,826
23	6-10-53	SR-E. I. du Pont de Nemours & Co.	Platform failed, damaging reactor actuator rods	270,000
24	1-28-52	RL—General Electric Co	Fire destroyed one-story 75' x 140' frame construction warehouse. No sprinklers, (See USAEC SERIOUS ACCIDENTS Issue #21, 3-7-52.)	269,578
25	5- 2-74	SR—E. I. du Pont de Nemours & Co.	Radioactive gas released accidentally from stack. No property damage or personnel exposures resulted.	265,000
26	4-23-50	SAN—Lawrence Radiation Laboratory	Multistory, unsprinklered frame research building destroyed by $fire$.	258,712
27	4-17-60	RL—General Electric Co	Fire involving spent fuel elements within process dissolver led to damage of equipment and contamination spread, (See TID-5360, Suppl. 3, p. 20; 1961 NUCLEAR SAFETY, Vol. 2, #4, p. 52.)	250,443
28	9-13-60	SR—E. I. du Pont de Nemours & Co.	Contaminated cooling water discharged from canyon onto floor. No overexposures. (See TID-5360, Suppl. 3, p. 22.)	250,050
29	12-29-52	AL—Holmes and Narver	Typhoon damage	250,000

SUMMARY OF ALL INCIDENTS CAUSING OVER \$50,000 PROPERTY DAMAGE OR LOSS IN THE HISTORY OF THE AEC-1943-1975

Inci- dent No.	Date	Field Office 1—Contractor	Remarks	AEC Property Damage
30	12-13-63	OR-Goodyear Atomic Corp	Transformer in switchyard suffered internal failure.	244,800
31	11–14–73	RL—Atlantic Richfield Hanford Co.	8,600 gallons of <i>contaminated waste</i> overflowed on the ground when a salt plug formed in a storage tank riser. Cost was for decontamination.	204,184
32	5- 4-57	SR—E. I. du Pont de Nemours & Co.	Leak in reactor heat exchanger resulted in loss of heavy water moderator.	202,000
33	10-29-52	OR—Government	Fire following tractor-trailer accident spread to, and ultimately destroyed, cargo and tractor-trailer. Bulk of loss due to self-sustaining combustion of massive uranium. (See TID-5360, p. 46; AECU 3613, p. 9.)	200,000
34	12-26-69	AL—Mason & Hanger— Silas Mason	High explosives detonated during remotely-controlled pressing operations.	200,000
35	8-15-58	OR-Union Carbide Corp	Welding sparks ignited fiberboard and fire spread rapidly through wood frame building. (See USAEC SERIOUS ACCIDENTS Issue #139, 10-23-58.)	199,923
36	6-22-72	AL—Catalyst Research Corp.	A flood caused water to react with calcium causing a hydrogen explosion which collapsed the build- ing, resulting in damage to some Government- owned equipment.	187,686
37	1-20-65	SAN—Lawrence Radiation Laboratory	Material release to atmosphere. (See TID-5360, Suppl. 6, p. 16)	185,000*
38	6-21-67	RL—Douglas United Nuclear	Oil fire in heat exchanger cell of reactor	185,000
39	7-2-50	OR-Union Carbide Corp	Transformer in main switchyard. Fire	171,000
40	8 6-70	SAN—Lawrence Radiation Laboratory.	Accidental <i>release</i> of tritium occurred when automatic safety devices discharged the gas through a 100-foot-high exhaust stack. No overexposures.	165,000*
41	12-26-73	CH—Fermilab	_Fire in urethane foam insulation in beam tunnel under construction caused damage to accelerator experimental building. (See USAEC Serious Accidents Issue #336, 9-19-74.)	163,000 non-Govt.
42	4-23-58	SAN—Lawrence Radiation Laboratory.	Rotor bolt sheared off and got between <i>generator</i> rotor and stator, tearing insulation and shorting wiring.	140,000
43	3-18-60	SR-E. I. du Pont de Nemours & Co.	Fire followed a hydrogen-sulfide gas release from a tritium process equipment condenser.	135,300
44	6-17-55	OR—Union Carbide Corp	Hydrogen explosion occurred in 125,000-gallon evaporator feed tank. (See USAEC SERIOUS ACCIDENTS Issue #86, 9-1-55.)	132,275
45	10-26-61	AL—Sandia Corp. (Sub- Wurlitzer.)	Fire followed friction or static ignition of "heat pad paper" containing powered zirconium. (See TID-5360, Suppl. 4, p. 30.)	131,210
46	8-21-59	SR—E. I. du Pont de Nemours & Co.	Solution leaked from loosened flange during maintenance work on waste evaporator in hot canyon, vaporized and contaminated a crane. (See TID-5360, Suppl. 3, p. 13; USAEC SERIOUS ACCIDENTS Issue #157, 12-15-59.)	129,423

SUMMARY OF ALL INCIDENTS CAUSING OVER \$50,000 PROPERTY DAMAGE OR LOSS IN THE HISTORY OF THE AEC—1943-1975

Inci- dent No.	Date	Field Office 1—Contractor	Remarks	AEC Property Damage
47	5 665	NY—Harvard University; Massachusetts Institute of Technology.	Fire in modulator electrical pulsing equipment for accelerator.	127,000
48	1–23–49	RL—General Electric Co	Hexone-nitric acid chemical <i>explosion</i> followed by fire seriously damaged building. Spread of contamination was minor factor from loss viewpoint.	125,217
49	1945	AL—Los Alamos Scientific Laboratory.	Fire initiating in oil quench tank ignited and spread through frame shop building.	125,000
50	5- 4-70	SR—E. I. du Pont de Nemours & Co.	Solution containing 20 grams of curium-244 and americium-243 was <i>mistakenly transferred</i> to the high level (waste) drain. No overexposures.	124,523
51	1946	OR—Mallinckrodt Chemical Works.	Uncontrolled ether-nitric acid explosion in uranium solution purification plant.	110,000
52	7–23–57	LAR—General Electric Co	Crane overturned while handling a reactor core. Bulk of loss due to damaged reactor core.	105,225
53	7–24–64	SR—E. I. du Pont de Nemours & Co.	Radioactive gas release accidentally from stack to atmosphere. No property damage or personnel exposures resulted. (See TID-5360, Suppl. 5, p. 35)	102,000*
54	11–10–60	SAN—Lawrence Radiation Laboratory.	Fire started in curium processing cave by apparent overheating of oil bath in glovebox. Loss confined to one room, but all contents complete loss. Minor release of radioactive materials to environment. Damage due largely to fire destroying equipment. (See USAEC SERIOUS ACCIDENTS Issues #169, 11-25-60, #175, 4-5-61).	101,000
55	10-30-59	SNR—General Electric Co	Air-oil <i>explosion</i> occurred in air flask component of a 3,000-psi hydraulic oil system. (See USAEC SERIOUS ACCIDENTS Issue #155, 11-19-59.)	100,000
56	11- 8-57	SR—E. I. du Pont de Nemours & Co.	Zirconium-clad fuel element failed under test. A series of complications followed, chief of which was contaminated water leakage from earth basin through abandoned construction pipelines. No personnel exposure or property damage.	99,007
57	2-10-73	SR-E. I. du Pont de Nemours & Co.	An unusual <i>snow storm</i> collapsed the roof of a light metal warehouse.	98,000
58	12- 3-71	SR—Government	A severe <i>ice storm</i> caused damage to plant woodlands.	96,000
59	3-22-70	RL—Battelle Northwest	Estimated 1,000 curie strontium-90 release occurred during an attempt to measure the liquid level in a strontium-90 storage tank. No significant exposure.	95,000
60	3–26–63	SAN—Lawrence Radiation Laboratory.	Criticality occurred during subcritical experiment involving fissionable materials and small fire developed within enclosed concrete vault. (See TID-5360, Suppl. 5, p. 17.)	94,881

SUMMARY OF ALL INCIDENTS CAUSING OVER \$50,000 PROPERTY DAMAGE OR LOSS IN THE HISTORY OF THE AEC-1943-1975

Inci- dent No.	Date	Field Office 1—Contractor	Remarks	AEC Property Damage
61	12- 3-71	NV—Holmes & Narver	A crane being loaded on a barge at Amchitka capsized.	92,939
62	2-20-52	SAN—Lawrence Radiation Laboratory.	Fire initiating in hot plate in research laboratory broke out in attic and spread through two-story, frame, unsprinklered building.	92,798
63	11-13-63	AL—Mason & Hanger-Silas Mason Co., Inc.	Chemical explosion in explosives storage igloo	92,568
64	4-14-74	ID—Allied Chemical Corp	A contaminated waste line leaked in a pipe trench. Cost was for excavation and decontamination.	92,000
65	8- 8-58	RL—General Electric Co	Disintegration of emergency turbo generator from overspeed following dual failure of the governor and the overspeed trip devices. (See USAEC SERIOUS ACCIDENTS Issue #142, 1-21-59.)	90,000
66	1–17–59	OR—Union Carbide Corp	Multiple circuit breaker failure led to severe electrical fire. (See USAEC ACCIDENT AND FIRE PREVENTION INFORMATION Issue #92, 2-17-59.)	86,020
67	12- 8-54	SR—E. I. du Pont de Nemours & Co.	Weld failure in large water pipe at river pumphouse.	81,800
68	11-11-56	SR—E. I. du Pont de Nemours & Co.	Heavy water moderator loss due to <i>leak</i> in <i>reactor</i> heat exchanger.	80,000
69	8-23-65	RL—Battelle Northwest	Minor fire and explosion following acetone ignition in glovebox caused extensive contamination spread. (See TID-5360, Suppl. 6, p. 24; USAEC SERIOUS ACCIDENTS Issue #261, 2-15-56.)	76,800
70	5-19-57	AL—Sandia Corp	Fire destroyed 36' x 60' Butler building. Major damage to generator.	76,120
71	2–13–58	RL—General Electric Co	Chemical <i>explosion</i> occurred in silver nitrate reaction vessel used to absorb iodine vapors from process offgases. Incident occurred following introduction of efforts to extend useful life of iodine 131 removal equipment. (See USAEC SERIOUS ACCIDENTS Issue #134, 7-28-58.)	75,700
72	7–10–71	NV—Holmes & Narver	An LCM boat being towed off Amchitka capsized and sank.	75,108
73	5 565	NV—Reynolds Electrical & Engineering Co.	Drill rig overturned	75,000
74	7-31-65	RL—General Electric Co	Explosion during manual reignition of oil-fired boiler after flameout during test.	75,000
75	8-31-57	AL—Holmes and Narver	Helicopter seriously damaged when dropped while being unloaded by crane from boat.	75,000
76	2 1-51	OR—Mallinckrodt Chemical Works.	Ether-nitric acid explosion during attempts to remove scale from process tank in uranium solution purification building. (See USAEC SERIOUS ACCIDENTS Issue #2, 2-15-51.)	75,000
77	9-19-64	NV—Reynolds Electrical & Engineering Co.	While electrical cables were being lowered into a test hole, <i>cable broke</i> and fell into hole below drill rig. (See TID-5360, Suppl. 5, p. 44.)	74,000

SUMMARY OF ALL INCIDENTS CAUSING OVER \$50,000 PROPERTY DAMAGE OR LOSS IN THE HISTORY OF THE AEC-1943-1975

Inci- dent No.	Date	Field Office ¹ —Contractor	Remarks	AEC Property Damage
78	12- 2-45	OR—Union Carbide Corp	Fire in cork pipe covering in purge and product room.	73,000
79	3-29-57	PNR—Westinghouse Electric Corp.	Explosion (pressure rupture) of high pressure autoclave during normal operation due to fatigue resulting from cyclic thermal and mechanical stresses. (See USAEC SERIOUS ACCIDENTS Issue #133, 6-24-58.)	71,500
80	3 3-67	SR—E. I. du Pont de Nemours & Co.	Heavy water loss when water flowed onto reactor top from hydraulic lifting of upper shield plug.	71,000
81	9-21-58	AL—Holmes and Narver	Severe wave action from storm resulted in damage to cargo pier, barge slip, and fuel barge.	70,844
82	12-55	AL—Holmes and Narver	Damage by wave action to man-made island	70,000
83	1–18–57	SR—E. I. du Pont de Nemours & Co.	Heavy water loss due to leak in heat exchanger for reactor.	70,000
84	8-14/17-61	RL—Government	Range fire. Over three-day period, 62 known grass and range fires occurred involving 30,480 acres.	69,866
85	5-47	OR—Union Carbide Corp	Fire destroyed two-story, frame, unsprinklered office building.	69,000
86	3-18-69	NV—EG&G NV—Govt; AL—LASL	Fire in electronics laboratory and office trailer	67,900
87	1–22–64 & 3–2–64	RL—Peter Kiewit Sons' Co _	Tunnel collapsed while backfilling over tunnel roof	66,000
88	6-22-68	RL—Douglas United Nuclear	Reactor scrammed	66,000
89	9- 9-57	OR—Goodyear Atomic Corp _	Transformer failure. No fire. Principal cost for transformer repair.	65,000
90	3-12-67	NV—Reynolds Electrical & Engineering Co.	Trailer fire caused by overheating of heater unit	65,000
91	5-16-54	RL—Blaw-Knox	Fire followed by spontaneous combustion in janitor's closet, destroying building. (See USAEC SERIOUS ACCIDENTS Issue #67, 7-27-54.)	62,355
92	10–16–59	ID—Phillips Petroleum Co	Criticality accident occurred in process equipment waste collection tank. (See TID-5360, Suppl. 3, p. 14; USAEC SERIOUS ACCIDENTS Issue #163, 4-18-60; 1960 NUCLEAR SAFETY, Vol. 1, #3, p. 75.)	61,800
93	2-25-64	AL—Mason & Hanger-Silas Mason Co., Inc.	Detonation of high explosives during normal processing operation.	60,400
94	12- 9-56	SR—E. I. du Pont de Nemours & Co.	Heavy water moderator loss due to leak in heat exchanger for reactor.	60,000
95	8–22–71	AL—Dow Chemical Co.	An exothermic reaction in a small can containing plutonium caused container rupture and contaminated the area. (See USAEC Serious Accidents Issue #325, 3-27-72.)	60,000
96	12- 4-63	AL—Sandia Corp. (Sub-Eagle Picher).	Transporting heat-pad paper in fibre containers to vault; the paper flashed and fire spread from paper to other parts of the dryroom adjacent to vault.	58,507

SUMMARY OF ALL INCIDENTS CAUSING OVER \$50,000 PROPERTY DAMAGE OR LOSS IN THE HISTORY OF THE AEC—1943-1975

Inci- dent No.	Date	Field Office 1—Contractor	Remarks	AEC Property Damage
97	1-10-68	AL—Mason & Hanger-Silas Mason Co., Inc.	High explosives detonated during remotely-controlled pressing operations.	57,763
98	10-29-61	AL—Government	Aircraft struck 500' radio tower. Tower collapsed and wing tank torn from plane.	57,000
99	6–12–64	AL—Dow Chemical Co	Explosion occurred within drybox when burning plutonium chips dropped into carbon tetrachloride bath. (See TID-5360, Suppl. 5, p. 32; USAEC SERIOUS ACCIDENTS Issue #246, 3-12-65.)	56,400
100	1-29-66	SR—E. I. du Pont de Nemours & Co.	Water supply lines and fire sprinkler lines froze_	56,000
101	6-20-68	AL—Sandia Corp	Truck fire. Computer and electronic test equipment damaged.	55,673
102	5-17-52	AL—Mason & Hanger-Silas Mason Co., Inc.	Water damage due to ruptured 4" waterline	54,000
103	9- 7-55	AL—Reynolds Electrical & Engineering Co.	Fire in temporary construction warehouse destroyed frame building housing combustible construction materials. Adjoining acetylene cylinder storage building also destroyed. (See USAEC SERIOUS ACCIDENTS Issue #111, 11-9-56.)	53,608
104	8-25-65	AL—Mason & Hanger-Silas Mason Co.	Hailstorm damage	52,537
105	1-21-66	RL—Douglas United Nuclear	Boiler at reactor suffered internal damage from firebox explosion.	52,499
106	4 970	CH—Argonne National Laboratory	Seal plug blown from research reactor's experimental tube when an experimenter overpressurized the tube during a leak test. No overexposures.	52,300
107	12- 9-63	OR—Goodyear Atomic Corp	Compressor in cell debladed while onstream. De- blading took place while psi test being con- ducted, and was accompanied by small fire on exterior of compressor shell.	51,500
108	9-12-70	NY—Princeton Univ. Plasma Physics Lab	Short circuit occurred on the secondary side of a power system in a 4160-volt circuit breaker cubicle. Three switchgear units damaged.	51,050
109	4-17-64	RL—General Electric Co	The erroneous placer ent of some enriched (0.947 %) fuel elements within reactor necessitated reactor reloading with attendant increased costs for fuel handling and processing. (See TID-5360, Suppl. 5, p. 28.)	51,000
110	1, 2-69	RL—Battelle Northwest	Flood damage	51,000
111	6- 5-54	AL—Government	Forest fire on an AEC reservation	50,000
112	1-12-53	SR-E. I. du Pont de Nemours & Co.	Explosive chemical reaction in evaporator outside building. Minor building and contamination damage. (See TID-5360, p. 58; USAEC SERIOUS ACCIDENTS Issue #41, 3-23-53.)	50,000

SUMMARY OF ALL INCIDENTS CAUSING OVER \$50,000 PROPERTY DAMAGE OR LOSS IN THE HISTORY OF THE AEC-1943-1975

Inci- dent No.	Date	Field Office ¹ —Contractor	Remarks	ACE Property Damage
113	12- 4-51	RL—General Electric Co	Fire of spontaneous origin broke out in nitric acid- saturated combustible waste used for cleaning up contamination from prior criticality incident. Extent and magnitude of contamination spread by fire caused abandonment of building. (See TID-5360, p. 53.)	50,000
114	9-29-59	SR—E. I. du Pont de Nemours & Co.	Hurricane Gracie damaged storage pond dam wall	50,000
115	6- 5-66	CH—Atomics International	Sodium leak occurred in gas-fired sodium heater_	50,000
116	6- 2-67	AL—Mason & Hanger-Silas Mason Co.	$High\ explosives\ detonated,$ cause not determined	50,000

¹ See footnote 1, page 49.

* These property loss figures are based on a current commercial price of about 55¢ per curie of tritium and do not represent the actual classified loss figures.

Section 2

CRITICALITY ACCIDENTS

In the AEC's operational activities (not licensed) for the past 32 years there have been a total of 26 occasions (see Chart XV) when the power level of fissile systems became uncontrollable because of unplanned or unexpected changes in the system reactivity. On three occasions, the power excursions were planned; however, the fission energy released during the excursion was significantly larger than was expected. There have been a total of six deaths attributable to criticality accidents. The property damage resulting from these excursions has been approximately \$4,455,000; however, 98% of the property loss was due to the SL-1 reactor excursion. It is interesting to note that there were no criticality accidents during the last 7 years of the AEC and no injuries or fatalities in nearly the last 15 years.

Further study of this accident record reveals that nine of the unplanned excursions occurred behind heavy shielding and three of them occurred in facilities remotely located with respect to personnel. Hence, the probability of injuries to people was reduced almost to the vanishing point. It is also noted that fourteen of the accidents occurred during experiments, six occurred in production or processing facilities, and five in reactor activities. In these laboratory, production, and reactor facilities there were, respectively, two, one, and three fatalities.

A review of these incidents has been made by W. R. Stratton, University of California, Los Alamos Scientific Laboratory, Los Alamos, N. Mex. All we have done below is to prepare a brief description of each incident.

CHART XV

CRITICALITY ACCIDENTS IN USAEC FACILITIES*

				Fissions			
			METAL SYSTLE	MS IN AIR			
ug 8, 1945	Los Alamos, New Mexico	$62~{\rm Kg}~\delta$ phase Pu	Spherical core tungster carbide	~1016	Hand stacking reflector	None	
May 21, 1946	Los Alamos, New Mexico	6 2 Kg δ-phase Pu	reflected Spherical core	\sim 3 x 1015	Hand stacking reflector	None	
pr 18, 1952	The Los Alamos Scientific Lab , New mexico	92 4 Kg uranium metal, 93% U 235	Be reflected Cylinder unreflected	1 5 x 10 ¹⁶	Computation error	None	-
eb 3, 1954	The Los Alamos Scientific Lab, New Mexico	58 Kg uranium metal, 93% U-235	Sphere unreflected	5 6 x 10 ¹⁶	Incorrect operation	Slight warping of pieces	\$600
eb 12, 1957	The Los Alamos Scientific Lab , New Mexico (GODIVA)	54 Kg uranium metal, 93% U-235	Sphere unreflected except for experiment	1 2 x 10 ¹⁷	Shift of experiment	Warping, oxidation near melting close to center	\$2 400
Tov 10, 1961	The Oak Ridge National Lab , Tennessee	75 Kg uranium metal, 93% U 235	experiment	$\sim \! 10^{16}$	Too rapid assembly	None	-
Mar 26, 1963	LRL Livermore Calif	47 Kg 93% U-235	Cylinder reflected	5 x 10 ¹⁷	Too rapid assembly	Assembly machine and fire effects	\$94 881
			SOLUTION S	YSTEMS			
Dec , 1949	The Los Alamos Scientific	~1 Kg U-235 UO ₂ (NO ³) ₂ m	Sphere graphite	3-4 x 10 ¹⁶	Manual withdrawal of two poison	None	u.m.
Nov 16, 1951	Lab , New Merico The Hanford Works,	13 6 liters water 1 15 Kg Pu	reflected Sphere 98% full	8 x 10 ¹⁶	control rods Po son control rod	None	**
	Richland, Washington	PuQ ₂ (NO ³) ₂ in 63 8 liters water	unreflected		run out too fast		
fay 26, 1954	The Oak Ridge National Lab, Tennessee	18 3 Kg U-235 UO ₂ F ₂ in 55 4 liters water	Cylindrical annulus unreflected	1 x 10 ¹⁷	Tilting of inner poison cylinder	None	V -10-10
eb 1, 1956	The Oak Ridge National Lab , Tennessee	27 7 Kg U-235 UO ₂ F ₂ m 58 9	Cylinder unreflected	1 6 x 10 ¹⁷	Falling scram set up waves creating	Warping of bottom of cylinder	
une 16, 1958	Y-12 Processing Plant, Oak Ridge, Tennessee	Inters water 2 5 Kg U-235 UO ₂ (NO ³) ₂ in	Cylinder concrete reflected below	1 3 x 10 ¹⁸	a critical geometry Wash water added to UO (NO ³) ₂ solution	None	\$1 00
Dec 30, 1958	The Los Alamos Scientific Lab New Mexico	56 liters water 3 27 Kg Pu PuO ₂ (NO ³) ₂ in	Cylinder water reflected below	1 5 x 10 ¹⁷	Agitator created a critical geometry	None	_
et 16, 1959	Pu Processing Plant Chemical Processing Plant, Idaho Reactor Testing Area	~168 liters water 34 5 Kg U-235 ~800 liters UO ₂ (NO ³) ₂ water	Cylinder concrete reflected below	~4 x 10 ¹⁹	Solution surged from safe to unsafe geometry	None	\$61 80 (to recove contam soluti
an 25, 1961	Chemical Processing Plant, Idaho Reactor Testing Area	8 Kg U-235 UO ₂ (NO ³) in 40 hters water	Cylinder	6 x 10 ¹⁷	Solution pumped from safe to unsafe geometry	None	\$6 00
pr 7, 1962	Hanford Atomic Products	Pu Solution	Cylinder	°8 x 10 ¹⁷	Solution over flow down unsafe geometry transfer tank	ı	\$160
an 30, 1968	Y-12 Processing Plant, Oak Ridge, Tennessee	3 3 Kg U-233 UO ₂ (NO ³) ₂ m 20 liters water	Sphere water reflected	1 1 x 10 ¹⁶	Solution surged from safe to unsafe geometry	None	_
		INHOMOGE	NEOUS WATER I	MODERATE	O SYSTEMS		
une 4, 1945	Los Alamos, New Mexico	35 4 Kg uranium ~83% U-235 1/2 in cubes	Pseudosphere water reflected	~3 x 10 ¹⁶	Water seeping between blocks	None	_
Mar 20, 1951	The Los Alamos Scientific Lab , New Mexico	2 cylinders uranium 24 4 and 38 5 Kg 93% U-235	2 cylinders water reflected	1017	Scram increased reactivity	Slight oxidation	_
une 2, 1952	The Argonne National Lab	6 8 Kg U-285 oxide particles in plastic	Inhomogeneous cylinder water reflected	1 22 x 10 ¹⁷	Manual withdrawal of central safety rod	Plastic destroyed	
uly 22, 1954	The Reactor Testing Area, Idaho Falls, Idaho (BORAX)	U A1 plates clad with A1	Inhomogeneous cylinder water moderated	4 68 x 10 ²⁸	Estimate of expected excursion too low	Reactor destroyed intentionally by test	_
an. 3, 1961	Idaho Reactor Testing Area (SL-1)	U A1 plates clad with A1	Inhomogeneous cylinder water moderated	1 5 x 10 ¹⁸	Manual withdrawal of control rod	Extensive to reactor	\$4 350 000
			MISCELLANEOU	S SYSTEMS			
Peb 11, 1945	Los Alamos, New Mexico	UH pressed in styrex	Cylinder	~6 x 10 ¹⁵	Reflector added and /or source too large	UH ² styrex cubes swollen and blistered	-
Nov 29, 1955	Idaho Reactor Testing Area (EBR-1)	1/2 in U-235 rods	Cylinder rods cooled by NaK	4 7 x 10 ¹⁷	Incorrect scram used	Core molten	Not reported
uly 3, 1956	The Los Alamos Scientific Lab , New Mexico	58 Kg uranium 93% U-235, 2 and 5 mil foils	Cylinder	3 2 x 10 ¹⁶	Too rapid assembly	None	_

^{*}For additional information on these accidents, see previous TID-5360 series and "A Review of Criticality Accidents' by W R Stratton, University of California (LASL)

^{**} A subsequent fire in contaminated waste from the cleanup operation resulted in \$50 000 damage on December 4 1951 (See Chart XIV and TID 5860)

CRITICALITY EXCURSION INCIDENT Oak Ridge, Tenn., Jan. 30, 1968

Unexpected criticality was achieved in a volume of an aqueous solution of a salt of U238 during a series of routine critical experiments in progress in a well-shielded assembly area of a critical experiments facility. The criticalityradiation alarm system functioned as designed, the evacuation of personnel from the building was prompt and orderly, and the excursion was terminated expeditiously by a negative coefficient of reactivity and was prevented from recurring by the action of the safety devices. The fission yield was $1.1 imes 10^{16}$. Gamma-ray sensitive personnel dosimeters read immediately following the excursion showed no direct exposure greater than 5 mr to any person present. There was no property damage or loss of fissile materials. An estimated 100 cm3 of solution (15 g of U) were spilled when a rubberstoppered connection immediately above the sphere was dislocated.

The purpose of the particular experiment in progress was to establish the critical concentration of a sphere of the solution of uranyl nitrate surrounded by a thick water reflector. In the course of approaching criticality by incremental additions of solution, a small volume of air was observed entrapped in a flexible transparent tube. Supercriticality occurred during an attempt, by remote manipulation of liquid levels, to remove the air.

ACCIDENTAL CRITICALITY EXCURSION Los Alamos, N. Mex., May 18, 1967

A nuclear excursion of 4×10^{16} fissions took place in the critical mockup of a high power density reactor. There was neither damage to the equipment nor significant exposure to persons; nevertheless, the incident indicated poor practice and an undesirable interpretation of operating procedures which has been corrected. The reactor mockup is fueled with elements composed of fully enriched uranium in a graphite matrix, and a smaller number of graphite moderating elements. This permits a relatively small core volume (250 liters). The core, housed in a graphite cylinder, drops out of its Be reflector for loading. Control and safety drums are within the annular reflector.

Before the incident, fuel along the core axis was replaced by additional moderating elements to investigate flux-trap effects. Instead of the usual step-wise interchange of elements, the entire moderating island was installed. Then, instead of step-wise multiplication measurements while inserting the core into the reflector, which is proper for initial approaches to criticality, there were no measurements during interrupted insertion. It had been inferred from the behavior of different moderating elements in an earlier mockup that the overall reactivity change would be minor. This was a serious mistake, for the actual change proved to be about \$10. Before complete closure was achieved, a very short period and scram (dropping the core and actuating the safety drums) occurred.

NUCLEAR EXCURSION AND FIRE Livermore, Calif., Mar. 26, 1963

A nuclear excursion and subsequent fire took place during a subcritical experiment in a shielded vault designed for critical assembly experiments. The excursion was estimated at 4×10^{17} fissions and was followed by oxidation of the enriched uranium metal in the assembly.

The cause of the excursion is believed to have been directly attributable to mechanical failure. The total property loss was \$94,881.

NUCLEAR EXCURSION Richland, Wash., Apr. 7, 1962

An unplanned nuclear excursion occurred in a plutonium processing facility because of the inadvertent accumulation of approximately 1500 grams of plutonium in 45–50 liters of dilute nitric acid solution in a 69-liter glass transfer tank. The sequence of events which led to the accumulation of the plutonium in the tank cannot be stated positively. However, it is believed that, when a tank valve was opened, the solution from another process vessel overflowed to a sump and was drawn into the transfer tank through a temporary line between this tank and the sump.

When the excursion occurred, radiation and evacuation alarms sounded. All but three employees left the building immediately, according to well-prepared and -rehearsed evacuation plans. Fortunately, they were not in close prox-

imity to the involved system nor in a high radiation field.

The course of the nuclear reaction involved initial criticality (10^{16} fissions); a subsidence; one or more later peaks; and after approximately one-half hour, a declining rate of fission, which terminated in a subcritical condition 37 hours later. The total number of fissions was approximately 8×10^{17} .

Of the 22 persons in the building at the time, only four employees, those who were in the room with the system, were hospitalized for observation. Three of them were the system operators, who were in close proximity to the excursion, and who received estimated radiation doses of 110, 43, and 19 rem. None of them showed symptoms definitely referable to their radiation exposures. The fourth was sent to the hospital only because he was in the room at the time of the incident.

Some fission product activity, airborne via the vent system and the exhaust stack, was detected in the atmosphere for a brief period after the accident. The physical damage amounted to less than \$1,000. (See TID-5360, Suppl. 4, page 17.)

NUCLEAR EXCURSION Oak Ridge, Tenn., Nov. 10, 1961

A criticality excursion occurred as enriched uranium metal, neutron-reflected and -moderated by hydrogen, was being assembled. The excursion was caused by a too rapid approach of the two pieces of metal used in the experiment.

There was no personnel exposure or property damage. The energy release was estimated to be between 10¹⁵ and 10¹⁶ fissions. Fission product contamination, both airborne and contained in the metal, decayed sufficiently overnight to allow unhindered continuation of the experiment.

The incident occurred in a critical experiment laboratory specifically designed to accommodate such occurrences, since events of this nature cannot be considered entirely unexpected in an experimental facility of this sort. (See TID-5360, Suppl. 4, p. 14.)

CRITICALITY ACCIDENT Idaho Falls, Idaho, Jan. 25, 1961

A nuclear excursion of approximately

 6×10^{17} fissions occurred in a first-cycle product evaporator at a chemical processing plant. The criticality accident resulted when a solution of enriched uranyl nitrate accidentally surged from a geometrically safe section of the evaporator into the upper critically unsafe, vapor disengagement section. The accident occurred behind thick concrete walls in a processing cell which is part of the first cycle for processing highly radioactive spent-fuel elements.

Personnel response to the radiation alarms and the evacuation signal was prompt and orderly.

Analyses of badges from 65 individuals indicated a maximum exposure of 55 millirem gamma and 0 beta. The maximum thermal neutron exposure detected in the badges analyzed was less than 10 millirem. Analyses of nuclear accident dosimeters indicated that there was negligible fast neutron flux associated with personnel exposures.

The radioactivity released to the atmosphere as a result of the accident was about twice normal background when it left the area. Loss of \$6,000 resulted from cleanup of the incident. (See TID-5360, Suppl. 4, p. 9; 1961 Nuclear Safety, Vol. 3, #2, p. 71.)

SL-I EXCURSION Idaho Falls, Idaho, Jan. 3, 1961

A nuclear excursion occurred within the reactor vessel, resulting in extensive damage of the reactor core and room, and in high radiation levels (approximately 500-1,000 rem/hr) within the reactor room.

At the time of the accident, a three-man crew was on the top of the reactor assembling the control rod drive mechanisms and housing. The nuclear excursion, which resulted in an explosion, was caused by manual withdrawal, by one or more of the maintenance crew, of the central control rod blade from the core considerably beyond the limit specified in the maintenance procedures.

Two members of the crew were killed instantly by the force of the explosion, and the third man died within two hours following the incident as a result of an injury to the head. Of the several hundred people engaged in recovery operations, 22 persons received radia-

tion exposures in the range of three to 27 rem gamma radiation total-body exposure. The maximum whole-body beta radiation was 120 rem.

Some gaseous fission products, including radioactive iodine, escaped to the atmosphere outside the building and were carried downwind in a narrow plume. Particulate fission material was largely confined to the reactor building, with slight radioactivity in the immediate vicinity of the building.

The total property loss was \$4,350,000. (See TID-5360, Suppl. 4, p. 8; 1962 Nuclear Safety, Vol. 3, #3, p. 64.)

CRITICALITY INCIDENT Idaho Falls, Idaho, Oct. 16, 1959

A nuclear incident occurred in a process equipment waste collection tank when an accidental transfer was made of about 200 liters of uranyl nitrate solution, containing about 34 kilograms of enriched uranium (91 percent U²³), from critically safe process storage tanks to a geometrically unsafe tank through a line formerly used for waste transfers.

Limited visual inspections and test indicated that no significant property damage or loss resulted beyond the approximately \$60,000 cost to recover contaminated uranium solution resulting from the incident.

Of the 21 personnel directly involved in this incident, seven received external exposures to radiation. The exposures were 8, 6, 3.95, 1.50, 1.38, 1.17, and 1.17 rem. Two individuals also received external exposures to the skin of 50 rem and 32 rem. No medical treatment was required for the 21 personnel involved. (See TID-5360, Suppl. 3, p. 14; USAEC Serious Accidents Issue #163, 4-18-60.)

FATAL INJURY ACCOMPANIES CRITICALITY ACCIDENT

Los Alamos, N. Mex., Dec. 30, 1958

The chemical operator introduced what was believed to be a dilute plutonium solution from one tank into another known to contain more plutonium in emulsion. Solids containing plutonium were probably washed from the bottom of the first tank with nitric acid and the resultant mixture of nitric acid and plutonium-bearing solids was added to the tank contain-

ing the emulsion. A criticality excursion occurred immediately after starting the motor to a propeller type stirrer at the bottom of the second tank.

The operator fell from the low stepladder on which he was standing and stumbled out of the door into the snow. A second chemical operator in an adjoining room had seen a flash, which probably resulted from a short circuit when the motor to the stirrer started, and went to the man's assistance. The accident victim mumbled he felt as though he was burning up. Because of this, it was assumed that there had been a chemical accident with a probable acid or plutonium exposure. There was no realization that a criticality accident had occurred for a number of minutes. The quantity of plutonium which actually was present in the tank was about ten times more than was supposed to be there at any time during the procedure.

The employee died 35 hours later from the effects of a radiation exposure with the whole-body dose calculated to be $12,000 \text{ rem } \pm$.

Two other employees received radiation exposure of 134 and 53 rem, respectively. Property damage was negligible. (See TID-5360, Suppl. 2, p. 30; USAEC Serious Accidents Issue #143, 1-22-59.)

NUCLEAR EXCURSION Oak Ridge, Tenn., June 16, 1958

A nuclear accident occurred in a 55-gallon stainless steel drum in a processing area in which enriched uranium is recovered from various materials by chemical methods in a complex of equipment. This recovery process was being remodeled at the time of the accident.

The incident occurred while they were draining material thought to be water from safe 5-inch storage pipes into an unsafe drum.

Eight employees were in the vicinity of the drum carrying out routine plant operations and maintenance. A chemical operator was participating in the leak testing which inadvertently set off the reaction. He was within three to six feet of the drum, while the other seven employees were from 15 to 50 feet away.

Using special post hoc methods for determining the neutron and gamma exposures of the employees involved, it was estimated that the eight men received: 461 rem, 428 rem, 413

rem, 341 rem, 298 rem, 86 rem, 86 rem, and 29 rem.

Area contamination was slight, with decontamination costs amounting to less than \$1,000.

During this incident 1.3×10^{18} fissions occurred. (See TID-5360, Suppl. 2, p. 25; USAES Serious Accidents Issue #136, 8-25-59; USAEC Health and Safety Information Issue #82, 9-5-58; 1959 Nuclear Safety, Vol. 1, #2, p. 59.

GODIVA EXCURSION Los Alamos, N. Mex., Feb. 12, 1957

The "Godiva" assembly was to be used to irradiate uranium-loaded graphite samples. The samples were to be heated in a shielded furnace, exposed to a "prompt" burst of neutrons and then transferred to a counter for evaluation. The experiments are conducted at an isolated site in a building separated from the control room and all personnel by about a quarter of a mile.

On the occasion of the accident, preliminary bursts were being produced. In the process of lowering the top safety block, an unexpected burst occurred that was estimated to have produced 1.2×10^{17} fissions. The energy was great enough to tear the uranium parts from the assembly, knocking one to the floor, and to distort the steel rods in the frame. The uranium was deformed and there was much more surface oxidation than usual.

There were no personal injuries or overexposures. No gamma radiation above background was detected outside the reactor building. Radiation levels in the building were high initially... seven roentgens per hour gamma just inside the door (12' from Godiva) and 5,000 to 20,000 counts per minute (per 55 cm² probe) alpha on horizontal surfaces about the room; therefore cleanup procedures were delayed $2\frac{1}{2}$ days until they could be completed without unnecessary exposure to cleanup personnel.

The total property loss was estimated at \$2,400. (See TID-5360, Suppl. 2, p. 18; USAEC Health and Safety Information Issue #75, 1-8-58.)

HONEYCOMB EXCURSION Los Alamos, N. Mex., July 3, 1956

Too rapid assembly caused the system to be-

come promptly critical. The burst yield was $3.2 imes 10^{16}$ fissions.

There were no radiation exposures nor any property damage as a result of the incident.

EXPERIMENTAL REACTOR Oak Ridge, Tenn., Feb. 1, 1956

A homogenous $\rm UO_2F_2$ water-moderated critical assembly was made prompt critical by an overaddition of fuel to the assembly. Before reaching the critical point, the hand-operated valve was turned off. However, fuel continued to be added to the reactor because of air pressure in the line. Although the automatic safety system operated, assuring termination of the burst, considerable fuel was displaced from the reactor. The number of fissions in the burst was estimated to be about 1.6×10^{17} .

No serious exposures resulted, since all personnel were shielded by a minimum of five feet of concrete. There was no significant property damage and all uranium was recovered. (See TID-5360, Suppl. 1, p. 5.)

CORE MELTDOWN Idaho Falls, Idaho, Nov. 29, 1955

The Experimental Breeder Reactor (EBR-I) was undergoing a series of experiments.

Without modification, certain safety instrumentation would not permit the conduct of the experiment; therefore, reliance was placed on manual control to shut down the reactor.

During an experiment, the scientist in charge told the operator to press the "emergency reactor off" button. This would have instantaneously removed sufficient reactivity. Owing to a misunderstanding, the operator began by withdrawing the control rods at normal speed. This allowed the reactor to reach a higher power than anticipated and resulted in consequent melting of the fuel elements.

Shortly after the accident, there was a rise in the radiation level in the building. The building was evacuated. There were no personnel injuries. There was minor contamination of the sodium potassium coolant. (See TID-5360, p. 30.)

BORAX I EXPLOSION Idaho Falls, Idaho, July 22, 1954

Destruction of the Borax I Reactor released

135 MW-sec of fission energy.

More than 200 safety experiments were made on the Borax I Reactor simulating control rod accidents. For the last test, conditions were set up so that the reactor would be run to destruction.

The tests were carried out by withdrawing four of the five control rods far enough to make the reactor critical at a very low power level. The fifth rod was then fired from the core by means of a spring. In this test, the rod was ejected in approximately 0.2 seconds. After the control rod was ejected, an explosion took place in the reactor which carried away the control mechanism and blew out the core. At half a mile, the radiation level rose to 25 mr/hr. Personnel were evacuated for about 30 minutes.

No one was injured and the destruction of the reactor was part of the cost of the experiment. (See TID-5360, p. 29.)

EXCURSION IN AN ENRICHED URANIUM WATER SOLUTION Oak Ridge Tenn., May 26, 1954

The experiment in progress at the time of the incident was one in a series designed to study criticality conditions of uranium-water solutions in annular cylindrical containers.

The cause of the accident was a displacement of the central tube, effectively a poison rod, to a region of less importance. This displacement resulted from a dislocation of the positioning spider by a pin, used to connect sections of the liquid level indicator rack, protruding beyond the side of the rack and engaging a leg of the spider as the indicator was raised. Removing the compressional force from the top of the central tube allowed it to fall against the inside of the 10-inch cylinder. Although the displacement was small, it was sufficient to cause a large increase in the effective neutron multiplication.

The safety system apparently operated normally and the reaction was stopped automatically. All personnel in the building during the incident were protected by a minimum of five feet of concrete shielding; therefore, no serious exposures were incurred. (See TID-5360, p. 18.)

SUPERCRITICALITY EXPERIMENT Los Alamos, N. Mex., Feb. 3, 1954

The incident occurred in the course of an extensive study of the properties of supercritical radiation bursts produced by an assembly of fissionable metal. This study was covered by a specific procedure. A reference check of critical conditions preceded each supercritical burst.

To attain rapidly sufficient power for a delayed critical check, it was customary to set control rods at the position of minimum reactivity and insert a reactivity booster in the form of a fissionable metal slug. This time, when the booster was inserted, radiation indicators and the assembly temperature recorded went offscale (to return in a few minutes), and scrams were actuated. The resulting shock separated parts of the assembly and damaged steel supporting members.

There was no injury. The property loss was an expenditure of \$600 for repair of the assembly. (See TID-5360, p. 9.)

SUDDEN INCREASE IN REACTIVITY DURING CONTROL ROD TESTS Lemont, Ill., June 2, 1952

Manual withdrawal of a control rod from a critical assembly caused an accidental super-criticality.

The operation being conducted was the comparison of a series of newly-manufactured control rods. The assembly had been operated with the standard control rod. It was then shut down by inserting all control rods and draining the water moderator, a standard safe method of shutting down the assembly when core changes are to be made. The standard rod was removed and the first of the series of control rods to be tested was inserted.

The assembly was filled with water with the test control rod fully in and the standard type control rods fully inserted. Withdrawal of one of the standard control rods 32 centimeters caused the assembly to become critical and the power was leveled off while the desired measurements were made. The control rod was then reinserted into the original "in" position.

With the water still in the assembly, the four members of the crew then went into the assembly room for the purpose of replacing the control rod which they had just tested. The group leader went up on the platform, reached out with his right hand and started to pull out the tested rod. As soon as he had withdrawn it about one foot, the center of the assembly emitted a bluish glow and a large bubble formed. Simultaneously, there was a muffled explosive noise. The group leader let go of the control rod which he was removing and it fell back into position. The crew left the assembly room immediately and went to the control room.

Four employees received radiation exposures ranging from 12 to 190 rem. (See TID-5360, p. 23.)

CRITICALITY RESULTS FROM ERROR IN CALCULATIONS

Los Alamos, N. Mex., Apr. 18, 1952

Two stacks of fissionable disks were being built up stepwise to give a slightly subcritical assembly with the two stacks brought together by remote control. The individual stacks were built up by hand in fixed assemblies and the two stacks brought together only by remote mechanisms.

After two members of the operating crew calculated erroneously from previous steps that one more disk could be added safely, the disk was added and, with attempted caution, the system was assembled remotely. Radiation indicators went off-scale, actuating scrams, neutron counters jammed, and a puff of smoke was observed on the television viewer. Within three to five minutes indicators and counters returned to operating ranges.

There was no injury, no loss of material, no damage to facilities, and negligible loss of operating time. (See TID-5360, p. 7.)

EXCURSION IN A PLUTONIUM NITRATE SOLUTION

Richland, Wash., Nov. 16, 1951

Upon completion of volume measurements, it was thought that some additional information as to the required dilution could be determined by finding where criticality might occur on the rods. The control rod was pulled first with very minor reactivity effect. Following this, the safety rod was withdrawn intermittently at high speed (2.3"/sec). A waiting period for the delayed neutron effect of about 15 seconds was made just prior to the incident. This was

too short a time to determine whether or not the assembly was critical. The operators next heard the safety controls actuate, instrument indicators moved offscale, scalers jammed, and the most startling manifestation was that of the breakdown of "counters" playing back through the public address system. The portable "Juno" in the control room was offscale. Presumably, a further rod withdrawal had been made.

There were no injuries. The building was successfully decontaminated, except for the test room and assembly. Before decontamination of this area was completed, a fire occurred and, subsequently, the building was abandoned because of the respread of contamination. (See TID-5360, p. 14.)

SCRAM MECHANISM CAUSES CRITICALITY Los Alamos, N. Mex., Mar. 20, 1951

Interactions between two masses of fissionable material in water were measured at progressively decreasing horizontal separations. Remotely controlled operations established the desired horizontal separation of the two components and flooded the system.

After the final measurement, the system was "scrammed" (a rapid disassembly mechanism was actuated). Safety monitor indicators went off-scale, neutron counters jammed, and the television viewer indicated steaming. Within a few minutes, indicators and counters returned to operating ranges and indicated a rapid decay of radiation.

There was no injury, no loss of material, and no damage to facilities. (See TID-5360, p. 13.)

CRITICALITY DURING CONTROL ROD TESTS Los Alamos, N. Mex., December 1949

The reactor was being remodeled for higher power operation. As part of the required alterations, two new control rods had been placed in the system in addition to the three existing control rods.

The employee who had built the rod control mechanism wanted to test the comparative fall times of these new rods. He opened the enclosure on top of the reactor and manually lifted the rods, neglecting the possibility that this would affect the reactivity of the reactor because of its higher power arrangement. Here-

tofore, the three existing rods were sufficient for safety.

Normally, rods are raised remotely from the control room when the control panel is activated by a key switch. Since the rods were pulled out manually with the panel being off, no equipment was turned on except a direct reading temperature meter. Therefore, there were no neutron sensitive devices to record or warn of a rise in the neutron level. It was not observed until after the incident that the reactor temperature had risen about 25° centigrade.

The removal of the two rods probably gave a $\triangle K$ of about 0.86 percent, producing an initial period of about 0.16 second. Since the measured temperature coefficient is approximately -0.034 percent k/C°, the observed temperature rise indicates the rods were out sufficiently long so that the reactor was stopped by the negative temperature coefficient.

There were no injuries. The employee doing the work received 2.5 rem of gamma radiation according to his film badge. There was no damage done to the reactor and no loss of active material. (See TID-5360, p. 21.)

INADVERTENT SUPERCRITICALITY RESULTS IN DEATH

Los Alamos, N. Mex., May 21, 1946

A senior scientist was demonstrating the technique of critical assembly and associated studies and measurements to another scientist. The particular technique employed in the demonstration was to bring a hollow hemisphere of beryllium around a mass of fissionable material which was resting in a similar lower hollow hemisphere.

The system was checked with two one-inch spacers between the upper hemisphere and the lower shell which contained the fissionable material; the system was subcritical at this time.

Then the spacers were removed so that one edge of the upper hemisphere rested on the lower shell while the other edge of the upper hemisphere was supported by a screwdriver. This latter edge was permitted to approach the lower shell slowly. While one hand held the screwdriver, the other hand was holding the upper shell with the thumb placed in an opening at the polar point.

At that time, the screwdriver apparently slipped and the upper shell fell into position around the fissionable material. Of the eight people in the room, two were directly engaged in the work leading to this accident.

The "blue glow" was observed, a heat wave felt, and immediately the top shell was slipped off and everyone left the room. The scientist who was demonstrating the experiment received sufficient dosage to result in injuries from which he died nine days later. The scientist assisting received sufficient radiation dosage to cause serious injuries and some permanent partial disability.

The other six employees in the room suffered no permanent injury. (See TID-5360, p. 4.)

FATALITY FROM CRITICAL MASS EXPERIMENTS Los Alamos, N. Mex., Aug. 8, 1945

During the process of making critical mass studies and measurements, an employee working in the laboratory at night alone (except for a guard seated 12 feet away) was stacking blocks of tamper material around a mass of fissionable material.

As the assembly neared a critical configuration, the employee was lifting one last piece of tamper material which was quite heavy. As this piece neared the setup, the instrument indicated that fission multiplication would be produced, and as the employee moved his hand to set the block at a distance from the pile, he dropped the block, which landed directly on top of the setup.

A "blue glow" was observed and the employee proceeded to disassemble the critical material and its tamper. In doing so, he added heavily to the radiation dosage to his hands and arms.

The employee received sufficient radiation dosage to result in injuries from which he died 13 days later.

The guard suffered no permanent injury. (See TID-5360, p. 2.)

UNANTICIPATED CRITICALITY IN WATER-SHIELDED ASSEMBLY

Los Alamos, N. Mex., June 4, 1945

An experiment was designed to measure the critical mass of enriched uranium when surrounded by hydrogenous material. The enriched uranium was in the form of cast blocks of the

metal, $\frac{1}{2}" \times \frac{1}{2}" \times \frac{1}{2}"$ and $\frac{1}{2}" \times \frac{1}{2}" \times 1"$. The blocks were stacked in a pseudospherical arrangement in 12 courses in a $6'' \times 6'' \times 6''$ polyethylene box. The voids in the courses were filled with polyethylene blocks of appropriate dimensions. The polyethylene box was supported by a 2-foot-high stool within a 3-foot cubical steel tank. The tank had a 2-inch opening in the bottom through which it could be filled and drained by means of supply and drain hoses attached to a 3/4-inch tee. The opening in the tank was fitted with a shutoff valve, as was the drain hose. A poloniumberyllium source of about 200 mc strength was placed on top of the assembly. A fission chamber and a boron proportional counter were used to follow the experiment.

The immediate supervisor was absent from the scene when the experiment was begun. According to one of the operators, the water level was raised above the polonium-beryllium source with the supply valve almost fully open. At this point, a slight increase in counting rate was observed, which corresponded with what had been observed previously when the source alone was immersed in water. A few seconds later, the counting rate began to increase at an alarming rate.

At this point, the supervisor returned, walked to within three feet of the tank and noted a blue glow surrounding the box. Simultaneously, the two operators were hastily closing the supply valve and opening the drain valve. The building was evacuated.

The three individuals involved received excessive radiation exposures, estimated in two cases as about 66.5 rem, and in the third as 7.4 rem. The doses delivered to the head and neck of these individuals may have been considerably greater. They were hospitalized for observation, but no untoward symptoms appeared. No significant changes in blood counts were observed, and sperm counts on one occasion, sometime after the incident, were normal. It is not believed that the individuals concerned received any significant radiation damage. There was no damage to equipment, no loss of active material, and no local contamination problem. (See TID-5360, p. 10.)

DRAGON REACTOR EXCURSION Los Alamos, N. Mex., Feb. 11, 1945

This was the first reactor designed to generate prompt power excursions. Prompt critical was obtained by dropping a slug of UH_3 in styrex through a vertical hole in a small assembly of the same material, which was diluted with polyethylene and reflected by graphite and polyethylene. Near the end of the planned sequence of burst of increasing power, a 6×10^{15} fission burst blistered and swelled the small cubes comprising the assembly matrix. No material was lost, there was no contamination, and there were no exposures.

PART V

BEST NO-INJURY RECORDS KNOWN IN AEC ACTIVITIES

The following list, broken down into the six principal categories of work involved in the AEC's activities, shows the names of the top three contractors and field offices completing the largest number of continuous man-hours in their category without a disabling injury.

Contractor or Field Office and Location	Man-Hours	Dates					
Production:							
E. I. du Pont de Nemours & Co., Inc., Aiken, S.C.	39,345,150	6/24/67 to 5/ 2/72					
Monsanto Research Corp., Mound, Ohio	32,507,781*	8/24/66 to 1/18/75					
The Dow Chemical Co., Rocky Flats Division Golden, Colo	24,295,542	9/17/57 to 7/10/63					
Research:							
Westinghouse Electric Corp, Bettis Atomic Power Laboratory, West							
Mifflin, Pa	19,194,917	10/27/62 to 11/22/65					
Sandia Corp., Albuquerque, N. Mex	14,936,169	7/16/59 to 9/ 6/60					
Phillips Petroleum Co., Idaho Falls, Idaho	12,921,162	12/ 5/62 to 1/13/66					
Services:							
EG&G, Inc., Las Vegas, Nevada	6,692,830	6/29/70 to 2/25/74					
Computer Science Corp., Richland, Wash.	3,744,009	7/ 1/65 to 1/18/75					
Lucius Pitkin, Inc., Grand Junction, Colo.	3,387,104	12/ 2/60 to 1/19/75					
Construction:							
E. I. du Pont de Nemours & Co., Inc. Augusta, Ga	4,847,317	2/26/57 to 2/29/58					
E. I. du Pont de Nemours & Co., Inc. Augusta, Ga	3,730,361	2/22/54 to 4/ 7/54					
Holmes & Narver, Honolulu, Hawaii	3,241,292	6/12/70 to 11/15/72					
Architect-Engineering:							
Ebasco Services, Inc. New York, N.Y.	1,522,000	11/17/60 to 12/11/70					
Vitro Engineering, Richland, Wash	1,275,337	6/ 1/72 to 12/31/74					
Hanford Engineering Services, Richland, Wash	1,142,862	5/15/63 to 3/31/67					
Gernment:							
Savannah River Operations Office	4,935,000*	10/ 5/61 to 8/13/75					
Richland Operations Office	4,885,300	12/ 3/63 to 7/14/72					
Idaho Operations Office	4,301,828	1/22/62 to 5/ 1/66					

^{*}Record continuing.

APPENDIX A

FATALITIES

Manhattan Engineer District—Atomic Energy Commission 1943—1975

BRIEF DESCRIPTIONS OF FATALITIES MED—AEC 1943–1975

No.	Date	Field Office ¹ & Facility ²	Remarks
1	4-15-43	ALA-C	A plumber drowned when the driver of a pickup truck, in which ten men were riding, lost control of the truck and is overturned, landing in a water-filled drainage ditch.
2	5- 3-43	CL-C	A laborer was crushed to death when he walked in front of a moving Caterpillar tractor.
3	5 543	CL-C	While working under a railway cement car, a laborer was crushed to death when a mechanical failure caused the braker to release the car and it ran over him.
4	5-29-43	на-с	While a truck driver was servicing a dump truck with the bed in the raised position, the bed dropped, crushing his chest.
5	7-26-43	на-с	While a tractor was being operated, it dropped into an unbarricaded gravel pit, crushing the driver, a mechanic.
6	7-26-43	CL-C	While working on a scaffold, bricklayer suffered a broken neck when he was thrown 10' to the ground after the staging collapsed.
7	7-28-43	HA-C	A heavy equipment operator was crushed by a Caterpillar when it dropped off the edge of the working area, throwing him onto the Caterpillar track which carried him over the front of the track and ran over him.
8	7-28-43	CL-C	A lineman was electrocuted while working on a transformer platform when he placed his hand, protected by a canvaglove only, on a primary bushing which connected directly to an insulated neutral bus.
9	8-16-43	CL-C	A laborer was decapitated by a Caterpillar-drawn scraperpan which ran over him after he had slipped in soft dirt and fallen in the track of the machine.
10	8-17-43	WR-C	A painter died of multiple internal injuries from a 25' fall to the ground when stepping through a door into a room where the temporary flooring had been removed, preparatory to the installation of the permanent flooring.
11	8-19-43	CL-C	An oiler was crushed to death under the wheels of a railway freight engine where he was thrown from a truck. The driver of the truck had started across the tracks at a railway crossing after the engine had passed, when the engine suddenly backed up and struck the truck.
12	9- 9-43	CL-C	A brakeman was crushed to death under the wheels of a railway freight engine where he had fallen when he slipped while crossing in front of the drawbar.
13	10- 3-43	НА-С	The driver of a water truck stopped by the roadside to offer assistance to another trucker. The driver of a third truck, attempting to avoid a head-on collision, veered, striking both of the standing drivers, resulting in the death of the water tank driver from multiple internal and skeletal injuries. The other driver fractured both legs.
14	10-16-43	НА-С	A lineman, in changing his position on a pole, erroneously thought his safety belt had "clicked" shut, and fell 26 He died from a fractured skull and brain injury.
15	11- 2-43	CL-C	While standing on wet ground, a crane oiler was electrocuted when the crane boom contacted overhead wires.
16	11- 9-43	HA-C	A truckdriver was riding in a tractor with an inexperienced driver. The tractor skidded, causing the trailer to pus the truckdriver into a windshield frame. He died four days later as a result of a crushed chest and a collapsed lun- caused by the accident.
17	11-17-43	CL-C	A laborer was burned to death when his oil-splashed clothing ignited after he had thrown fuel oil on an open fire. H increased the intensity of the flames by running through an open field for help.
18	11-20-43	НА-С	During the unloading of heavy structural steel from a freight car, a 24' steel column fell on a rigger, crushing hi chest cage.
19	11-29-43	CL-C	A laborer's chest was crushed when a wall section of an unshored 8-foot trench in which he was working caved i and covered him with dirt.
20	1- 4-44	CL-C	The skull of a laborer was fractured when he was thrown from the bed of a convoy truck, with no tailgate, after the driver hit a small depression in a dirt road, causing the truck to lunge to one side.
21 22 23 24	1-13-44	НА-С	The collision of two onsite railroad trains, operating in a fog, resulted in the deaths of two engineers, a conductor an a fireman from multiple internal and skeletal injuries.
25	2-11-44	CL-C	Fatal injuries were suffered by a welder when the chain hoist broke and the suspended station wagon, under which he was working, fell across his back.
26	2-14-44	CL-C	The skull of a carpenter was fractured as the result of a 10' fall from a ladder after the ground, which had been froze when the ladder was put in place, thawed sufficiently to allow one of the footings to settle and the ladder to slip
	0.00.44	10-O	A chemist was working on an experiment when a chemical explosion took place. He died of multiple internal injuries
27	2-29-44	10-0	

BRIEF DESCRIPTIONS OF FATALITIES—Continued

MED-AEC 1943-1975

No	Date	Field Office ¹ & Facility ²	Remarks
29	3-24-44	CL-C	While standing near a crane, a carpenter was electrocuted when the crane boom contacted high voltage wires
30	5- 2-44	CL-C	During a welding operation in an elevator shaft, an ironworker was fatally burned in an explosion caused by a spark from his welding torch igniting oxygen remaining after the air had been purged
31	5- 4-44	CL-C	When a truck driver lost control of the truck he was driving, it overturned and he was crushed under it
32	5- 9-44	CL-C	A truckdriver was crushed between the seat and the steering wheel of the Dumpster he was operating when a dump truck backed into him
33	5–2 7–44	CL-C	While standing on the unplaced end of a 24' steel I beam, an ironworker received fatal head and neck injuries when the beam end sheared off when he struck it with his sledge hammer to force it into place, causing him to fall into the angle formed by the beam and the upright column
34	6-12-44	DE-C	An electrician was fatally injured by receiving an electric shock caused by short in a rectifier
35 36 37 38 39	6-14-44	НА-С	Five welder chippers were crushed to death when a 49-ton steel tank fell upon them when its shoring failed
40	6-22-44	HA-C	While standing on a 4' pipe a carpenter foreman fell 23' He died the following day of a fractured skull and brain injury received from the fall
41	7-11-44	CL-C	When a sheet metal worker crawled through an opening in the roof to pry open a hatch cover, he fell 35' through transite flooring to the cell floor. He died from a fractured skull and brain injury
42	7-15-44	CL-C	An electrician was electrocuted while standing adjacent to exposed leads operating an electrical testing machine, when he threw the switch on the tester, energizing the cables, and his leg came into contact with the leads
43	7-17-44	$_{ m HA-C}$	A machine operator was crushed between two 9400 lb concrete pipes, while engaged in storing the pipe
44	7-22-44	НА-О	While driving a pickup truck at a high rate of speed, the driver, an instrument engineer, was thrown from the truck and killed when it turned over twice. He died of multiple internal and skeletal injuries
45 46 47	8-12-44	CL-C	Three crew members disappeared (presumed dead) when an airplane was lost. Numerous searching missions failed to yield any evidence of plane or crew
48	8-17-44	CL-O	An electrician was electrocuted when he climbed upon the top of the cab in the course of repairing a crane and fell into a 440 volt bus
49	10-14-44	CL-C	A cement finisher received a fractured skull and brain injury from a 28½' fall through the transite cover over a floor opening
50	10-19-44	CL-C	A boilermaker received a fractured skull and brain injury in a 35 fall to a concrete floor when he lost his balance
51	10-25-44	CL-O	After testing motor field coils for faulty insulation, an electrician failed to open the switch to disconnect the current and was electrocuted when he removed the electrodes simultaneously with both hands
52	11- 6-44	CL-O	A low voltage panel cover had been removed and the leads within the cubicle extended outside. A serviceman, hold ing the leads in his hand, was startled when they contacted, creating an arc, causing him to strike his knee against the energized cubicle, resulting in his electrocution.
53	11-11-44	CL-C	When an ironworker lost his hold while descending between two joists from a scaffold, he fell 11 to a concrete floor, fracturing his skull
54	1-15-45	CL-C	An ironworker and an inspector were crushed to death when a boom collapsed and the load and boom fell on them
55 56	1-18-45	CL-C	When a carpenter placed his hands, bearing the weight of his body, on the unsupported end of a scaffold, it tilted, throwing him 18' to the floor below. He died from a fractured skull and brain injury
57	1-22-45	CL-O	A millwright was burned to death when he drew gasoline from a welding generator into a metal pail, which contacted the energized terminal on the starter motor, causing a spark to ignite the gasoline
58	2- 6-45	CL-O	A millwright died as the result of the inhalation of chemical fumes while replacing a plug cock in a distillation line
59	4- 5-45	CL-C	An electrician was electrocuted when his arm contacted exposed terminals as he was drilling a hole in a panel box
60	5- 8-45	CL-O	A process operator was electrocuted when his arm made contact with a metal part of a circuit while he was cleaning glass in a tank
61	6- 4-45	CL-C	An ironworker rigger was electrocuted when the rigging swung into a 13,800 volt powerline as he was steadying the load by holding to the choker line

No	Date	Field Office ¹ & Facility ²	Remarks
62	6-11-45	CL-O	A carpenter was electrocuted while repairing a door hinge on an inoperative unit when he removed the insulated bar- rier from the adjacent operating unit and reached through the opening to tighten the nut holding the hinge assembly and his hand contacted the current carrying part
63	7- 2-45	CL-C	The chest cage of a rigger was crushed when a crane boom fell on him.
64	7-23-45	CL-O	A painter was electrocuted when he lost his balance, and grasped a 460-volt trolley line and an I beam and fell to the floor.
65	8- 4-45	CL-O	An electrician was electrocuted while repairing a light fixture when he contacted the circuit through the pliers in his right hand and the conduit in his left hand
66	8- 7-45	SF-G	A carpenter was crushed to death when a bulldozer, being used to push dirt onto the roof of a leanto shelter, was ru onto the top of the shelter, collapsing the roof and burying him in the dirt that caved in.
67	8-21-45	SF-O	A physicist, working alone at night, caused an inadvertent criticality, which resulted in his receiving radiation from which he died 13 days later (See TID-5360, p. 2).
68	9-12-45	НА-С	While riding in the back of a pickup truck, a laborer received fatal internal injuries when he was thrown out of the truck when it was hit by another truck.
69	9-21-45	CL-C	A steamfitter was about to ascend a stairway when a piece of angle iron fell 35' from the floor above, fracturing h skull
70	10- 9-45	CL-C	An electrician was electrocuted while conducting a dummy load test at a tank that had not been de-energized. He neglected to use ground hooks before entering the unit, and his hand contacted the current when he attempted to attach the dummy load cable.
71	11-14-45	CL-O	While working in a dimly lighted area, an inspector stepped into a duct to inspect a fan, unaware that the grating had not been installed, and fell 15' through the opening to the floor.
72	11-19-45	CL-O	A baker was electrocuted while working in his bare feet washing the floor and hosing down the walls of a bakesh when he contacted current from a defective ungrounded pedestal electric fan
73	2- 5-46	SF-G	A blacksmith was struck by a truck.
74	3-19-46	SL-C	While installing a light fixture, an electrician fell approximately $7\frac{1}{2}$ from a scaffold. He died from a fractured sky and brain injury
75	4- 4-46	CL-G	A guard drowned when he lost control of the jeep he was driving and ran off a bridge into a creek
76	5-21-46	SF-O	While demonstrating the technique of critical assembly, an inadvertent criticality occurred, resulting in the death nine days later of the demonstrator, senior scientist (See TID-5360, p 4)
77	7- 1-46	SF-O	A truckdriver was killed when his truck turned over
78	8- 2-46	SF-O	An engineer was killed as the result of a chemical explosion.
79	8- 7-46	SF-O	A tractor driver died from multiple internal injuries when he lost control of the tractor he was driving.
80	8-10-46	HA-G	A pilot was killed in an airplane crash.
81	10- 7-47	OR-O	An electrician was electrocuted when he contacted a 460 volt line which he assumed to be de energized
82	11-18-47	SF-O	An ironworker was electrocuted when a crane beam came into contact with a high tension line while he was attempting to block up the outriggers of the crane
83	11-28-47	OR-C	An order received fatal second and third degree burns when the hose from a gasoline tank truck sprayed gasoline him, as well as on the surrounding area, after which fire from a nearby salamander ignited the gasoline.
84	1943-46	SF-O	A junior scientist received chronic beryllium poisoning as a contractor employee between 1943 and 1946. He died December 1947
85	3~18-48	SF-O	Speeding while driving resulted in an automobile accident which pinned the driver under the automobile. He die of a skull fracture and brain injury.
86	3-29-48	на-с	A truckdriver was pinned between the body and the frame of a concrete dump truck when the elevated body fell. I died of multiple internal and skeletal injuries
87	4- 9-48	OR-C	A runaway gondola car containing sand pinned a bin operator, working on a nearby cement car, under its whe crushing his chest.
88	6-26-48	SF-O	A lineman was electrocuted while climbing a pole.
89	7-31-48	НА-О	The driver of a weapons carrier was pinned between the ground and the rim of the steering wheel when the carriwent out of control and landed in a ditch. He died from a skull fracture and a crushed chest.

See footnotes at end of table.

90 9-25-48 SF-C An ironworker was electrocuted during the installation of electrical cables 91 11-22-48 HA-G A motor vehicle collision resulted in internal injuries to a records analyst his injuries five days later 92 11-25-48 OR-O During horseplay, a guard accidentally shot another guard in the abdom 93 12-13-48 OR-C An air tool operator and a pipelayer died of suffocation as the result of the 94 SF-C A truckdriver was killed when the truck he was driving hit debris in the rongumped from the truck and the truck he was driving hit debris in the rongumped from the truck and the truck passed over his body crushing he 6-29-49 CH-O While working in a pit of a power plant steamline, a steam valve broke, resulting in fatal second and third degree burns 97 8-26-49 SF-C When a scaffold rope broke, a painter fell 26 to the bottom of a steel to fracture 98 11-14-49 OR-O A laborer died of multiple internal injuries received when he got caught 99 11-23-49 HA-C A piledriver operator fell 4' into a river and drowned 100 12- 1-49 SF-C During the construction of a building wall, one section fell, killing an irong 101 2-11-50 SF-G Two security guards were killed in an airplane crash 104 6-23-50 OR-C A deckhand received foot injuries when his foot was caught between the Complications of the injuries caused his death 104 6-23-50 OR-C A laborer, cleaning cement residue from supporting beams while standing the concrete floor, causing a basal skull fracture 105 8-2-50 OR-C An ironworker foreman was electrocuted when a crane boom contacted of a hitch 106 8-31-50 SF-G A warehouseman was riding on the running board of a pickup truck When to collide head on with a bus the warehouseman either jumped or fell in ded of the internal injuries received	
his injuries five days later 92 11-25-48 OR-O During horseplay, a guard accidentally shot another guard in the abdom 93 12-13-48 OR-C An air tool operator and a pipelayer died of suffocation as the result of the sum of	S
93 12-13-48 OR-C An air tool operator and a pipelayer died of suffocation as the result of the 94 94 95 6-20-49 SF-C A truckdriver was killed when the truck he was driving hit debris in the rogumped from the truck and the truck passed over his body crushing he 96 6-29-49 CH-O While working in a pit of a power plant steamline, a steam valve broker resulting in fatal second and third degree burns. 97 8-26-49 SF-C When a scaffold rope broke, a painter fell 26 to the bottom of a steel to fracture. 98 11-14-49 OR-O A laborer died of multiple internal injuries received when he got caught 99 11-23-49 HA-C A piledriver operator fell 4' into a river and drowned. 100 12- 1-49 SF-C During the construction of a building wall, one section fell, killing an irogum 101 2-11-50 SF-G Two security guards were killed in an airplane crash. 103 4- 6-50 SF-C A deckhand received foot injuries when his foot was caught between the Complications of the injuries caused his death. 104 6-23-50 OR-C A laborer, cleaning cement residue from supporting beams while standing the concrete floor, causing a basal skull fracture. 105 8- 2-50 OR-C An ironworker foreman was electrocuted when a crane boom contacted of a hitch. 106 8-31-50 SF-G A warehouseman was riding on the running board of a pickup truck When to collide head on with a bust the warehouseman either jumped or fell it.	He died from pneumonia complications of
95 6-20-49 SF-C A truckdriver was killed when the truck he was driving hit debris in the ro jumped from the truck and the truck passed over his body crushing hit debris in the ro jumped from the truck and the truck passed over his body crushing hit debris in the ro jumped from the truck and the truck passed over his body crushing hit debris in the ro jumped from the truck and the truck passed over his body crushing hit debris in the ro jumped from the truck and the truck passed over his body crushing hit debris in the ro jumped from the truck and the truck he was driving hit debris in the ro jumped from the truck and the truck he was driving hit debris in the ro jumped from the truck and the truck he was driving hit debris in the ro jumped from the truck and the truck he was driving hit debris in the ro jumped from the truck and the truck he was driving hit debris in the ro jumped or fell in the round from the truck and the truck he was driving hit debris in the round from the truck he was driving hit debris in the roushing hit debris in the round hit degree burns 96 6-29-49 CH-O While working in a pit of a power plant tread over his body crushing hit debris in the round hit degree burns 97 8-26-49 SF-C When a scaffold rope broke, a painter fell 26 to the bottom of a steal tracker. 98 11-14-49 OR-O A laborer died of multiple internal injuries received when he got caught to a steal tracker. 101 12-14-49 OR-O A piledriver operator fell 4' into a river and drowned 102 11-23-49 HA-C A piledriver operator fell 4' into a river and drowned 103 12-14-49 SF-C During the construction of a building wall, one section fell, killing an iround from the construction of a building wall, one section fell, killing an iround from the construction of a building wall, one section fell the fracture 103 12-14-49 SF-C During the construction of a building wall, one section fell the fracture 104 12-14-49 SF-C During the construction of a building wall, one section fell the fracture 105 12-14-49 SF-C During the construction of a	en, thinking the gun was unloaded
jumped from the truck and the truck passed over his body crushing h 96 6-29-49 CH-O While working in a pit of a power plant steamline, a steam valve broke, resulting in fatal second and third degree burns 97 8-26-49 SF-C When a scaffold rope broke, a painter fell 26 to the bottom of a steel ta fracture 98 11-14-49 OR-O A laborer died of multiple internal injuries received when he got caught 99 11-23-49 HA-C A piledriver operator fell 4' into a river and drowned 100 12- 1-49 SF-C During the construction of a building wall, one section fell, killing an iron 101 2-11-50 SF-G Two security guards were killed in an airplane crash 102 A deckhand received foot injuries when his foot was caught between the Complications of the injuries caused his death 104 6-23-50 OR-C A laborer, cleaning cement residue from supporting beams while standing the concrete floor, causing a basal skull fracture 105 8- 2-50 OR-C An ironworker foreman was electrocuted when a crane boom contacted of a hitch 106 8-31-50 SF-G A warehouseman was riding on the running board of a pickup truck When to collide head on with a bus the warehouseman either jumped or fell is	he cave in of a newly dug trench
resulting in fatal second and third degree burns 97 8-26-49 SF-C When a scaffold rope broke, a painter fell 26 to the bottom of a steel ta fracture 98 11-14-49 OR-O A laborer died of multiple internal injuries received when he got caught 99 11-23-49 HA-C A piledriver operator fell 4' into a river and drowned 100 12- 1-49 SF-C During the construction of a building wall, one section fell, killing an iron 101 2-11-50 SF-G Two security guards were killed in an airplane crash 102 103 4- 6-50 SF-C A deckhand received foot injuries when his foot was caught between the Complications of the injuries caused his death 104 6-23-50 OR-C A laborer, cleaning cement residue from supporting beams while standing the concrete floor, causing a basal skull fracture 105 8- 2-50 OR-C An ironworker foreman was electrocuted when a crane boom contacted of a hitch 106 8-31-50 SF-G A warehouseman was riding on the running board of a pickup truck When to collide head on with a bus the warehouseman either jumped or fell is	•
fracture 98 11-14-49 OR-O A laborer died of multiple internal injuries received when he got caught 99 11-23-49 HA-C A piledriver operator fell 4' into a river and drowned 100 12- 1-49 SF-C During the construction of a building wall, one section fell, killing an iron 101 2-11-50 SF-G Two security guards were killed in an airplane crash 102 103 4- 6-50 SF-C A deckhand received foot injuries when his foot was caught between the Complications of the injuries caused his death 104 6-23-50 OR-C A laborer, cleaning cement residue from supporting beams while standing the concrete floor, causing a basal skull fracture 105 8- 2-50 OR-C An ironworker foreman was electrocuted when a crane boom contacted of a hitch 106 8-31-50 SF-G A warehouseman was riding on the running board of a pickup truck When to collide head on with a bus the warehouseman either jumped or fell it.	, enveloping a maintenance man in steam,
99 11-23-49 HA-C A piledriver operator fell 4' into a river and drowned 100 12- 1-49 SF-C During the construction of a building wall, one section fell, killing an iron 101 2-11-50 SF-G Two security guards were killed in an airplane crash 102	ank, striking his head, causing a basal skull
100 12- 1-49 SF-C During the construction of a building wall, one section fell, killing an iron 101 2-11-50 SF-G Two security guards were killed in an airplane crash 102 103 4- 6-50 SF-C A deckhand received foot injuries when his foot was caught between the Complications of the injuries caused his death 104 6-23-50 OR-C A laborer, cleaning cement residue from supporting beams while standin 105 8- 2-50 OR-C An ironworker foreman was electrocuted when a crane boom contacted of a hitch 106 8-31-50 SF-G A warehouseman was riding on the running board of a pickup truck When 107 to collide head on with a bus the warehouseman either jumped or fell it	between a truck and a loading platform
101 2-11-50 SF-G Two security guards were killed in an airplane crash 102 103 4- 6-50 SF-C A deckhand received foot injuries when his foot was caught between the Complications of the injuries caused his death 104 6-23-50 OR-C A laborer, cleaning cement residue from supporting beams while standing the concrete floor, causing a basal skull fracture 105 8- 2-50 OR-C An ironworker foreman was electrocuted when a crane boom contacted of a hitch 106 8-31-50 SF-G A warehouseman was riding on the running board of a pickup truck When to collide head on with a bus the warehouseman either jumped or fell it.	
102 103 4- 6-50 SF-C A deckhand received foot injuries when his foot was caught between the Complications of the injuries caused his death 104 6-23-50 OR-C A laborer, cleaning cement residue from supporting beams while standing the concrete floor, causing a basal skull fracture 105 8- 2-50 OR-C An ironworker foreman was electrocuted when a crane boom contacted of a hitch 106 8-31-50 SF-G A warehouseman was riding on the running board of a pickup truck When to collide head on with a bus the warehouseman either jumped or fell it.	nworker and injuring six others
Complications of the injuries caused his death 104 6-23-50 OR-C A laborer, cleaning cement residue from supporting beams while standing the concrete floor, causing a basal skull fracture 105 8- 2-50 OR-C An ironworker foreman was electrocuted when a crane boom contacted of a hitch 106 8-31-50 SF-G A warehouseman was riding on the running board of a pickup truck When to collide head on with a bus the warehouseman either jumped or fell it.	
the concrete floor, causing a basal skull fracture 105 8- 2-50 OR-C An ironworker foreman was electrocuted when a crane boom contacted of a hitch 106 8-31-50 SF-G A warehouseman was riding on the running board of a pickup truck When to collide head on with a bus the warehouseman either jumped or fell it.	e deck of a boat and the guardrail of a tug
a hitch 106 8-31-50 SF-G A warehouseman was riding on the running board of a pickup truck When to collide head on with a bus the warehouseman either jumped or fell is	g on a ladder, fell 18, striking his head on
to collide head on with a bus the warehouseman either jumped or fell i	overhead energized wires as he was making
·	
107 9-21-50 OR-O A tractor, being driven by a farm laborer, got out of control, turned over	er and crushed him to death
108 11-29-50 SF-C While working in a pipe trench, an air tool operator was crushed by a 16	6 pipe falling on him
109 1- 2-51 SF-C A painter fell 45' from a scaffold fracturing his skull (See USAEC SER	LIOUS ACCIDENTS Issue #1, 1-24-51)
110 1-23-51 SF-C A carpenter fell 23 from a fire tower striking the base of his skull on a co DENTS Issue #2, 2-15-51)	oncrete pad (See USALC SERIOUS ACCI-
111 2- 9-51 OR-O A rigger died as a result of injuries received when his head was caught be on a railroad car (See USAEC SPRIOUS ACCIDENTS Issue #2, 2-:	
112 3-8-51 OR-C While lowering a transformer section, a lineman's hands slipped off the him under the right eye. He died as a result of head and neck injuries (i #3, 3-16-51)	
113 3-18-51 SNR-O A laboratory employee was asphyxiated by the accidental presence of respirator was attached (See TID-5360 p 9, USAEC SERIOUS AC	nitrogen in a process air line to which his CCIDENTS Issue #4, 4-10-51)
114 3-20-51 OR-C A truck driver was electrocuted when a crane boom came into contact was helping adjust the cables of the crane	with an energized electric powerline while he
115 3-20-51 ID-C While working on a water tower, a welder fell 15 when a truck was driver which he was standing breaking the cable He died of a fractured sku ACCIDENTS Issue #5 4-12 51)	n over a cable supporting the platform upon ill and brain injury (See USAEC SERIOUS
116 4-11-51 SF-O A painter died ifter using carbon tetrachloride in cleaning procedures SERIOUS ACCIDI NTS Issue #8, 6 20-51)	prior to spraving with paint (See USAEC
117 6 25-51 OR-C During the cleaning procedures of a condenser being installed, the use of a millwright	carbon tetrachloride resulted in the death o
118 7-23-51 SR-C A steamfitter suffered a heatstroke while helping to hook up a river suc	etion pump
See footnotes at end of table	FF

No	Date	Field Office ¹ & Facility ²	Remarks
119 120	7-27-51	SF-C	The head-on collision of two 5,000-gal water tank trucks crushed the bodies of both drivers. (See USAEC SERIOUS ACCIDENTS Issue #10, 8-24-51)
121	8-13-51	OR-C	During the unloading of crane sections from a box-ar with a winch truck, one load fell on an ironworker foreman, resulting in his death from a skull fracture and brain injury. (See USAEC SERIOUS ACCIDENTS Issue #12 10-4-51).
122	8-13-51	SF-C	A mechanical engineer's chest was crushed when a dump truck he was directing backed over him.
123	8-24-51	OR-O	A lineman fell 15' while checking the output current of a lighting transformer. He died from a fractured skull and brain injury.
124	10-13-51	OR-C	While working $22\frac{1}{2}$ aboveground, a carpenter stepped on a faulty board and fell, dying two days later as a result of head and brain injuries received in the fall.
125	10-20-51	OR-C	When a sheetmetal worker stepped on an unsupported piece of metal roofing, he fell 41', resulting in his death from multiple internal and skeletal injuries.
126	10-29-51	ID-C	The wall of a warehouse under construction was blown over by high winds, pinning a carpenter underneath it. He died as the result of a broken neck. (See USAEC SERIOUS ACCIDENTS Issue #14, 1-3-52).
127	11-14-51	SR-C	A traffic clerk was killed when the car he was driving got out of control and dropped into a 6' ditch. He died from a crushing injury to his chest with total transsection of the aorta
128	11-14-51	SF-C	A laborer was suffocated when he was buried alive under loose earth which was pushed down upon him by a bull dozer
129	11-21-51	СН-О	A machinist was electrocuted when the boom of a crane came into contact with a live powerline as he lifted a floodligh from a truck, the current traveling through the boom and truck. (See USAEC SERIOUS ACCIDENTS Issue #16, 1-11-52)
130	11-29-51	SR-C	An ironworker fell 70' when the unfastened board he was standing on was pushed off its bearing by the reactionar force of the impact wrench he was using. He died from a committed basal skull fracture. (See USAEC SERIOU ACCIDENTS Issue #17, 1-14-52)
131	12- 7-51	OR-C	An ironworker died from a skull fracture and brain injury in a 22' fall onto a concrete floor (See USAEC SERIOUS ACCIDENTS Issue #17, 1-14-52).
132	12-14-51	SR-C	A carpenter died from a broken neck in a 28' fall when he removed a piece of plywood covering from a floor opening and fell through the hole to the concrete floor below (See USAEC SERIOUS ACCIDENTS Issue #17, 1-14-52)
133	1-30-52	OR-C	A pipefitter's head was crushed when a dumptruck backed over him
134	3-13-52	SF-O	A truckdriver died of a compound fractured skull when a large magnet fell on him.
135	3-21-52	OR-C	An ironworker was electrocuted when a crane hit live electric wires while he was guiding the crane with his hand of the load
136	3-27-52	SF-C	A heavy equipment foreman died of multiple internal and skeletal injuries when the track of a heavy crane passe over him (See USAEC SERIOUS ACCIDENTS Issue #25, 6-23-52).
137	5-26-52	SF-C	An ironworker was crushed between the counterweight of a ciane and the angle iron at the equipment box on the truck chassis of the crane (See USAEC SERIOUS ACCIDENTS Issue #25, 6-23-52).
138	7- 3-52	SF-C	An ironworker was electrocuted when the boom of a crane came into contact with a temporary distribution line while he was handling a steel column suspended from the crane.
139	8-11-52	SF-C	While repairing a boat, a mechanic was electrocuted while handling an electric pump.
140	9- 4-52	OR-C	A painter was killed, during the moving of a scaffold, when he fell 45' to the concrete floor, fracturing his skull. (Se USAEC SERIOUS ACCIDENTS Issue #35, 1-7-53).
141	9-18-52	GJ-O	An equipment operator apparently fell asleep while driving a jeep and was killed when the jeep struck a bridge abut ment. He died of a skull fracture and brain injury. (See USAEC SERIOUS ACCIDENTS Issue #31, 10-15-52)
142	9-29-52	OR-C	A laborer hauling concrete fell 29' when a concrete-hauling cart started moving backward, causing him to be pushe off the platform on which he was standing. He died of a skull fracture and brain injury.
143	11- 8-52	OR-C	A crane flagman was struck by a dirt loading truck when he stepped in its path after signaling its driver to proceed. He died of multiple internal injuries
144	1-14-53	OR-C	While repairing a road scraper, which was blocked up, a welder was pinned under the machine when the blocking gave way. He died two days later from multiple internal injuries
145	3- 6-53	SR-C	While spray painting a pump intake basin, two employees received fatal second and third degree burns during

See footnotes at end of table.

No	Date	Field Office ¹ & Facility ²	Remarks
146			flash fire, probably caused by the ignition of the flammable solvent in the paint by an open light bulb (See USAEC SERIOUS ACCIDENTS Issue #42, 3 24-53)
147	3-17-53	OR-C	The right wheels of a dump truck ran over an operating engineer when he stepped into its path as it was backing up. He died of multiple internal injuries
148	4-27-53	НА-С	An equipment operator was crushed against a concrete basin wall by the counterweight of a crane (See USAEC SERIOUS ACCIDENTS Issue #49, 6 30 53)
149	6-16-53	HA-C	A rigger died as the result of multiple internal injuries received in a fall from a flatbed truck
150	6-20-53	OR-C	A truckdriver was standing beside a truck crane when the crane swung around, struck him in the head, and threw him between the counterweight and the truck cab, crushing his head (compound fracture of the skull) (See USAEC SERIOUS ACCIDENTS Issue #49, 6 30 53)
151	9-15-53	OR-C	A pipelitter was crushed between the counterweight and frame of a crane truck (See USAEC SERIOUS ACCIDENTS Issue #56, 12-15-53)
152	9-19-53	на-с	While working on steel girders at the 90' level and attempting to move a scaffold plank, it swung upward, striking a steel construction foreman in the face, throwing him off balance and he fell. He died of multiple internal and skeleta injuries
153	10-15-53	SR-C	An ironworker fell 50' while engaged in removing an air duct. He died as a result of a fractured skull and brain injury
154	10-30-53	на-с	An operator received a compound skull fracture when the bulldozer he was driving overturned, pinning him under neath (See USAEC SERIOUS ACCIDENTS Issue #54, 12-2-53)
155	1-14-54	OR-C	An ironworker fell $21'$ from a steel girder while engaged in bolting procedures. He died of a fracture at the base of his skull
156	1-29-54	на-с	An electrician fell 9' from a scaffold. He died as a result of a fractured skull and brain injury. (See USAEC SERIOUS ACCIDENTS Issue #62, 3-23-54)
157	2-18-54	SF-C	An electronics technician was electrocuted while disconnecting an energized 110 volt power lead when his body came into contact with grounded equipment (See USAEC SLRIOUS ACCIDENTS Issue #66, 7-7-54)
158 159	3 -15- 54	NY-O	Two pilot plant operators died as a result of second and third degree burns received in a chemical explosion (Se USAFC SERIOUS ACCIDENTS Issue #63, 6-9-54)
160	3-17-54	NY-C	A crane backed over an oiler, crushing his entire body
161	5 554	OR-C	A laborer's chest and trunk were completely crushed between a dump truck tailgate and a Gradall while giving a truc driver signals
162	5-19-54	OR-C	A welder fell from the roof, through a ventilator shaft, 82' to the ground, receiving multiple internal and skeletinguries from which he died two days later
163	5-24-54	HA-C	A cement finisher fractured his skull in a 25' fall through an access hole to a concrete floor
164	6- 5-54	GJ-C	A laborer's chest and trunk were completely crushed between the boom of a crane and the forms into which he was helping to pour concrete
165	7-30-54	OR-O	A lineman was electrocuted while working on a street lighting circuit from the platform of a ladder truck
166	8- 9-54	OR-O	A plumber received fatal injuries (crushed chest and lacerations of left lung) when he fell 38' from a 24 pipe
167	8-11-54	SF-O	A supervisory employee broke his neck in a 25' fall from a built in iron ladder to the concrete floor in a power generating plant
168	8-18-54	OR-O	An electrician was electrocuted while handling a 115-volt extension cord
169 170	9 754	SR-O	Two maintenance mechanics, removing a blank flange from a rundown tank, released toxic gas and scalding liquing resulting in extensive second and third degree burns of their entire bodies, causing their deaths (See USALC SER OUS ACCIDENTS Issue #72, 10–19–54)
171	10-12-54	OR-O	A chemical operator fell 20' to a concrete floor. He died as a result of a fractured skull and brain injury. (See USAEC SERIOUS ACCIDENTS Issue #79, 3-21-55)
172	11-16-54	OR-C	While climbing a ladder, a pipefitter fell 17' to the concrete floor below, fracturing his skull and causing brain injury
173	4- 2-55	SF-C	An asbestos worker received a fractured skull when he was struck on the head by a piece of 4 iron pipe thrown fro the top of a water tower 30' above ground

No.	Date	Field Office ¹ & Facility ²	Remarks
174	5- 2-55	OR-C	An ironworker received a compound fractured skull and brain injury when he slipped from a ladder, falling 50' to the concrete floor.
175	6- 6-55	SF-G	An equipment operator was crushed to death when a pickup truck he was driving turned over, pinning him in the truck.
176	72955	SF-O	A hot-mix plant operator was electrocuted when he touched the load and the load line cable of the crane contacted an overhead powerline.
177	8-30-55	НА-О	An explosion occurred in an electric furnace, causing hot dry salt to be blown into the face of the operator, who died as a result of second and third degree burns. (See USAEC SERIOUS ACCIDENTS Issue #88, 10-14-55.)
178	9- 9-55	GJ-O	A utility man suffocated in a fine ore bin while trying to determine why the ore was not feeding into the conveyor belt when an undetermined area gave way, killing him by suffocation. (See USAEC SERIOUS ACCIDENTS Issue #98, 3-22-56).
179 180	10-16-55	OR-O	Two chemical operators suffocated in a tank during degreasing operations involving the use of Freon-113. (See USAEC SERIOUS ACCIDENTS Issue #91, 11-30-55).
181	11-22-55	NY-O	A cyclotron operator was electrocuted while investigating the cause of the trouble in a modulator circuit. (See USAEC SERIOUS ACCIDENTS Issue #96, 3-19-56).
182	11–25–55	НА-О	A coal handler suffocated when the coal slid, covering him, as he prodded it with a bar. (See USAEC SERIOUS ACCIDENTS Issue #98, 3-22-56).
183	4-11-56	OR-C	During the installation of girders, an ironworker was thrown off balance as a crane load dropped suddenly, causing him to fall 17' to the ground. He died as a result of a broken neck.
184 185	5-14-56	OR-O	Zirconium drums exploded, followed by fire, resulting in second and third degree burns to two salvage handlers, both of whom died as a result of their burns. (See USAEC ACCIDENT AND FIRE PREVENTION INFORMATION Issue #44, 6-20-56).
186	62656	AL-O	The accidental detonation of an experimental explosive caused fatal multiple blast injuries to a technician.
187	7- 2-56	NY-O	A chemical engineer died as a result of extensive second and third degree burns received in a fire following a thorium
188	7-24-56	AL-C	explosion. (See TID-5360, Suppl. 1, p. 16; USAEC SERIOUS ACCIDENTS Issue #107, 8-20-56). A labor relations director was killed when the car he was driving overturned on a curve. He died from a crushed chest and internal injuries.
189	8-26-56	СН-О	An ironworker was electrocuted when a truck crane struck and broke an overhead high-voltage line. (See USAEC SERIOUS ACCIDENTS Issue #112, 11-16-56).
190	9-19-56	AL-O	A pipefitter received internal crushing injuries when a truck backed over him while he was working on a hydrant. (See USAEC SERIOUS ACCIDENTS Issue #113, 12-7-56).
191	1–29–57	OR-C	A millwright was electrocuted while helping to move a cover plate assembly fixture into position when it came into contact with two power cables. (See TID-5360, Suppl. 2, p. 7; USAEC SERIOUS ACCIDENTS Issue #120, 5-17-57).
192	3-11-57	OR-C	A rigger was electrocuted when a boom on a crane contacted a 13,800-volt feeder line while he had hold of a pipe being lifted by the crane. (See TID-5360, Suppl. 2, p. 8).
193	6-22-57	AL-O	A surveyor was killed when his body was thrown 40' from a car which overturned several times after he lost control of it. He died from multiple skull and internal injuries. (See TID-5360, Suppl. 2, p. 8).
194	8- 1-57	GJG	A geologist died of multiple skull and internal injuries received in an airplane crash. (See TID-5360, Suppl. 2, p. 9).
195	12- 4-57	SR-O	An area engineer was thrown out of the car he was driving when it collided with a train, which he apparently did not see until it was too late. He died of multiple skull and internal injuries. (See TID-5360, Suppl. 2, p. 9).
196	1-13-58	WASH-G	A project officer was killed in a motor vehicle accident.
197	4- 7-58	SAN-O	A nuclear physicist was drowned when a helicopter crashed in the ocean. (See TID-5360, Suppl. 2, p. 10).
198	6-17-58	AL-C	A laborer died from a fractured skull and brain injury when two tons of rock fell on him. (See TID-5360, Suppl. 2 p. 10).
199	8-25-58	AL-C	A lineman was electrocuted while chipping rust on a switch. (See TID-5360, Suppl. 2, p. 11).
200	12-18-58	OR-C	A laborer was asphyxiated when trapped under 192 cubic feet of earth when a trench wall toppled. (See TID-5360, Suppl. 2, p. 11).
201	12-30-58	AL-O	A chemical operator died as the result of radiation received during a criticality accident. His whole-body exposure was 12,000 rem ±50%. (See TID-5360, Suppl. 2, p. 30; USAEC SERIOUS ACCIDENTS Issue #143, 1-22-59).
202 203	2-24-59	AL-O	A machine operator and a toolmaker were blown to fragments when the explosives they were machining detonated. (See TID-5360, Suppl. 3, p. 26).

See footnotes at end of table.

No.	Date	Field Office 1 & Facility 2	Remarks
204	4-10-59	на-с	While attempting to move himself along a 4" pipe which he was straddling, a boilermaker rigger lost his balance and fell 50'. He died from a skull fracture and brain injury (See TID-5360, Suppl. 3, p. 27, USAEC SERIOUS ACCIDENTS Issue #146, 7-15-59).
205	5-13-59	ID-C	When the overhead tielines of the scaffold upon which a sheetmetal man was working were removed, the scaffold crashed to the concrete floor, causing him to fall 60' He died from multiple internal and skeletal injuries. (See TID-5360, Suppl. 3, p. 27, USAEC SERIOUS ACCIDENTS Issue #146, 7-15-59).
206	8- 7-59	OR-C	An electrician was electrocuted while attempting to start an arc welder at a time when the ground was wet and charged with electricity. (See TID-5360, Suppl. 3, p. 28, USAEC SERIOUS ACCIDENTS Issue #149, 10-9-59).
207 208 209	10-14-59	AL-O	Four laborers were killed while unloading explosives scraps at a burning ground when the explosives inadverten exploded. They died from multiple blast injuries. (See TID-5360, Suppl. 3, p. 29).
210 211	12- 2-59	AL-O	A medical administrator was killed in an automobile collision when an oncoming car tried to pass another vehicle and hit his car head on. He died from multiple internal injuries. (See TID-5360, Suppl. 3, p. 29).
212	12-18-59	СН-О	A reactor assembly inspector was asphyxiated while taking measurements, without proper respiratory equipment on the bottom of an argon-filled pit. (See TID-5360, Suppl. 3, p. 30, USAEC SERIOUS ACCIDENTS Issue #159, 1-13-60).
213	12-23-59	AL-C	A broken pendant line on a crane caused a one-cubic-yard bucket of concrete to fall on a laborer, crushing him. (See TID-5360, Suppl. 3, p. 31)
214	1-29-60	AL-O	A skindiver, engaged in placing dynamite charges under water, drowned. (See TID-5360, Suppl. 3, p. 31).
215	3-18-60	AL-C	A kitchen helper slipped while carrying a 20-gal. container of hot soup, and died of uremia, a direct complication of the burns he received. (See TID-5360, Suppl. 3, p. 32).
216	4-13-60	NY-C	A carpenter, while standing on a 36" wall, lost his balance and fell 20' to a concrete floor. The cause of death was a fractured cervical vertebrae and a crushed chest. (See TID-5360, Suppl. 3, p. 32).
217	8-31-60	ID-C	A painter, engaged in painting railings, ladders and cages on a silo, fell 70' to the ground. He died from a skull fracture (See TID-5360, Suppl. 3, p. 33).
218 219 220	1- 3-61	ID-O	All three members (military) of an operating crew were killed when a reactor excursion occurred. The three men died of multiple blast skeletal and internal injuries (See TID-5360, Suppl. 4, p. 1962 NUCLEAR SAFETY, Vol. 3 #3, p. 64).
221	1-24-61	AL-O	While working atop a bunker, a physics laboratory technician lost his balance and fell backward over the edge of the bunker 10' to a concrete pad. He died of severe brain damage and brain hemorrhage resulting from the fall. (See TID-5360, Suppl. 4, p 27, USAEC SERIOUS ACCIDENTS Issue #173 2-24-61).
222	2- 2-61	AL-O	A technician died of multiple internal injuries received in a head-on collision when the car he was driving veered (cause unknown) to the wrong side of the road. (See TID-5360, Suppl. 4, p. 28).
223	2-14-61	AL-O	A fabrication technician was asphyxiated by solvent vapors (methyl chloroform) while working alone inside of a vacuum annealing furnace shell. (See TID-5360, Suppl. 4, p. 28, USAEC SERIOUS ACCIDENTS Issue #174, 2-28-61).
224 225	3–10–61	OR-C	While two tower erectors were helping to erect the top beam section of an instrument tower, the top 70' of the tower broke off, catapulting both employees 145' to the ground. One employee died from a broken neck the day of the accident, the other employee died almost a year later from complications of internal injuries received from the fall. (See TID-5360, Suppl. 4, p. 29).
226	3-16-61	PNR-C	While engaged in painting a ceiling, the scaffold, upon which a painter was standing, collapsed, and he fell 15' to the floor below, fracturing his skull and causing brain hemorrhage. (See TID-5360, Suppl 4, p. 29).
227	8-14-61	HA-O	A heavy equipment operator was killed when a tractor, out of control, rolled backwards over him, crushing his body. (See TID-5360, Suppl. 4, p. 29).
228	9- 7-61	AL-O	A group leader was thrown out of a car he was driving when it overturned. He died of a fractured skull and brain injury. (See TID-5360, Suppl. 4, p. 30).
229	1-22-62	SR-C	A carpenter, atop a 2600-lb. concrete form, was crushed to death between the form and the steel mat when the form fell away from its reinforcing steel, carrying him with it (See TID-5360, Suppl 4, p. 31, USAEC SERIOUS ACCIDENTS Issue #182, 5-24-62).
230	3-18-62	OR-O	An explosion in a metal reduction furnace sprayed hot liquid on two operators, one of whom died 12 days later of extensive second and third degree burns on 70% of his body. The other operator, although severely burned, survived. (See TID-5360, Suppl. 4, p. 31).

No.	Date	Field Office ¹ & Facility ²	Remarks
231	3-23-62	OR-C	A pipeman's chest cage was crushed when a large, solid section of a trench caved in upon him. (See TID-5360, Suppl. 4, p. 32; USAEC SERIOUS ACCIDENTS Issue #183, 6-1-62).
232	3-29-62	CH-C	A pipefitter fractured his skull in a 21' fall while walking on an 18" pipe. (See TID-5360, Suppl. 4, p. 32).
233	6-20-62	OR-O	While two coal handlers were using rods to break a bridge formation in a coal pile, the pile suddenly gave way, the men were covered with coal; one escaped, the other died of suffocation. (See TID-5360, Suppl. 4, p. 32).
234	8-15-62	OR-O	An electrical maintenance supervisor died nine days after receiving second degree burns when an explosion occurred during routine maintenance of a circuit breaker tank. (See TID-5360, Suppl. 4, p. 33; USAEC SERIOUS ACCI DENTS Issue #189 11-19-62).
235	10- 7-62	NV-O	A fireman was thrown out of a power wagon when it overturned. He died of a fractured skull and a brain injury (See TID-5360, Suppl. 4, p. 33).
236	1- 5-63	СН-О	A shift supervisor died of internal injuries and a basal skull fracture resulting from a 54-foot fall when he stepped backward into an open shield plug hole while giving signals to a crane operator. (See TID-5360, Suppl. 5, p. 39; USAEC SERIOUS ACCIDENTS Issue #204, 5-13-63).
237	2-16-63	NV-C	During excavation work, a construction worker was crushed by a Caterpillar when the entire length of the Cater pillar tread ran over his body, causing multiple internal injuries. (See TID-5360, Suppl. 5, p. 40).
238	4-30-63	OR-O	While testing an ion source on a developmental power supply, a physicist was electrocuted. (See TID-5360, Suppl. 5 p. 40).
239	6-25-63	SNR-C	A carpenter fell 65' from a cooling tower. The cause of death was a compound fractured skull, broken neck and multiple internal injuries with massive hemorrhage. (See TID-5360, Suppl. 5, p. 40).
240	6-25-63	NY-O	While an operator's helper was kneeling on the top of a box, being moved by a forklift truck, to counterbalance th overhanging weight, the box tipped forward and he fell to the ground, He was reported to have died of a pulmonar; embolism 17 days after the accident. (See TID-5360, Suppl. 5, p. 41; USAEC ACCIDENTS Issue #213, 11-8-63)
241	7-23-63	OR-C	An apprentice pipefitter was asphyxiated while checking for an inert gas leak in a valve pit. (See TID-5360, Suppl. p. 42; USAEC SERIOUS ACCIDENTS Issue #223, 4-3-64).
242	8 163	OR-C	While an ironworker was climbing down a rolling-type scaffold, the scaffold began to swing and fold, finally topplin to the floor. He held on until the scaffold was about halfway down, then fell the remaining distance to the concret floor, dying five days later as a result of multiple skull fractures. (See TID-5360, Suppl. 5, p. 42; USAEC SERIOU ACCIDENTS Issue #218, 2-14-64).
243	7-10-63	NV-C	A custodial employee suffered a fatal pulmonary embolism as the result of injuries (femoral vein thrombosis) receive in an automobile accident three months earlier. (See TID-5360, Suppl. 5, p. 41).
244	9-26-63	AL-O	When a truck backed over a can of paint thinner, the can ruptured, spraying the contents on a laborer's clothing Flames from a dump fire ignited his coveralls, and he died about six weeks later as a result of the chemical bur received. (See TID-5360, Suppl. 5, p. 42).
245	3-11-64	SAN-O	An electronics coordinator died as the result of a skull fracture received when the car in which he was driving over turned when he failed to manipulate a curve. (See TID-5360, Suppl. 5, p. 43; USAEC SERIOUS ACCIDENT Issue #234, 10-23-64).
246	4-21-64	NV-C	A teamster was crushed to death beneath an 8,000-gallon water tanker which he was driving when it got out of cortrol. (See TID-5360, Suppl. 5, p. 44).
247	7- 1-64	AL-C	A roofer died three days after a fall 22' from a flat roof from injuries sustained in the fall. (See TID-5360, Suppl. p. 44).
248	91964	NV-C	Electrical cables were being lowered into an underground complex when a drill rig cable broke causing the cab spools to be jerked from their racks. Four men were hit by the spools, one receiving extensive head and chest injuri from which he died. The other three received multiple contusions and abrasions. (See TID-5360, Suppl. 5, p. 44
249	9-23-64	SAN-C	A drill rig crew member was electrocuted when a rig boom contacted overhead electric powerlines. (See TID-5360 Suppl. 5, p. 45; USAEC SERIOUS ACCIDENTS Issue #238, 12-15-64).
250	12-15-64	NV-C	When a drill rig assembly failed, allowing the swivel assembly pipe to fall, the rig operator was killed instantly fro a crushing blow on the head. (See TID-5360, Suppl. 5, p. 46).
251	12- 8-64	RL-O	A track maintenance man died two weeks after an accident in which the maintenance car in which he was riding he a head-on collision with a locomotive. He died from a fractured skull and brain injury. (See TID-5360, Supp. 5, p. 45).
252	1-28-65	NV-C	A rotary drill helper was killed instantly when a "finger" (a 4' length of 4" pipe weighing 87 lbs.) fell 85' from the fingerboard of the mast of a drill rig, striking him on the head, neck, and shoulders. The cause of death was depressed occipital skull fracture with a 4" laceration of the scalp. (See TID-5360, Suppl. 6, p. 49).

See footnotes at end of table.

No.	Date	Field Office ¹ & Facility ²	Remarks
253	2-23-65	NV-C	A wireman foreman was electrocuted while working in a switchgear cabinet. (See TID-5360, Suppl. 6, p. 41).
254	6-14-65	OR-O	A lineman was fatally injured when he fell 18' from an electric pole to the sidewalk, Investigation revealed that his body belt was unbuckled. The cause of death was a fractured skull. (See TID-5360, Suppl. 6, p. 41; USAEC SERIOUS ACCIDENTS Issue #252, 8-27-65).
255	6-21-65	NV-C	An employee suffered fatal injuries when he fell 24' from a derrick platform to a concrete pad. The cause of death was severe depressed skull fracture, frontal region; multiple fractures both arms; possible internal injuries. (See TID – 5360, Suppl. 6, p. 41).
256	7- 5-65	NY-O	An explosion and fire occurred in the experimental hall of an accelerator complex. Eight persons were injured, one of whom died fifteen days later as the result of third-degree burns over 60% of the body and of a ruptured liver. (See TID 5360, Suppl. 6, p. 42; TID-22594).
257	12-23-65	SAN-C	A six-ton concrete plank fell, seriously injuring one employee and crushing another to death. (See TID-5360, Suppl. 6, p. 43).
258	1–11–66	NV-C	A miner died thirteen days after being struck on the top of the head by a falling rock. His death was caused by respiratory failure due to transverse myelitis of the cervical cord caused by the injury. (See TID-5360, Suppl. 6, p. 44.)
259	1-12-66	SNPO-N-C	An employee died of third-degree burns over 100% of the body surface as the result of inadvertent ignition of gasoline and acetate recording tapes in preparation for disposal in a burn pit. (See TID-5360, Suppl. 6, p. 44; USAEC SERIOUS ACCIDENTS Issue #263, 5-27-66).
260	5- 1-66	AL-O	An employee died from crushing injuries to chest and head in a head-on motor vehicle collision while driving a Government-owned car. (See TID-5360, Suppl. 6, p. 45).
261	5-26-66	AL-C	While painters were engaged in spray painting the outside and top surfaces of a water storage tank, one painter stepped backward into an opening on the tank top, and fell 35' to the bottom of the tank. The cause of death was a fractured skull. (See TID-5360, Suppl. 6, p. 45).
262	6-10-66	NV-C	An employee died on July 16 of a pulmonary embolism suffered as a complication of injuries (compound fracture of the right ankle, fracture of the right shoulde, scalp lacerations) received on June 10, when a bucket fell on him during the filling of sand bags. (See TID-5360, Suppl. 6, p. 46).
26 3	6-17-66	NY-G	Two employees were involved in a single-car accident; one died eight days later as the result of brain and chest injuries; the other received only minor injuries. (See TID-5360, Suppl. 6, p. 47).
264	6-24-66	SAN-C	An employee was killed when the dirt loader he was operating overturned and crushed him. (See TID-5360, Suppl. 6, p. 47).
265	9-22-66	AL-C	A crane moving a steel stanchion contacted an 11,000-volt powerline. The employee guiding the stanchion into place died a few hours later as the result of the electric shock he received. (See TID-5360, Suppl. 6, p. 48).
266	10-12-66	AL-C	An electrician was electrocuted while working alone on a transformer. (See TID-5360, Suppl. 6, p. 49).
267	3-11-67	SR-O	During normal railroad car switching movements, an employee fell under a moving train and was decapitated. Since there were no witnesses, the cause was not determined.
268	4- 5-67	AL-O	When his foot slipped while servicing a tractor, an employee fell 7' to the ground. Surgery was performed the following day to pin the fracture of neck of left femur that resulted from the fall. He appeared to be recovering satisfactorily when he died unexpectedly five days after the accident of a pulmonary embolism secondary to the injury sustained.
269	4-10-67	AL-O	A painter fell 14' from a roof to the ground when, apparently, he slipped on a freshly painted area. He died six days later of a fat embolism secondary to fractures of the pelvis and arm.
270	4-14-67	RL-C	A clamshell bucket assembly toppled over, striking an employee on the neck and shoulder and driving him to the ground, the arm of the assembly coming to rest on his chest. He died immediately. Post mortem examination revealed the cause of death as ruptured acrta at acrtic arch. (See USAEC SERIOUS ACCIDENTS Issue #282, 7-28-67).
271	5-25-67	SNPO-C-O	A laboratory technician was found dead inside a core leaching furnace. Evidence indicates the employee climbed down into the furnace to retrieve a brush. Death was due to resultant asphyxiation from fumes.
272	6- 9-67	SAN-O	A fireman was helping to unload a firefighting vehicle from a trailer. It is not known what happened; however, evidence indicated that he jumped from the trailer truck, crashing into the windshield of a passing police car. The fatal injuries were a fracture of the base of the skull and a broken neck.
273 274	6-30-67	NV-C	Two miners were working at the bottom of a 3,200-foot hole when, without warning, a strong surge of muck and water flowed into their working area. One miner drowned immediately; the other was found alive, buried up to his neck in the muck and water, but drowned before he could be extricated.

No	Date	Field Office ¹ & Facility ²	Remarks
275	7 8-67	NV-C	An employee was steadying a row of 21 stored doors while another employee removed two of them. The doors suddenly shifted and fell over on the first man, crushing his head against shelving behind him. He was pronounce dead at the scene. The cause of death was multiple skull fractures with severe intracerebral hemorrhages causing central respiratory paralysis.
276	7-17-67	ID-C	A carpenter fell more than 13' when he attempted to climb down on the forms inside a containment vessel under construction. He was found conscious, although paralyzed completely from the neck down. He suffered severe needback, and leg injuries, in addition to shock, and he died the next day
277	8-17-68	OR-C	A road grader operator was crushed to death when a road roller overturned and rolled over him
278	8-19-68	RL-C	A driller's helper was buried in a cave-in which occurred during a hole-digging operation
279	11-14-68	NV-C	An aftercooler on an air compressor ruptured violently, resulting in the death of a mechanic who was struck lifting debris
280	3-13-69	NV-C	An electrician was electrocuted while working on a 4160 volt line
2 81	6-10-69	NV-C	One of four cables supporting a platform became detached, allowing two workers on the platform to fall. One of the workers was seriously injured and died two days later
282	6-16-69	CH-C	A carpenter was fatally injured when he fell through a floor opening at the site of a proposed stairwell from which temporary covering had been removed
283	10-23-69	NV-C	An employee was killed while standing at the bottom of an elevator shaft when a section of pipe fell down the sha and struck him
284	12-10-69	NV-C	An employee was electrocuted when the boom of a crane struck overhead wires
285	1-23-70	NV-C	A miner was fatally injured when he attempted to leave an elevator cage while it was descending. He was struck the cage before it could be stopped
286	2- 2-70	NV-C	An employee was killed when a pipe rolled off a truck, crushing him
287 288	3-10-70	AL-G -G	Two government employees were killed in the crash of a private airplane which they were using for official business
289	3-28-70	NV-C	While responding to a call, an ambulance aidman was killed when he fell from the side door of the vehicle, whi was traveling over 60 m p h
290	4- 8-70	CH-C	An employee was fatally injured due to a fall through an opening between floor joists
291	6-11-70	NV-C	An engineer drowned while scuba diving alone
292	7 - 2-70	NV-C	An employee was killed when the pickup truck he was driving left the road at a high rate of speed, rolled over, as threw him from the vehicle
293 294 295	11-25-70	WASH/-NV G -G -C	An AEC Commissioner and his aide, as well as a contractor employee, were killed in a small aircraft as it crashe into Lake Mead and disintegrated
2 96	2- 471	SNPO-N-C	A mechanic pipelitter was fatally injured when the pick up he was driving left the road went out control rolled over and threw him from the vehicle
297	2 13 71	AL-O	An electrician was accidently electrocuted while working on a high voltage transmission line.
298	6-13 71	AL-O	Employee was killed when Air Force C 135 transport crashed
299	10-21-71	NV-O	A service engineer was fatally injured while disconnecting the fifth wheel on a cement bin trailer who the trailer shifted slightly due to uneven ground
300	12- 5-71	RL-O	A lieutenant in a security patrol was accidentally electrocuted when he contacted a downed power lin He had been summoned to investigate flashing lights' reported during the night on a nearby hi (See USAEC SERIOUS ACCIDENTS Issue No 326, May 15 1972)
301	3- 3-72	SNR-O	Employee was fatally injured while returning from company business when the commercial aircraft was riding in crashed near Albany N Y
302	5 2-72	SR-O	Employee was fatally injured when he suddenly stepped between a cut of moving railroad cars and rubber tired end loader which was being used to pull the cars
303 304 305 306 307 308 309	5-19-72	AL-O	Eight employees and the pilot were fatally injured when the aircraft they were using crashed aburned on take off

No.	Date	Field Office 1 & Facility 2	Remarks		
312			A miner was fatally injured while raising an I beam wh sheave attached fell and struck the employee	en the slab of 10ck to which the spad eye and	
313	1 4-73	CH O	A staff engineer was electrocuted during energized trouble shooting operations on high-voltage in power radio frequency amplifier equipment in the ZGS Ring Building		
314	1 10 73	СН-С	A heavy equipment operator was fatally injured while would forward into the trench and pinned him against an		
315	1 11 73	SR O	A mechanic was fatally injured while helping to roll a wor platform toppled and struck him on the head	king platform across railroad tracks when the	
316	2-12-73	SR O	A mechanic died from complications resulting from a fall or	n ice	
317	9 24 73	СН-О	A groundsman was found by his supervisor pinned beneath the right rear wheel of the tractor he had been driving. He died while in the hospital later the same day of the injuries he had sustained		
318	11 21-73	NV C	A heavy duty repairman was fatally injured when one joint of 66' diameter casing rolled and struck him in the head		
319	7-15 74	AL-O	An electrical engineer was electrocuted while working on the control circuit of a betatron while it we energized		
320	7 18 74 RL-O A materials control clerk died of complications he received in a fall through a hole in the floor activated area of the building. The cover for the hole had not been properly replaced and appropriate the following the employee to fall into the basement.		-		
321	9 24 74	AL-O	A dump truck driver died of injuries he sustained when he the overturned dump bed. He was also severely burned v spilled upon him		
¹ Field Offices ALA—Alabama Ordnance Works AL—Albuquerque Operations Office BH—Brookhaven Office CH—Chicago Operations Office CL—Clinton Engineer Works		e Operations Offic Office erations Office	IO—Iowa Area NV—Nevada Operations Office NY—New York Operations Office OR—Oak Ridge Operations Office PNR—Pittsburgh Naval Reactors Office RL—Richland Operations Office (Formerly	Cleveland SNPO-N-Space Nuclear Propulsion Nevada SNR—Schenectady Naval Reactors Office SR—Savannah River Operations Office	

CL-Clinton Engineer Works

DE—Decatur Area

GJ—Grand Junction Office

HA—Hanford Operations Office

ID-Idaho Operations Office

RL-Richland Operations Office (Formerly HA)

SAN—San Francisco Operations Office

SF—Santa Fe Operations Office

SNPO-C-Space Nuclear Propulsion Office-

WASH—Washington Headquarters

WR-Wabash River Ordnance Works

² Facilities C—Construction G—Government O—Operation

APPENDIX B

RADIATION EXPOSURES OVER 15 REM

(Whole-Body)

Atomic Energy Commission 1947-1975

FATAL RADIATION EXPOSURE ACCOMPANIES CRITICALITY ACCIDENT

Los Alamos, N. Mex., Dec. 30, 1958–12,000 (±50%), 134, and 53 rem

After placing emulsion in a tank, the operator was believed to have added a dilute plutonium solution from a second tank. Solids containing plutonium were probably washed from the bottom of the second tank with nitric acid and the resultant mixture of nitric acid and plutonium-bearing solids added to the tank containing the emulsion. Shortly after starting the stirrer motor to initiate an expected mild nonnuclear reaction between the emulsion and the acid, the operator observed a "blue flash", also observed by an employee in an adjoining room.

The employee died 35 hours later from the effects of a radiation exposure tentatively estimated at 12,000 rem ($\pm 50\%$).

Two other employees received radiation exposures of 134 rem and 53 rem, respectively. Property damage was reported as negligible. (See TID-5360, Suppl. 2, p. 30; USAEC Serious Accidents Issue #143, 1-22-59.)

RADIATION EXPOSURES ACCOMPANY CRITICALITY ACCIDENT

Oak Ridge, Tenn., June 16, 1958–461, 428, 413, 341, 298, 86, 86, and 29 rem

A nuclear accident occurred in a 55-gallon stainless steel drum in a processing area in which enriched uranium is recovered from various materials by chemical methods in a complex of equipment. This recovery process was being remodeled at the time of the accident.

The incident occurred while they were draining material thought to be water from safe 5-inch storage pipes into an unsafe drum.

Eight employees were in the vicinity of the drum carrying out routine plant operations and maintenance. A chemical operator was participating in the leak testing which inadvertently set off the reaction. He was within three to six feet of the drum, while the other seven employees were from 15 to 50 feet away.

Using special post hoc methods for determining the neutron and gamma exposures of the employees involved, it was estimated that the

eight men received: 461 rem, 428 rem, 413 rem, 341 rem, 298 rem, 86 rem, 86 rem, and 29 rem.

Area contamination was slight, with decontamination costs amounting to less than \$1,000.

During this incident 1.3×10^{18} fissions occurred (See TID-5360, Suppl. 2, p. 25; USAEC Serious Accidents Issue #136, 8-25-59; USAEC Health and Safety Information Issue #82, 9-5-58; 1959 Nuclear Safety, Vol. 1, #2, p. 59.)

SERIOUS COBALT-60 EXPOSURE

Oak Ridge, Tenn., February 4, 1971—260 rem

A research technician was exposed to 8,000 curies of cobalt-60 gamma radiation while he was preparing to irradiate seed samples in a variable-dose-rate facility. A thermoluminescence dosimeter worn on the technician's belt indicated a total body exposure of 260 rem. The employee's medical symptoms, primarily nausea and vomiting on the first day as well as leukocyte depression, are typical of this level of exposure. (See USAEC Serious Accidents Issue No. 315, 4–9–71.)

SUDDEN INCREASE IN REACTIVITY DURING CONTROL ROD TESTS

Lemont, Ill., June 2, 1952-190, 160, and 70 rem

Manual withdrawal of a control rod from a critical assembly caused an accidental super-criticality.

The operation being conducted was the comparison of a series of newly-manufactured control rods. The assembly had been operated with the standard control rod. It was then shut down by inserting all control rods and draining the water moderator, a standard safe method of shutting down the assembly when core changes are to be made. The standard rod was removed and the first of a series of control rods to be tested was inserted.

The reactor was filled with water with the test control rod fully in and the standard type control rods fully inserted. Withdrawal of one of the standard control rods 32 centimeters caused the assembly to become critical and the power was leveled off while the desired measurements were made. The control rod was then reinserted into the original "in" position.

With the water still in the assembly, the four members of the crew then went into the assembly room for the purpose of replacing the control rod which they had just tested. The group leader went up on the platform, reached out with his right hand and started to pull out the tested rod. As soon as he had withdrawn it about one foot, the center of the assembly emitted a bluish glow and a large bubble formed. Simultaneously, there was a muffled explosive noise. The group leader let go of the control rod which he was removing and it fell back into position. The crew left the assembly room immediately and went to the control room.

Four employees received radiation exposures ranging from 12 to 190 rem. (See TID-5360, p. 23.)

SUSPECT RADIATION EXPOSURE

Stanford, Calif., May-June 1966-150 rem

An employee's badge indicated a radiation exposure had occurred over a period of several weeks while he was engaged in his routine duties at a linear accelerator.

Investigation indicated that the film badge did receive an estimated radiation exposure of 150 rem; however, there was no evidence that the employee had actually received the exposure.

RADIATION EXPOSURES ACCOMPANY NUCLEAR EXCURSION

Richland, Wash., Apr. 7, 1962-110, 43 and 19 rem

An unplanned nuclear excursion occurred in a plutonium processing facility due to the inadvertent accumulation of approximately 1500 grams of plutonium in 45–50 liters of dilute nitric acid solution in a 69-liter glass transfer tank. The sequence of events which led to the accumulation of the plutonium in the tank cannot be stated positively. However, it is believed that, when a tank valve was opened, the solution from another vessel overflowed to a sump and was drawn into the transfer tank through a temporary line between this tank and the sump.

When the excursion occurred, radiation and evacuation alarms sounded. All but three employees left the building immediately, according

to well-prepared and -rehearsed evacuation plans. Fortunately, they were not in close proximity to the involved system nor in a high radiation field.

Of the 22 persons in the building at the time, only four employees, those who were in the room with the system, were hospitalized for observation. Three of them were the system operators, who were in close proximity to the excursion, and who received estimated radiation doses of 110, 43 and 19 rem. None of them showed symptoms definitely referable to their radiation exposures. The fourth was sent to the hospital only because he was in the room at the time of the incident.

Some fission product activity, airborne via the vent system and the exhaust stack, was detected in the atmosphere for a brief period after the accident.

The physical damage amounted to less than \$1,000. (See TID-5360, Suppl. 4, p. 17.)

IRRADIATED FUEL INCIDENT

Puerto Rico, July 24, 1962—100, 58, 24, 18 and 18 rem

Seven employees were accidentally exposed to radiation from irradiated fuel elements when a crane operator mistakenly thought he had been given the all-clear signal to move a rack of hot fuel elements into a position against the aluminum window which separates the exposure room from the reactor pool. The room was to be vacated and the shield door closed before positioning the fuel elements against the window. The gamma room door could not be seen from the crane operator's position.

When the crane operator began moving the fuel elements into the window position, the 10-millirem monitor near the gamma room door tripped an alarm. The reactor supervisor immediately ordered the fuel elements moved away from the window, terminating the incident.

The estimated exposure time of the individuals was 1½ seconds. The seven employees' exposures were 100 rem, 58 rem, 24 rem, 18 rem, 18 rem, 8 rem, and 4 rem. There were no radiation injuries as a result of the accident. (See TID-5360, Suppl. 4, p. 21.)

ACCIDENTAL EXPOSURE

Oak Ridge, Tenn., Oct. 4, 1957-63 rem

An employee received an exposure to radiation for less than one minute when he mistakenly entered a room containing tanks of radioactive residues used in processing irradiated fuel elements.

The exposure was first discovered when a pocket dosimeter was examined at the end of the day's shift and was confirmed when the employee's film badge was processed. He apparently suffered no ill effects and continued working; however, he was transferred to other duties. (See TID-5360, Suppl. 2, p. 23.)

SUSPECT RADIATION EXPOSURE

Minneapolis, Minn., June 6-19, 1966-50 rem

An employee's film badge indicated a radiation exposure had occurred over a period of approximately 14 days while he was engaged in his routine duties at a linear accelerator.

Although neither proved nor disproved, since the employee's film badge showed an estimated external whole-body cumulative radiation exposure of 50 rem, it was charged to his record.

ELECTRON ACCELERATOR EXPOSURE

Livermore, Calif., Jan. 6, 1959-41 rem

A physicist was exposed while a series of adjustments were being made on beam-defining plates in a new electron linear accelerator. Radiation surveys were made with negative results when personnel entered the cells after the first three adjustment runs. No survey was made after the fourth and fifth runs. A survey made after the sixth run showed a 1,000 rem/hr level.

During all entries to the cell, the key which was designed to lock all controls in the "OFF" position was removed from the control panel. It was determined that the film badges had been exposed to about 200 Kev energy gamma radiation. An exposure dose of 41 rem was assigned to physicist "A". This dose was received in a period of about one minute, which was the established time he worked alone on plates 3 and 4 and entered the cell to measure very high radiation levels. The next highest reading of 400

millirem was received by physicist "B". All others received less than 50 millirem. (See TID-5360, Suppl. 3, p. 8.)

INADVERTENT EXPOSURE

Mercury, Nev., Mar. 1, 1955-39 rem

A security guard was to accompany the radiation safety monitors into the exclusion area after a weapons test and establish surveillance of equipment. The guard had his own vehicle.

When he arrived at the place where he was to meet the monitors, the guard found that they had already left and started out after them. Somehow, he lost his way and drove beyond the established safety point. When it became apparent that he could not find the radiation safety monitors, he contacted his headquarters by radio and notified them of his position. He was immediately ordered out of the area.

The guard's film badge indicated he had received a dose of 39 rem. (See TID-5360, p. 72.)

RADIATION EXPOSURE

Las Vegas, Nev., Jan. 18, 1956—28 and 19 rem

When the prescribed time after a shot had elapsed, four employees, dressed in the proper protective clothing, were recovering samples from a nuclear test area.

It had been prearranged to have a monitor enter the area in advance of the men; however, they entered the area to redeem the samples without the monitor.

The four men received external radiation exposures of 28, 19, 14 and 4 rem, respectively. Upon medical examination, the men showed no signs of ill effects. (*See TID-5360*, Suppl. 1, p. 4.)

CONTAMINATED EQUIPMENT CAUSES EXPOSURE

Mercury, Nev., 1954-27.8 rem

An employee unknowingly worked and slept in close proximity to highly contaminated equipment while it was in transport between testing sites. He received a 24 rem whole-body exposure in 24 hours; his total yearly exposure was 27.8 rem.

SL-I EXCURSION

Idaho Falls, Idaho, Jan. 3, 1961–27, 27, 25, 23, 21, 18, 16 and 15 rem

A nuclear excursion occurred within the reactor vessel, resulting in extensive damage of the reactor core and room, and in high radiation levels (approximately 500–1000 rem/hr) within the reactor room.

At the time of the accident, a three-man crew was on the top of the reactor assembling the control rod drive mechanisms and housing. The nuclear excursion, which resulted in an explosion, was caused by manual withdrawal, by one or more of the maintenance crew, of the central control rod blade from the core considerably beyond the limit specified in the maintenance procedure.

Two members of the crew were killed instantly by the force of the explosion and the third man died within two hours following the incident as a result of an injury to the head. Of the several hundred people engaged in recovery operations, 22 persons received radiation exposures in the range of three to 27 rem gamma radiation total-body exposure. The maximum whole-body beta radiation was 120 rem.

Some gaseous fission products, including radioactive iodine, escaped to the atmosphere outside the building and were carried downwind in a narrow plume. Particulate fission material was largely confined to the reactor building, with slight radioactivity in the immediate vicinity of the building.

The total property loss was \$4,350,000. (See TID-5360, Suppl. 4, p. 8; 1962 Nuclear Safety, Vol. 3, #3, p. 64.)

EXPOSURE TO EMPLOYEE'S DOSIMETER

Aiken, S. C., July 1971-23.6 rem

The routine reading of health physics thermoluminescence dosimeter (TLD) badges for the month of July revealed an employee's badge had received 23.6 rem exposure. A detailed investigation which included evaluation of employee's self-reader dosimeter, his criticality neutron dosimeter, his work assignments for July, and his TLD badge, and exposure records of other employees doing similar work, indicated the employee did not receive radiation in

excess of 100 millirem. However, since this could not be proved absolutely, the 23.6 rem exposure was charged to the employee's record.

EXPOSURE DURING REACTOR SHUTDOWN

Idaho Falls, Idaho, July 23, 1956-21.5 rem

During a shutdown operation for scheduled refueling, six employees were working on the reactor top adjacent to the reactor tank opening, while two men were present as observers and advisors. All were exposed to radiation when a highly radioactive reactor component was placed in a position where it was not adequately shielded because of lowered water level in the reactor tank. The moving of the component and the coincident lowering of the water level were done to facilitate insertion and removal of experiments in the reactor.

The eight employees received radiation exposures ranging from 2.5 rem to 21.5 rem. (See T1D-5360, Suppl. 1, p. 18.)

COBALT 60 EXPOSURE

Mercury, Nev., Oct. 4, 1960-18 rem

Two employees were following through the routine involved in the calibration of photocell detectors. The detectors were placed in the radiation beam area, 30" in front of the 340-curie cobalt 60 source unit. Currents were being recorded for each detector with the source exposed. Three detectors had previously been calibrated; the fourth was placed in position; both employees returned to the console; the source was exposed and the current output of the detector was recorded. After recording the current value, employee "A" noted that the warning lights were out and assumed that the source was no longer exposed. He approached the detector located in front of the source, without making a precautionary radiation survey, and started making mechanical adjustments on the photodiode. Employee "B" followed "A" and aided him in the adjustments.

"A" received a total-body dose of 18 rem as determined by film badge reading. "B" received a total whole-body dose of 5 rem. (See TID-5360, Suppl. 3, p. 23.)

EXPOSURES RESULT FROM HANDLING FISSION SAMPLES

Eniwetok, May 14, 1948-17 rem

Four employees, who were handling fission samples improperly, received whole-body exposures ranging from 1.7 rem to 17 rem.

EXPOSURE DUE TO TRITIUM UPTAKE

Miamisburg, Ohio, March 13, 1973-16.4 rem

A pipefitter doing a routine valve replacement job on a dryer in a tritium effluent recovery system received an uptake of tritium which resulted in an integrated whole body exposure of 16.4 rem. The uptake was the result of loss of hand protection during the maintenance work, which allowed tritiated water to come in direct contact with the skin through a hole(s) in the latex surgeon's gloves he was wearing.

GAMMA EXPOSURE

Mercury, Nev., 1954-15.1 rem

While handling 55-gallon drums, whose greasy surfaces had trapped considerable

amounts of radioactive fallout, an employee received 13 rem whole-body exposure during one working day. His total yearly exposure was 15.14 rem.

RADIOGRAPHY INCIDENT

Richland, Wash., May 16, 1963-15.2 rem

Construction employees, who wore no dosimeters, were inadvertently exposed to a lost 27-curie iridium 192 radiography source during the construction of a new production reactor. Exposures were estimated based upon radiation surveys and interviews with the personnel involved. The exposures ranged from 3.9 rem to 15.2 rem.

X-RAY TECHNICIAN EXPOSURE

Middletown, Conn., October 1958–15 rem ($\pm40\%$)

An employee was in a shielded X-ray room using a portable X-ray unit. The circumstances indicated that the employee was not exposed to the radiation shown by his film badge. However, investigation could not prove this; therefore, it was assumed that the employee was exposed.

APPENDIX C

REPORTABLE* ACCIDENTS, INCIDENTS, AND RADIATION EXPOSURES

USAEC FACILITIES 1959-1975

^{*}Requirements for a "reportable" incident have varied slightly since 1959. See Appendix D for current requirements as set forth in AEC Manual Chapter 0502.

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
59-1	1-4-59	SR-E. I. du Pont de Nemours & Co.	0	\$7,000
	sulfide g	on head of secondary condenser in unit failed gas to flow into water side of heat exchanger. e to overpressure. 4-5 T of gas released to atm	Relief valve vented	
59-2	1-15-59	AL-Reynolds Electrical & Engr. Co.	0	\$20,000
	Booms 1 38 T.	buckled on two 50-T cranes while lifting 65	f-ft tower weighing	
59-3	1-17-59	OR-Union Carbide Nuclear Co.	0	\$86,020
	Multiple	circuit breaker failure led to severe electrical	fire.	
59-4	2-1-59	AL-Bendix Aviation Corp.	0	\$22,197
	box and	oven failed when a power relay came loose for dropped to bottom of unit. Weight of relay in closed position, energizing oven heaters.		
59-5	2-24-59	AL-University of California (LASL)	2 fatalities	\$27,000
	Detonati	ion of explosives instantly killed 2 employees.		
59-6	3-25-59	SR-E. I. du Pont de Nemours & Co.	0	\$20,000
	Leaking	compression fitting.		
59-7	3-31-59	HA-General Electric Co.	1-1st degree burns-face	\$9,518
	Plutoniu	m glovebox explosion.		
59-8	4-2-59	SR-E. I. du Pont de Nemours & Co.	0	\$8,700
	Solvent suddenly containing reservoir surface (
59-9	4-2-59	OR-Union Carbide Nuclear Co.	0	\$7,485
		emoval of obsolete ventilation ducts, a ductoff a valve on the pump discharge side of cool		
59-10	4-10-59	HA-General Electric Co.	1 fatality	0
	Workman	n straddling 4-in. pipe fell 59 ft.	•	
59-11	4-17-59	OR-Union Carbide Nuclear Co.	0	\$9,886
	Electric 1	motor failure.		,

See footnotes at end of Appendix C.

No. ¹ - Type ²	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
59-12	4-17-59 AL—Government-owned Property Fire occurred in 1-story bedroom dwelling. The omaterials in the vicinity of the floor furnace.	0 cause was combustible	\$12,000
59-13	4-28-59 OR—Union Carbide Nuclear Co. Lightning damaged transformer.	0	\$6,500
59-14	5-13-59 ID-Wright-Cheney-Birch Employee was working on 60-ft scaffold when it to	1 fatality	0
59-15	5-13-59 LAR-Pratt & Whitney Aircraft (CANEL Electrical fire due to severe arcing on the line side o		\$30,000
59-16	6-3-59 SR-E. I. du Pont de Nemours & Co. Lightning damaged two 750-KVA transformers.	0	\$13,750
59-17	7-1-59 AL—University of California (LASL) ¾-in. copper tubing separated from male section pressure was applied, loose end of tubing whippe injuring 2 men.		0
59-18	7-3-59 SAN—University of California (LRL) Overpressure helium system caused release and quantity of curium 244, resulting in contaminatioverexposures.	0 distribution of small on of laboratory. No	\$32,400
59-19	7-17-59 AL—University of California (LASL) RA-Gas release.	0	\$8,8005
59-20	7-18-59 HA-General Electric Co. Fire involving bakery and grocery store. Electrical	0 short in junction box.	\$24,500
59-21	7-27-59 LAR—General Electric Co. Fire in construction contractor's material caused so to building.	0 moke and fire damage	\$9,540
59-22	7-31-59 HA—General Electric Co. Autoclave explosion.	0	\$4,000
59-23	8-1-59 NY—Princeton University Disruption of water service to stellarator caused by pump supply line.	0 y overpressure in well	\$12,000
59-24	8-6-59 AL—Monsanto Chemical Co. Drybox explosion.	0	\$1,933

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
59-25	8-7-59	OR-J. A. Jones Construction Co.	1 fatality	0
	Electricia machine.	n electrocuted when contacting energized		
59-26	8-16-59 Sodium s	CH—Atomics International storage tank exploded.	0	\$24,450
59-27	8-21-59	SR-E. I. du Pont de Nemours & Co.	0	\$129,324
		leaked from the loosened flange during mai porator in hot canyon, vaporized and contan		
59-28	9-4-59	LAR-General Electric Co.	0	\$7,500
	Wind dan	nage to aluminum side wall of building.		
59-29	9-23-59	SR-E. I. du Pont de Nemours & Co.	0	\$14,000
	Product I	oss due to sudden leak at a high pressure valv	e.	
59-30	9-29-59	SR-E. I. du Pont de Nemours & Co.	0	\$50,000
	Hurrican	e damaged water dam.		
59-31	10-3-59	SR-E. I. du Pont de Nemours & Co.	0	\$9,750
	Overheat	ing caused diesel engine damage.		
59-32		AL—University of California (LASL)	4 fatalities	\$5,341
	Explosion	n occurred while disposing of scrap and waste	explosives.	
59-33		ID-Phillips Petroleum Co.	0	\$61,800
	Criticality	y incident, release of radioactive materials.		
59-34	10-30-59	AL-B & R Tub Co., subcontractor Holmes & Narver	0	\$48,396
	Barge ove	erturned carrying drill rig and core.		
59-35	10-30-59	SNR—General Electric Co.	1 fatility	\$100,000
., .,	Air-oil ex	plosion occurred in air flask component of a 1. Fatality was not chargeable to AEC.	•	*100,000
59-36	11-3-59	AL-Holmes & Narver	0	\$7,919
	LST struc	ck deep water pier during storm causing dama	ige to pier.	
59-37	11-20-59	OR-Union Carbide Nuclear Co.	0	\$350,000
	Chemical	explosion in innercycle evaporator.		
59-38	11-23-59	OR-Mallinckrodt Chemical Co.	0	\$6,000
	combusti	ed flue in gas stack. Incident was probably on of propane gas or ignition of carbon which the stacks.		

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
59-39	•	ynolds Electrical & Engr. Co.	1 fatality	0
59-40	Loose contaminate	du Pont de Nemours & Co. de particles on the lid of a wassind, contaminating the ground, loc		\$5,200
59-41	inspector entered a	omics International cident occurred at sodium pure pump casing which was 15 ft. de ect the collar near the bottom.		0
59-42		roleum Combustion & Engr. Co. caused jib section of crane to fall on an employee.	1 fatality and drop 1 cu. yd.	0
59-43	12-29-59 OR-Nat An explosion occur	tional Lead Co. of Ohio	0	\$10,000+
60-3	Two boilers in a rein firebox while a	conne National Laboratory eactor power house exploded due an attempt was being made to so to boiler and adjacent piping w	tart unit manually.	\$35,000
60-4		mes & Narver liver drowned while performing assund.	1 fatality signed duties at the	0
60-5	A reactor vessel ho moved by means o	gonne National Laboratory olddown plug assembly dropped what is a hand winch. Two riggers were be plug was damaged.		\$13,115
60-7		niversity of California (LRL) ng of an experimental high explo	0 osive, a detonation	\$12,500
60-8	An employee was the monitoring syst	ion Carbide Nuclear Co. exposed while cleaning up a cell d tem to disclose the presence of radi 5,550 rem to the hand (beta dose).		0
60-9	Explosion occurred	ion Carbide Nuclear Co. I in a uranium sintering furnace lo mage to furnace and buildings.	0 cated in a foundry.	\$20,000

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
60-10	3-18-60	SR-E. I. du Pont de Nemours & Co.	0	\$135,300
		gen-sulfide gas release from a process equip fire. The property damage was to the condenser		
60-11	3-30-60	SR-E. I. du Pont de Nemours & Co.	0	\$6,000
	During ar an out-of out motor			
60-12	3-18-60	AL-Reynolds Elec. & Engr. Co.	1 fatality	0
	kitchen ei in first a	ping to pour 15 gallons of hot soup stock into mployee slipped, causing hot soup to spill on hand second degree burns to chest and inside caployee died as a result of the burns.	is body, resulting	
60-13	4-13-60	NY-Harvard University	1 fatality	0
	straighten	employee was standing on a 34-inch-wide g ling a reinforcing rod with a length of pipe, the oyee fell 20 ft. to a concrete subarea.		
60-14	4-17-60	HA-General Electric Co.	0	\$250,443
	caused h	explosion in pyrophoric metal contents of a cigh damage to dissolver, off-gas filter, and it. Contamination spread to cell, canyon, and of the accident are not established.	related process	
60-15	4-26-60	OR-Union Carbide Nuclear Co.	0	\$39,500
	a hot cell the cell for into the r	ated graphite-clad reactor fuel element was be with a remotely operated saw. A change in a corced contaminated graphite dust from the cell test of the building. There were no overexposuranup of the area.	ir pressure inside, and it dispersed	
60-16	4-5-60	SR-E. I. du Pont de Nemours & Co.	0	\$216,285
	was cause circumfer	an outlet nozzle on a reactor necessitated a shied by three cracks extending approximately 2 ence of the nozzle. The cost was chiefly due to and the loss of heavy water.	½ in. around the	
60-18	6-15-60	AL-Reynolds Elec. & Engr. Corp.	0	\$9,950
	with a cra	crew was removing the astrodome from a 20- ane. As the dome was being lowered, the sling to fall approximately 10 ft.		
60-19	6-11-60	AL-General Electric Co.	0	\$9,098
		f overload switches to operate during severe rnout of transformer.	electrical storm	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage	
60-20	6-24-60	ID—Phillips Petroleum	1 injured	0	
	ricochete	e seriously injured when portion of a stud (cord, entering forehead over right eye and lodgiowder-actuated power tool.			
60-21	6-28-60	OR-Goodyear Atomic Corp.	0	\$7,145	
		less steel lining of a new liquid nitrogen s collapsed when its contents were partly eva- te test.			
60-22	7-11-60	AL-Los Alamos Medical Center	0	\$12,000	
	A 15-KV damaged	switchgear located in a subbasement equi by fire.	pment room was		
60-23	7-15-60	OR-Mallinckrodt Chemical Works	1 injured	\$5,000	
	Hydrogen gas explosion occurred in gas furnace enclosure in metal plant. One employee suffered serious injuries.				
60-24	7-6-60	AL-Mound Laboratory	0	\$31,360	
	result of being lock to a malf- gloves ble	lental discharge of radioactive material into a pressure buildup in a drybox. This was due to ked in the open position and a venting solend unction. The pressure built up to a point that we out, thereby releasing radioactive particulative persons received minor exposures.	to an inlet solenoid bid being closed due tone of the drybox		
60-25	8-31-60	ID-Fluor Corp., Ltd.	1 fatality	0	
		employee was painting the handrails around ries when he fell 69 ft.	a silo, he suffered		
60-26	9-13-60	SR-E. I. du Pont de Nemours & Co.	0	\$250,000	
		ated cooling water discharged from canyon sures. The large loss was due to decontamination			
60-27	9-29-60	SR-E. I. du Pont de Nemours & Co.	0	\$8,300	
	Water lead				
60-28	6/2-6-60	SR-E. I. du Pont de Nemours & Co.	0	\$24,000	
	contamin	hipment of irradiated fuel elements, 30 ated water leaked from the cask. The clination of area.			
60-29	8-4-60	OR-Goodyear Atomic Corp.	0	\$18,132	
	During views breaker fa	olent storm, severe power system disturbance illure.	caused oil circuit		

No. ¹ - Type ²	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
60-30	10-7-60 AL—Sandia Corp.	0	\$16,500
	Beechcraft Drone Aircraft, which was to be used f when radio control was lost in desert.	or air sampling, crashed	
60-31	11-8-60 AL-Sandia Corp.	1 exposed 1 exposed/injured	0
	Employees were accidentally exposed to electron Van de Graaff accelerator (12,340 & 1277 rem ha		
60-32	9-13-60 LAR-General Electric Co.	0	\$12,000
	During an electrical storm lightning damaged trans	former.	
60-33	7-12-60 HA-Government-Hanford	0	\$6,000
	15-mile per hour breeze spread a grass fire overproperty.	er 3,000 acres of AEC	
60-34	11-2-60 SR-E. I. du Pont de Nemours & Co.	0	\$37,100
	Fire in a construction building.		
60-35	11-10-60 SAN-University of California (LRL)	0	\$101,000
	Fire started in curium processing cave by an appearance bath in glovebox. Loss confined to one room, but loss. No release of radioactive materials to environ	it all contents complete	
60-36	11-10-60 SR-E. I. du Pont de Nemours & Co.	0	\$40,000
	Induced draft fan failed due to excessive vibration		
60-37	11-14-60 AL-Sandia Corp.	0	\$32,000
	Fire occurred in heat paper stored in dry room.		
60-38	12-7-60 OR—Union Carbide Nuclear Co.	0	\$10,036
	A full, high pressure, 30-tube gas trailer overtucoupling to tractor.	rned in the process of	
60-39	11-18-60 HA-General Electric Co.	1 injured	0
	Pipefitter slipped and fell 15 ft. down a shaft.		
60-40	12-21-60 HA-General Electric Co.	0	\$12,294
	Buildup of pressure in a steam autoclave resulted some material from the autoclave through the buildesulted.		
60-41	10-4-60 AL-Edgerton, Germeshausen & Grier	2 exposed	0
	Two employees were exposed to gamma radiation	(18 & 5 rem wb).	
60-42	11-17-60 OR—Union Carbide Nuclear Co.	0	\$103,260
	Ten-ton cylinder of UF ₆ ruptured.		

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
60-43	11/8-28- 60	OR-National Lead Co. of Ohio	0	\$5,000+
		nriched uranium tetrafluoride lost throug ocated in the plant.	n stack of dust	
61-1	1-3-61	ID—Combustion Engineering, Inc.	3 fatalities 9 exposed	\$4,350,000
	crew were	within reactor vessel of SL-1 reactor plant. killed instantly by explosion. Third died versult of injury to head. Maximum overecrew members during emergency was 27 removed.	vithin about two xposure to nine	
61-2	1-9-61	AL-ACF Industries, Inc.	0	\$27,060
	Fire in plat	ting shop.		
61-3	1-11-61	AL-Reynolds Electrical & Engineering Co.	0	\$8,000
	mover acc	e being towed from test bunker to disassemed identally uncoupled and vehicle car crashed maging car and bunker.		
61-4	1-24-61	AL-Los Alamos Scientific Laboratory	1 fatality	0
	Employee	fell from bunker 10-12' to concrete pad.		
61-5	2-2-61	AL-ACF Industries, Inc.	1 fatality	\$2,500
	Head-on m	notor vehicle collision.		
61-6	2-14-61	AL-Los Alamos Scientific Laboratory	1 fatality	0
	Employee	overcome by solvent vapors while working in	enclosure.	
61-7	1-25-61	ID—Phillips Petroleum Co.	0	\$6,000
	solution ac	accident occurred at chemical processing placidentally surged from geometrically safe coing to momentary occurrence of chain reactionses.	ntainer to unsafe	
61-8	3-10-61	OR-Central Illinois Tower Maintenance Co.	2 fatalities	0
	Two employers.	oyees fell 145' when top section collapsed d	uring erection of	
61-9	3-16-61	PNR—Eichleay Corp.	1 fatality 3 injured	0
		rrangement rigged for painting overhead stru llapsed, causing the death of one and injuries t		

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
61-10	5-11-61	AL-Monsanto Chemical Co. (Mound Laboratory)	1 exposed	\$4,016
	radioacti	buildup in closed caustic scrubber system we material into room. Employee received 71 rea contaminated.		
61-11	1-10-61	SR-E. I. du Pont de Nemours & Co.	0	\$7,750
		d machine used to discharge reactor com I-beam used to support portable bridge.	mponents struck	
61-12	5-19-61	OR-Goodyear Atomic Corp.	0	\$37,130
	Air circu	it breaker failed resulting in shutdown of seven	cells.	
61-13	7-11-61	SAN-University of California (LRL)	0	\$13,500
	Fire occ	urred involving approximately 190 pounds of c	hemical explosive.	
61-14	7-18-61	HA-General Electric Co.	0	\$5,900
	Two Har	nford railroad locomotives collided head on.		
61-15	8-1-61	HA-Hanford Operations Office	0	\$8,000
		res burned approximately 4,300 acres, probably ective muffler on railroad diesel locomotive.	y caused by sparks	
61-16	8-14-61	HA-General Electric Co.	1 fatality	0
		ee fatally injured when tractor rolled backwas was assisting in unloading it from a trailer.	rds out of control	
61-17	8-14-61	SNR-General Electric Co.	0	\$5,700
		ned approximately 3,000 square feet of newly to building and ventilating equipment located o		
61-18	8-29-61	AL-Sandia Corp.	0	\$14,700
	Flash floof cost.	ood at deactivated base. Removal of 8-12 inch	es of silt majority	
61-19	9-2-61	ID-Phillips Petroleum Co.	0	\$20,000
	Compres rotor.	sor malfunctioned, damaging insulation and wi	iring on stator and	
61-20	9-7-61	AL-Los Alamos Scientific Laboratory	1 fatality	0
	Employe turned o	ee killed in motor vehicle accident in which ver.	car skidded and	
61-21	8-14-61	HA-Hanford Operations Office	0	\$69,865
	Series of	brush fires caused by violent electrical storm.		

No. ¹ - Type ²	Date Field Office ³ - Contractor	Injuries ⁴ Exposures	AEC Property Damage
61-22	9-13-61 AL—Bendix Corp. Flood following Hurricane Carla.	0	\$449,200
61-23	10-2/24- SR-E. I. du Pont de Nemours & Co	0	\$400,000
	Series of flume failures occurred in SRP reasystem.	ctor cooling water effluent	
61-24	10-25-61 AL-Dow Chemical Co.	0	\$7,000
	Explosion (considered to be of low order) occur	urred in boiler.	
61-25	10-26-61 AL-Sandia Corp.	1 fatality 3 injured	\$131,210
	Fire in dry room.		
61-26	10-20-61 AL—Monsanto Chemical Co. (Mound Laboratory)	1 exposed	\$590
	Employee received 1.4 body burden of polo containing polonium was dropped. Small amoreadily cleaned up. (22 rem to spleen)		
61-27	10-29-61 AL-Albuquerque Operations Office	e 0	\$57,000
	Airplane struck 500-foot radio tower, collaps plane.	sing tower. Wing torn from	
61-28	11-7-61 AL-ACF Industries, Inc.	0	\$34,450
	Gas explosion in portable metal shed housin received minor injuries. Shed badly damage exterior to reactor also damaged.		
61-29	10-27-61 OR—Oak Ridge National Laborator	y 1 exposed	0
	Employee received beta burns to hands an occasions while performing operations on fuel were 1,200 rem to fingers of left hand and 9 hand.	specimens. Dose estimates	
61-30	10-15-61 ID—Phillips Petroleum Company	0	\$10,000
	Contractor's bus collided with private car; a minor injuries. Private car driver killed.	20 bus passengers received	
61-31	9-18-61 ID—Idaho Operations Office	0	\$7,525
	Flood damage.		
61-33	12-19-61 HA-General Electric Co.	0	0
(press release)	Superficial plutonium contamination punctu wire pierced glove while wiring inside of a hoof		

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
61-34	8-16-61 HA-J. A. Jones Construction Co.	0	\$5,100
	Contamination spread occurred while dismantling equipment in a process building. Five employees recei contamination.	old laboratory ved some skin	
61-36	12-12-61 ID-Phillips Petroleum Co.	0	\$16,360
	Reactor manually scrammed following fission break cause of primary coolant flow resulting from remnants of trar resin sight box.		
61-37	12-4-61 BH—Brookhaven National Laboratory	0	\$10,850
	Fire in biology laboratory. Major portion of loss equipment.	was damaged	
61-38	4-20-61 HA—General Electric Co.	0	\$13,000
	Uranyl nitrate (1,355 lbs. of depleted uranium) lost to grotrailer was overfilled due to misunderstanding between reand their lunch relief.		
61-39	4-13-61 HA—General Electric Co.	0	\$12,900
	Approximately 30,000 gals. of nitric acid (100%) lost to as result of valves being left open.	chemical sewer	
61-40	11-21-61 HA—General Electric Co.	0	\$9,000
	Approximately 1,089 pounds of depleted uranium lost to in plant.	chemical sewer	
62-1	1-22-62 SR-E. I. du Pont de Nemours & Co.	1 fatality	0
	Carpenter crushed beneath concrete form.		
62-2	2-15-62 SR-E. I. du Pont de Nemours & Co.	0	0
	Purging of stack gas sampling line released contamina material requiring washing of 163 vehicles for decontamina		
62-3	2-14-62 NV—Reynolds Electrical & Engineering Co.	0	\$7,000
	Tractor-trailer loaded with drill rig overturned.		
62-5	2-21-62 OR-National Lead Co. of Ohio	1 injured	\$420
	Hydrogen explosion occurred in uranium casting pot w being removed. One employee received severe laceration of injury.		
62-6	3-18-62 OR—Union Carbide Nuclear Co.	1 fatality 1 injured	\$15,500
	Chemical explosion occurred during routine operations in a furnace. Two operators 35 feet from furnace were burned body, one died 12 days later.		

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
62-7	3-29-62 CH—Pipefitter fell 25	Argonne National Laboratory feet.	1 fatality	0
62-9		Union Carbide Nuclear Co. ventilation system, probable cause elect	0 rical spark.	\$24,700
62-10		W. L. Hailey & Co., Inc. d by slide of shale from side of trench.	1 fatality	0
62-11	· · · -	General Electric Co. ent with plutonium solution. Exposure le body.	3 exposed es were 110, 43,	0
62-12		Reynolds Electrical & Engineering Co. er when anchors pulled out to which	0 n guy wires were	\$20,000
62-13		Bendix Corp. erheated damaging channels in the oven.	0	\$20,430
62-14		General Electric Co. quipment failure.	0	\$10,000
62-15 (press release)	Employee receive pumps in loadou	General Electric Co. red cut on right index finger while clean it area. 70,000 d/m detected in excised permissible body burden estimated to	tissue. Less than	0
62-16		occurred when electrician attempted to	0 light oil fire.	\$9,728
62-17 (press release)	Pipefitter receive maintenance wo d/m detected	General Electric Co. ed puncture wound in left index finger ork in hood. Initial radiation measurer at wound site. Tissue excised. Estir ssible body burden remained at wound s	ment of 250,000 mate of 10-20%	0
62-18	While breaking b	Union Carbide Nuclear Co. oridge formation of coal in reclaim hoppoper ployees. One suffocated.	1 fatality er, coal gave way,	0
62-19	4-18-62 SR-I	E. I. du Pont de Nemours &Co. stack.	0	\$26,0005
62-20	4-25-62 NV—Drill rig collapse	Reynolds Electrical & Engineering Co.	0	\$19,000

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
62-21	Apr/ June- 1962	PNR—Westinghouse Electric Corp.	1 exposed	0
		ee received quarterly exposure of 8.1 rem dur ectrometer.	ing calibration of	
62-22	Mar/ July- 1962	ID—General Electric Co.	1 exposed	0
	Employe	ee received exposure of 3.2 rem one quarter and	3.9 rem another.	
62-23	7-24-62	OR-Puerto Rico Nuclear Center	7 exposed	0
	of irradi separates rem, 58	perator thought he had been given all clear signal ated fuel elements into position against aluminute sexposure room from reactor pool. Exposures rem, 24 rem, 18 rem, 18 rem, 8 rem, and zed for observation.	m window which eceived were 100	
62-24	· 7-26-62	AL-Monsanto Chemical Co. (Mound Laboratory)	3 exposed	\$4,243
	into roc Cost was	of calorimeter can accidentally discharged alphom atmosphere, causing surface and personnes due to decontamination. Bone exposures rals (26, 24, & 23 rem).	l contamination.	
62-25		HA-General Electric Co.	0	\$22,884
		climatizer room apparently caused by over pallast on one of the climatizers.	heated electrical	
62-26	7-12-62	AL-Albuquerque Operations Office	0	\$13,000
	Fire in A	AEC-owned building.		
62-27	8-14-62	PNR-Pittsburgh Naval Reactors Office	1 injured	\$15,000
		as rammed from rear by another freight train. to work within 2 weeks. Damage was to Governments.		
62-28		OR—Union Carbide Nuclear Co. see died from burns received when flash fire on of manhole port in side of oil circuit ard.		0
62-29	-	NV—Reynolds Electrical & Engineering Co.	1 fatality	\$1,179
	Power w	agon overturned.		
62-30	Apr/ June- 1962	AL-Dow Chemical Co.	3 exposed	0
		l operators received 3.1 rem, 3.3 rem and 3.4 rocessing plutonium metal.	rem, respectively,	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
62-31	June/ Aug- 1962	ID-General Electric Co.	1 exposed	0
	During c exposure	deanup of SL-1 incident, employee received as.	3.1 rem whole body	
62-32	8-24-62	ID—Phillips Petroleum Co. HA—General Electric Co.	0	\$1,600
		nd load (radioactive material shipping cask) wr, due to iodine 131 leaking from the cask.		
62-33	10-7-62	NY-Martin Co.	0	C
(press release)		electric power plant, McMurdo Sound, Anta AEC loss.	arctica, damaged by	
62-34	10-19-62	OR—Union Carbide Nuclear Co.	0	0
	Private damage t	driver hit truck carrying cylinders of radioa to truck.	active materials. No	
62-35	10-21-62	SR-E. I. du Pont de Nemours & Co.	0	\$13,200
	Approximal Approximation Appro	mately 700 pounds of D_2O lost when roll.	otameter sight glass	
62-36	Sept/ Oct- 1962	SAN-Lawrence Radiation Laboratory	1 exposed	0
		e working weekend duties as roving health 3.5 rem neutron exposure, as indicated by film		
62-37	11-13-62	2 ID-Phillips Petroleum Co.	0	0
(press release)	Slight in	crease in radioactivity levels caused temporary	y evacuation.	
62-38	12-3-62	AL-Albuquerque Operations Office	0	0
	compone	volving courier coach and two ATMX cars ents (no high explosives) derailed. Ship of \$15,500 repairs to coach and cars acknowled.	pment undamaged.	
62-40	9-14-62	OR-Oak Ridge Operations Office	0	0
	Fire in ra	adioactive shipment by train. Shipment undar	naged.	
62-41	12-13-62	OR-Union Carbide Nuclear Co.	0	\$2,900,000
	Explosio	n and fire in cell.		
62-42	12-14-62	OR-Union Carbide Nuclear Co.	0	0
	Truck m material	oving UF ₆ in cylinders involved in accident released.	with private car. No	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
62-43	Sept/ Dec- 1962	AL-Los Alamos Scientific Laboratory	1 exposed	0
		ndling residue in a recovery operation, an em exposure of 6.4 rem.	ployee received a	
62-44		SR—E. I. du Pont de Nemours & Co. se from a stack.	0	\$25,400 ⁵
62-45		SR-E. I. du Pont de Nemours & Co. se from a stack.	0	\$21,500 ⁵
62-46	8-4-62 While atte	NV—Reynolds Electrical & Engineering Co. empting to remove stuck pipe, drilling mast was	0 s damaged.	\$9,535
62-47		SNR—United Nuclear Corp. m overhead cutting and welding fell on discress room from ceiling to floor, igniting cur		\$16,310
63-1 A		ID—Phillips Petroleum Co. ansporting fuel elements involved in accident undamaged.	0 with private car.	0
63-2 A	from 54'	CH—Atomics International ervisor died of internal injuries and basal skull fall when he stepped backward into open shiel hals to crane operator.		0
63-3 A		OR—Mallinckrodt Chemical Works insporting radioactive material involved in acciment undamaged.	0 ident with private	0
63-4 A	Truck tra	OR—National Lead Co. of Ohio insporting uranium fuel slugs involved in accinent undamaged.	0 dent with private	0
63-5 A	upon arri	BH-NY-Nuclear Materials & Equipment Corp. leven packages of contaminated precious met wal at destination. Decontamination of several vicessitated.		\$27,560
63-6 B		OR—Government ent-owned dwelling totally destroyed by fire be heating system.	0 pelieved started in	\$6,787

No. ¹ - Type ²	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
63-7 B	1-26-63 PNR-Duquesne Light Co.	0	\$33,455
	Fire (definite cause undetermined) occurred in contract building. Government-owned office machines, furnit equipment damaged.		
63-11 A	2-16-63 NV—Camay Drilling Co.	1 fatality	0
	During excavation work, a construction worker was cru when the entire length of the tractor tread ran over lemultiple internal injuries.		
63-12 A	2-12-63 RL—General Electric Co.	0	\$8,650
	Promethium 147 contamination found in laboratory rot to other parts of building.	oms; also tracked	
63-13 B	2-10-63 AL—Sandia Corp.	0	\$10,200
	During construction of laboratory, power outage result "air structure," which was completely destroyed by high		
63-14 B	2-3-63 RL-Government	0	\$15,350
	Two small earth-fill dams washed out by melting snow.		
63-15 B	2-26-63 SR-E. I. du Pont de Nemours & Co.	0	\$24,000
	Fuel element dropped into reactor, damaging element.		
63-16 B	3-14-63 SR-E. I. du Pont de Nemours & Co.	0	\$22,0005
	Tritium release to atmosphere through stack.		
63-17 A	3-26-63 SAN—Lawrence Radiation Laboratory	0	\$94,881
	Criticality occurred during subcritical experiment invomaterials and small fire developed within enclosed concre		
63-18 B	3-16-63 AL—Dow Chemical Co.	0	\$8,200
	High-velocity winds caused circuit breaker failure in sub in fire readily controlled by fire extinguisher.	estation, resulting	
63-19 B	1-12-63 ID-C. F. Braun & Co.	0	\$5,800
	During subzero weather, water in firewater header header.	froze, damaging	
63-20 B	4-17-63 RL-General Electric Co.	1 exposed	0
	Maintenance employee received whole-body exposure working on fuel tube of reactor.	of 5 rem while	
63-21 A	4-22-63 OR—Union Carbide Corp., Nuclear Div.	0	\$25
	Tractor-trailer carrying interplant shipment of radic tipped over when forced off road by oncoming trundamaged.		

No. ¹ - Type ²	Date Field Office ³		juries ⁴ - xposures	AEC Property Damage
63-22 B	4-20-63 NV-Sandia Corp.		0	\$14,848
	Fire damaged aerodynamic bagenerator engine and was ignited high-velocity winds completely d	l by engine backfire. Later, on		
63-23 B	4-25-63 NV-Government		0	\$12,000
	High-velocity winds damaged thr	ee balloons.		
63-24 A	4-30-63 OR—Union Carbide C	orp., Nuclear Div. 1 fa	tality	0
	While testing an ion source, a phy	sicist was electrocuted.		
63-25 B	5-16-63 RL-Kaiser Engineers	5 ex	posed	0
	During process of removing co 27-curie iridium 192 sealed so unnoticed on cell floor for appreapproximately 76 workers wer source was located. Five indiv (15.2, 9.6, 7.4, 4, 3.9 rem).	ource fell out of cable and oximately five hours. During to intermittently in area when	remained his period, e exposed	
63-26 A	6-6-63 NV-Reynolds Electri Inc. Fifteen employees exposed du tunnel, nine receiving in excess	ring re-entry and recovery of 30 rem per year to thyroid		0
63-27 B	350, 265, 200, 133, 37, 36, & 34 4-15/5-8 CH-Atomics Internat		nood	0
03-27 D	Employee received partial-body X-ray diffraction machine.		posed orking on	Ü
63-28 B	6-19-63 NV-Reynolds Electric Inc.	cal & Engineering Co.,	0	\$17,000
	Drill rig toppled over while leveli	ng adjustments were in process	S.	
63-29 A	6-25-63 SNR-Marley Corp.	1 fat	ality	0
	During construction of fan cyli was compound fractured skull, massive hemorrhage.			
63-30 A	6-25-63 NY-Pratt & Whitney CANEL	Aircraft Div., 1 far	ality	0
	While operator's helper was kn forklift truck, to counterbalance and he fell to ground. He suffe days later as result of injuries rec	overhanging weight, box tippered fatal pulmonary embolus	ed forward	
63-31 B	4-23-63 AL—Dow Chemical Co).	0	\$5,662
	Spill of contaminated nitric acid	solution.		

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
63-32 B	6-20-63	AL-Dow Chemical Co.	0	\$8,364
		line carrying high-level plutonium solution causeing and equipment.	ed contamination	
63-34 B	8-9-63	PNR-Westinghouse Electric Corp.	0	\$9,400
		vinds during electrical storm damaged roofs, stees, shrubs and fences.	tacks, ventilation	
63-35 B	6-28/7-8	SAN-Lawrence Radiation Laboratory	2 exposed	0
	excess o engaged	nployees received quarterly exposures to their f 25 rem, (calendar year exposures of '55 and in transferring radioactive materials into high port tongs.	44 rem) while	
63-36A	7-23-63	OR-H. K. Ferguson Co.	1 fatality	0
	Apprent valve pit	ice pipefitter was asphyxiated while checking for .	r inert gas leak in	
63-37A	7-24-63	AL-Mason & Hanger-Silas Mason Co., Inc., San Antonio, Tex.	0	0
		erailed. Coach carrying radioactive materials real undamaged.	emained upright.	
63-38 B	Apr June (OR—General Electric Co.	2 exposed	0
	rem who	ployees received quarterly external radiation ex ble body, 32 rem left hand, 14 rem right hand; the ody, 27 rem left hand, 25 rem right hand. Ex- naking physical measurements of irradiated	ne other, 2.1 rem posures occurred	
63-39 A	8-3-63	PNR-Westinghouse Electric Corp.	0	0
		g cask dropped during transfer. Contamination are foot spot by removing 1/8-inch of wooden sur		
63-40 B	8-6-63	OR—Union Carbide Corp. Nuclear Division	0	\$43,400
	and was	finite cause undetermined) originated in buildin confined to laboratory hoods and exhaust samaged building.		
63-41 A	8-1-63	OR-Union Carbide Corp. Paducah, Ky.	1 fatality	0
	to swing about ha	onworker was climbing down rolling-type scaffolg and fold, finally toppling to floor. He held on talfway down, then fell remaining distance (appression, dying five days later as result of skull frac	intil scaffold was oximately 6') to	

No. ¹ - Type ²	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
63-43 B	7-23-63 SR-E. I. du Pont de Nemours & Co. Tritium release to atmosphere through stack.	0	\$10,0005
63-44 B	7-25-63 NY-Babcock & Wilcox Co. While engaged in routine radiography, employee rexposure of 6 rem.	1 exposed eccived estimated	0
63-45 A	 7-10-63 NV—Reynolds Electrical & Engineering Co., Inc. A custodial employee suffered fatal pulmonary embinjuries received in automobile accident three months expressions. 	olism as result of	0
63-46 B	10-28-63 OR—Oak Ridge National Laboratory While work was being performed on infrared tritiur received tritium exposure of 12.5 rem to total body tiss	1 exposed	0
63-47 B	10-31-63 RL—General Electric Co.Lightning ignited sage and grass at 18 locations.	0	\$7,442
63-48 A	11-6-63 RL—General Electric Co. Fire (definite cause undetermined) in plutonium pur Plutonium contamination in immediate area of fire. slight skin contamination, readily removed. Costs relais \$85,400; decontamination costs \$251,300; overhead losses \$60,300.	Firemen received ted directly to fire	\$397,000
63-49 B	11-8-63 SNPO-N-Los Alamos Scientific Laboratory Overpressurization of hydrogen feed lines to turbine destruction of turbine, shrapnel damaged pipes, condui	pump resulted in	\$70,000
63-50 A	11-13-63 AL—Mason & Hanger-Silas Mason Co., Inc., San Antonio, Tex.High explosives (120 lbs.) detonated in storage igloo.	0	\$92,568
63-52 A	11-15-63 ID—Phillips Petroleum Co. Low-level spread of plutonium contamination from glo	0 vebox.	\$25,451
63-53 A	9-26-63 AL—The Zia Co. When truck backed over can of paint thinner, can contents on laborer's clothing. Flames from dum coveralls, and he died about six weeks later as result received.	p fire ignited his	0
63-54 B	12-4-63 AL—Eagle-Picher Co. Flash fire (definite cause undetermined) in vault who stored. One employee received first and second degree		\$58,507

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
63-55 B	12-9-63 OR—Goodyear Atomic Corp. Compressor in cell debladed while on-stream, acon exterior of compressor shell.	0 companied by small fire	\$51,500
63-56 A	12-12-63 ID—Phillips Petroleum Co. Truck transporting radioactive material undamaged.	0 jackknifed. Shipment	0
63-57 B	12-11-63 RL—Government Fire, probably caused by cigarette, in Governmen	0 t-owned drug store.	\$23,500
63-59 B	12-13-63 OR—Goodyear Atomic Corp. Power transformer failed causing tank to ruptur immediately.	0 re. Insulating oil ignited	\$244,800
63-60 B	10-17-63 CH-Argonne National Laboratory While making adjustment on gradient synchrotro whole-body exposure of 3.8 rem.	1 exposed n, an employee received	0
63-61 B	12-21-63 AL—Monsanto Chemical Co. During installation of copper tubing, plastic bayoxide was punctured, resulting in contamination decontamination.		\$7,611
63-62 B	Oct AL—Los Alamos Scientific Laboratory Dec. 63 Two men engaged in casting operations with no whole-body skin doses of 15.2 rem and 17.3 rem	ormal uranium received	0
63-63 B	10-31-63 SNPO—N—Pan American World Airway While in the process of loading collimator onto to Operator dropped load onto truck in attempt to crane \$5,483; damage to truck \$400.	ruck, crane began to tip.	\$5,883
64-1 A	1-20-64 AL—Government Empty AEC-owned 4-ton truck skidded on ic privately owned car carrying five passengers, three The three truck couriers were bruised but otherwise.	e of whom were injured.	0
64-2 A	1-23-64 RL—General Electric Co. Several employees received minor contamin equipment in waste storage facilities. They were a Cost due to decontamination of equipment.		\$2,141
64-3 A	2-3-64 OR—Union Carbide Corp. Nuclear Div. Interplant truck shipment of radioactive mater private car. Shipment undamaged.		0

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
64-4 B	1-25-63	AL-The Bendix Corp.	0	\$5,838
	Fire in a torch.	ir-conditioning system, believed to have been s	started by cutting	
64-5 B	2-25-63	AL—Mason & Hanger-Silas Mason Co. Burlington, Iowa	0	\$60,400
		n (definite cause undetermined) during as of high explosives. No radioactive material in		
64-6 A	2-24-63	AL—Mason & Hanger-Silas Mason Co. Clarksville, Tenn.	0	0
		outine disposal of high explosives waste, brubout 20 acres of no value. No radioactive mate		
64-7 A	2-24-63	ID-Phillips Petroleum Co.	0	0
		arrying 1/2-ton shipping cask containing sr we material in collision. Shipment undamaged.	mall quantity of	
64-8 B	2-4-63	NV-Holmes & Narver, Inc.	0	\$14,000
	Fire (def	inite cause undetermined) in construction su	applies in storage	
64-9 A	3-11-63	SAN-Lawrence Radiation Laboratory	1 fatality	\$1,600
		cs coordinator died as result of skull fracture r was driving overturned when he failed to manip		
64-10 B	2-12-63	RL-General Electric Co.	0	\$14,400
		er vessel of reactor loop damaged as result of water in system.	operating heaters	
64-11 B	3-11-63	RL-General Electric Co.	1 exposed	0
	against l	ce of irradiated wire pierced rubber glove of mais skin approximately three minutes, he re to his right thumb of 57 rem.		
64-12 A	3-15-63	NY-Materials & Equipment Corp.	0	0
	Truck oundamage	carrying radioactive materials slid into c	litch. Shipment	
64-13 B	3-19-63	CH-Atomics International	0	\$6,075
	by conde	ter, being used to test two new waste tanks, wensation from contaminated vent line connect becquently drained onto asphalt surface, cont ditch.	ted to one tank.	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
64-14 B	Jan CH-l Mar. 64	Battelle Memorial Institute	1 exposed	0
		handling of fission products in he ly external whole-body gamma exposu		
64-15 B		Reynolds Electrical & Engineering Co. Inc.	, 1 fatality	0
		gal. water tanker tried to jump clear; however, he was uanble to do so, and death.		
64-16 B	4-19-64 AL—	The Bendix Corp.	0	\$5,143
	Lightning damag	ged switchgear.		
64-17 B	3-31-64 CH-	Atomics International	0	\$23,000
		l in sodium loop tubing; resultant ng of six banks of thermoelectric t urther use.		
64-18 A	4-22-64 SAN-	-Advanced Technology Laboratories	0	0
	bottles of rad	nipment of five, each drum containing ioactive materials, was damaged door release of material resulted.		
64-19 B	5-10-64 ID-P	hillips Petroleum Co.	0	\$12,884
	pipelines to per Contaminated f	flushing to remove radioactive comit tie-in to new lines, leak developed build and steam issuing from leak were approximately ten acres. Major	d in hose coupling. re rapidly dispersed	
64-20 B	2-15-64 SR-I	E. I. du Pont de Nemours & Co.	0	\$10,460
		t left in reactor pipeline system using nonradioactive contamination of		
64-21 B	Jan PNR- Mar. 64	–Duquesne Light Co.	2 exposed	0
		adding doses, two employees received rem, respectively.	whole-body dose of	
64-22 B	4-23-64 SR-I	E. I. du Pont de Nemours & Co.	0	\$19,8005
	Tritium release	to atmosphere through stack.		
64-23 A	5-18-64 CH—	Battelle Memorial Institute	0	0
	rem/hr (gamma)	pped by truck, found at destination). Investigation revealed cask had been tamination; no significant personnel r	n dropped en route.	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
64-24 B	7-27-64	NY-Westinghouse Electric Corp.	0	\$10,500
	When a j crates ne			
64-25 B	6-12-64	AL-Dow Chemical Co.	1 exposed/injured	\$56,400
	dropped the oper	explosion caused by burning plutonium chain to carbon tetrachloride bath. The thumb and ator had to be amputated to effect decontangments of plutonium had become embedded in	l index finger of nination because	
64-26 A	5-26-64	OR-Mallinckrodt Chemical Works	0	0
		railer hauling radioactive material involved in Shipment undamaged.	n accident with	
64-27 B	6-10-64	NV—Reynolds Electrical & Engineering Co., Inc.	0	\$5,000
		unit, mounted on semitrailer, being towed by ckknifed, causing semi-trailer to turn over, de		
64-28 B	6-3-64	SR-E. I. du Pont de Nemours & Co.	0	\$11,000 ⁵
	Tritium r	elease to atmosphere through stack.		
64-29 B	6-14-64	SR-E. I. du Pont de Nemours & Co.	0	\$8,400
	Loss of a inadverte	approximately 600 lbs. of heavy water throug ntly.	h pipe left open	
64-30 B	6-18-64	CH-Notre Dame University	2 exposed	0
		ployees received exposures of approximately while working with 2000-curie cobalt 60 source.	180 rem to the	
64-31 A	7-1-64	AL-Federal Roofing & Siding Co.	1 fatality	0
		lied three days later from results of head and when he fell 22' to the ground from the roo		
64-32 B	7-2-64	AL-Los Alamos Scientific Laboratory	0	\$11,597
	•	n, attributed to accumulation of unburned air movement in furnace upper passageways,	•	
64-33 B	6-28-64	SR-E. I. du Pont de Nemours & Co.	o	\$11,0005
	Tritium r	elease to atmosphere through stack.		
64-34 B	6-19-64	SR-E. I. du Pont de Nemours & Co.	0	\$49,500 ⁵
	Tritium r	elease to atmosphere through stack.		

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
64-35 A	7-10-64 OR-National Lead Co. of Ohio	0	0
	Drum of radioactive material and trailer to contaminated. Both readily decontaminated. National radiation exposures.		
64-36 B	4-27/ AL-Monsanto Research Corp. 5-11-64	1 exposed	0
	During routine work with polonium in a laborate kidney dose of approximately 45 rem in ensuing y		
64-37 B	7-10-64 RL—General Electric Co.	1 exposed	\$75
	During pressing operations within glovebox, plute Ejected fragments caused deep laceration of empontamination of adjacent working area (180 rem	ployee's arm and minor	
64-38 A	7-23-64 OR-National Lead Co. of Ohio	0	0
	When door of freight car broke open during sw drums containing radioactive material fell out. I drum spilled in yard area but was recovered.		
64-39 B	4-17-64 RL—General Electric Co.	0	\$51,000
	Charging error made in loading reactor resulted limits.	in exceeding operating	
64-40 B	7-22-64 ID—Phillips Petroleum Co.	1 exposed	0
	Employee received exposure of approximately 31 rem to the other while manually removing radi stainless steel tubes.		
64-41 B	7-21-64 BH—Brookhaven National Laboratory	0	\$11,613
	Explosion in hydrogen purifier in bubble changer valve inadvertently left in closed position du Precooler and adsorber coils torn open and contain	ring purging operation.	
64-42 B	8-13-64 NV—Reynolds Electrical & Engineering Inc.	g Co., 0	\$10,000
	Mobile drill rig developed excessive speed on negotiate curve, and turned over, damaging rig car		
64-43 B	7-17/ SR-E. I. du Pont de Nemours & Co. 7-30-64	0	\$6,000
	Leaking nitric acid corroded canyon cell equipment	nt beyond repair.	
64-44 A	8-22-64 SR—Sylcor Division of Sylvania Electri Products	с 0	\$2,300
	Trailer-truck loaded with radioactive material co Loss represents direct damage to fuel elements. injured.		

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
64-45 B	9-2-64	RL—General Electric Co.	0	\$8,800
	Fragmen	normal operations, plastic impeller of exhaust its penetrated housing of adjacent fan causing water line was broken and a third fan unit dan	g it to disintegrate.	
64-46 B	Apr June (SAN—Lawrence Radiation Laboratory	1 exposed	0
	Chemist rem.	working in vicinity of cyclotron received whole	e-body dose of 3.4	
64-47 A	9-2-64	CH-Battelle Memorial Institute	0	0
	by gros	ailer arrived at destination with trailer bed slig s fission products coming from surface of d material. Truck-trailer decontaminated and	of cask containing	
64-48 B	9-14-64	NV-Reynolds Electrical & Engineering Co., Inc.	. 0	\$12,000
	Defective to fall.	e weld on drill rig leg caused leg to buckle in	ward and the mast	
64-49 A	9-19-64	NV-Reynolds Electrical & Engineering Co., Inc.	1 fatality 1 injured	\$74,000
	wire rop racks. Fo chest inj	al cables were being lowered into undergroun be from a hoist broke causing cable spools to be our men were hit by the spools, one receiving suries from which he died, one being seriously to lesser injuries. Four men were trapped und	e jerked from their extensive head and injured, other two	
64-50 A	9-23-64	SAN-Case Foundation Co.	1 fatality	0
		ee electrocuted when he contacted a drill 1 power lines.	rig which struck	
64-51 B	1-22/3-2	RL-Peter Kiewit Sons' Co.	0	\$66,000
		et of disposal tunnel collapsed while backfillings. Six weeks later, another 50 feet collapsed.	ng operations were	
64-52 B	7-13-64	SAN-Lawrence Radiation Laboratory	0	\$9,500
		plosives accidentally exploded and burned during n. No radioactive material involved.	ing normal pressing	
64-53 B	7-24-64	SR-E. I. du Pont de Nemours & Co.	0	\$102,0005
	Tritium	release to atmosphere through stack.		

No. ¹ - Type ²	Date Field Office ³ - Contracto	or Injuries ⁴ - Exposures	AEC Property Damage
64-54 B	10-1-64 SR-E. I. du Pont de Nemours & G	Co. 0	\$21,000
	Fire (definite cause undetermined) occur column in hot canyon. Fire caused airborne for remote maintenance. Water to quench	contamination to crane used	
64-55 B	10-27-64 AL-Monsanto Research Corp.	0	\$34,922
	Chemical explosion in metal hood when flashpoint. Two sets of gloves were significant contamination spread in operating area. The contamination.	hredded by the explosion.	
64-56 A	11-3-64 RL—General Electric Co.	0	\$318,000
	Roof fire (definite cause undetermined) resbiology building. All laboratory experiment lost. Also some valuable records.		
64-57 A	11-11-64 CH-Argonne National Laborator	y 0	0
	Broken valve on autoclave, housed in contaminated water to seep out of cask container and truck floor.		
64-59 B	11-16-64 OR—Union Carbide Corp., Nuclea	ar Div. 0	\$16,000
	Explosion in first stage of nitrogen compress thrown through roof and also damaging compressor was housed.		
64-60 B	Feb SAN-Lawrence Radiation Labora Mar. 64	atory 1 exposed	0
	During routine laboratory work, employee re 8.2 rem whole body.	eceived quarterly exposure of	
64-61 B	11-27-64 OR—General Electric Co.	0	\$41,680
	Fire in 10,000 KVA transformer.		
64-63 A	12-15-64 NV—Reynolds Electrical & Engine Inc.	eering Co., 1 fatality 1 injured	\$2,340
	When drill rig assembly failed, swivel assertilled instantly from crushing blow on head head injuries and broken arm.		
64-64 A	12-8-64 RL—General Electric Co.	1 fatality 1 injured	\$504
	Head-on collision of interplant locomotive employee riding in maintenance car died treceived; second employee seriously injurnaintenance car.	wo weeks later from injuries	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
64-65 B	12-22-64	ID—Phillips Petroleum Co.	0	\$10,000
	High wind	ls damaged movable test cell building.		
64-66 B	12-22-64	SR-E. I. du Pont de Nemours & Co.	0	\$12,700 ⁵
	Tritium re	elease to atmosphere through stack.		
64-67 B	10-28/ 11-2-64	NV—Holmes & Narver, Inc.	0	\$30,000
	Crane dan winds.	maged while aboard ship during high seas accom	panied by gusty	
64-68 B	12-17-64	NV—Reynolds Electrical & Engineering Co., Inc.	0	\$17,500
		f bridle line allowed crane mast to fall to derrice bending of mast members.	k stand, causing	
64-69 B	Dec. 64	ORUnion Carbide Corp., Nuclear Div.	1 exposed	0
	in enclose The empl	apling, weighing, and grinding uranium oxides of process system, operator received a lung burdoyee will receive an estimated integrated lung of first year.	den of $0.021 \mu c$.	
64-70 B	12-28-64	SAN—General Atomic—Division of General Dynamics Corp.	0	\$20,000
	malfunction generators	tonium-fueled prototype generators were don of high temperature environmental tests to be subject to ambient temperature of a re designed to withstand maximum ambient	t oven caused of over 600°F.	
65-1 A	1-15-65	OR—Union Carbide Corp., Nuclear Div. (Operational Incident)	0	\$296,000
	strainer. 7	which was to have been blocked off, was mistake. This error resulted in the irretrievable loss of an ia its discharge into a waste pond.		
65-3 A	1-20-65	SAN-Lawrence Radiation Laboratory, Livermore	0	\$185,000 ⁵
		ental release of radioactive gas (discharged throughen an employee, intending to tighten a stora it instead.		
65-4 B	1-17-65	OR-Oak Ridge Institute of Nuclear Studies	0	\$11,185
		exhibit and a privately-owned vehicle collideived minor bruises.	ed. The exhibit	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
65-5 A	1-28-65	NV—Reynolds Electrical and Engineering Co. Inc.	, 1 fatality	0
	4" pipe w drill rig,	drill helper was killed instantly when a "finge reighing 87 lbs.) fell 85' from the fingerboard striking him on the head, neck, and shoulde given as depressed occipital skull fracture wit	of the mast of a ers. The cause of	
65-6 B	2-5-65	SAN-Lawrence Radiation Laboratory, Livermore	0	\$10,795
	An anten telephone	na on a scientific trailer was damaged wh line.	nen it snagged a	
65-7 A	2-23-65	NV—Reynolds Electrical and Engineering Co. Inc.	, 1 fatality	0
	A wirema cabinet.	an foreman was electrocuted while working	in a switchgear	
65-8 A	2-20-65	OR-Government	0	0
		transporting 100 drums of thorium residues, clination was required.	overturned. Some	
65-9 B	1-14-65	CH-Atomics International	2 exposed	0
	exposures	ployees received estimated external whole of 4 rem each while moving an irractive probe with a high-bay crane.		
65-10 B	2-20-65	NV—Reynolds Electrical and Engineering Co. Inc.	, 2 exposed	0
	estimated	loyees, participating in a post-shot drilling of thyroid exposures of 31 and 27rem, respective e escaped from an "abandonment" valve open	ely, when gaseous	
65-11 B	1-11-65	SAN-Lawrence Radiation Laboratory, Berkeley	1 exposed	0
	exposure	oyee received an estimated external whole of 3.6 rem (film badge reading) while we a cyclotron vault.		
65-12 B	3-5/25-65	OR-Union Carbide Corp., Nuclear Div.	1 exposed	0
	oxide sph	the fabrication of strontium 89 impregnated eres, an employee received an estimated cun of 50 rem to each hand.		
65-13 B	4-14-65	NV-Lawrence Radiation Laboratory	6 exposed (LRL) 3 exposed (USAF	0
	before th	oud monitoring, when the cloud rose higher e airplane could complete its mission, six s received estimated external whole-body radia	AEC contractor	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
65-13 B— Cont.		5, 4.2, 4.1, and 4.1 rem, respectively; three 4.4 rem, respectively.	USAF personnel	
65-14 A	4-28-65 O	R-Union Carbide Corp., Nuclear Div.	2 exposed	0
	One employ rem and to burn develop	it started continuous operation because of ee received an estimated radiation exposure the end of the right thumb of 3500 rem bed but healed); the second employee recei- posure of 11 rem to the skin.	to the skin of 19 (a second-degree	
65-15 B	5-5-65 N	V—Reynolds Electrical and Engineering Co., Inc.	, 0	\$75,000
	A drill rig wa	s damaged when it overturned.		
65-16 B	5-6-65 N	Y—Harvard University and Massachusetts Institute of Technology	0	\$127,000
	modulator,	ibutable to the failure of one or more occurred at an electron accelerator. The ipment damaged beyond repair and the continuous cont	amount of loss	
65-17 B	3-29/ A 4-30-65	L-Monsanto Research Corp.	1 exposed	0
	employee 1	ving trash from hoods in a plutonium received an estimated external whole-bosure of 3.9 rem.		
65-18 B	3-29/5-9 A	L-Monsanto Research Corp.	1 exposed	0
		processing of radioactive material, an empleternal whole-body cumulative radiation exp	•	
65-19 B	5-22-65 O	R—Oak Ridge National Laboratory	1 exposed	0
		received a radiation exposure to the left for then the beam shutter on a Van de Graaff knowledge.		
65-20 A	6-14-65 O	R—Union Carbide Corp., Nuclear Div.	1 fatality	0
	the sidewalk	vas fatally injured when he fell 18' from an a. Investigation revealed that his body belt death was a fractured skull.		
65-21 B	6-14-65 A	L-Government	1 injured	\$7,292
	parked posit evasive action fireman susta foot, a sever	being used to fight a brush fire rolled, do ion on a mesa into a canyon, dropping 60' on taken to avoid being struck by the rolained severe injuries to both heels, broken to a laceration on the head, and a severe bruise in multiple contusions and lacerations. The	. As the result of llaway vehicle, a cones in the right of the left thigh,	

No.1 - Type ²	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
65-22 A	6-21-65 NV-Shaft Drillers, Inc.	1 fatality	0
	An employee suffered fatal injuries when he fe platform onto a concrete pad. The cause of death skull fracture, frontal region; multiple fracture internal injuries.	h was severe depressed	
65-23 A	6-24-65 OR-Oak Ridge National Laboratory	2 injured	\$2,500
	Two cooperative program students were injurexplosion occurred in a laboratory as one of the stomake "fireworks" for his own use by mixin magnesium perchlorate. This student suffered a peright eye, severe burns of the left eye, and blast in abdomen, upper extremities, and neck; very severe groin. The second student, working nearby (and "fireworks" venture) received multiple lacerations the body.	tudents was attempting g red phosphorus and enetrating injury of the njury to the chest wall, blast injury to the left d not involved in the	
65-24 A	7-5-65 NY—Harvard University and Massachuse Institute of Technology	tts 7 injured 1 fatality	\$1,453,000
	An explosion and fire occurred in the experiments complex. The incident was caused by the sequent and outer beryllium windows of a liquid hydrogen persons were injured, one of whom died fifteen dathird degree burns suffered over 60% of the body at the seven others, one had severe burns; one, serious back injury; two, burns; one, head injuries and cuand leg. Two firemen were injured, also: one, finger injury requiring ten stitches. The property led damaged beyond repair and necessary repair costs.	tial failure of the inner bubble chamber. Eight tys later as the result of and a ruptured liver. Of s burns; one, burns and tts; one, injury to chin smoke inhalation; one	
65-25 B	4-8-64 AL-Dow Chemical Co.	0	\$8,810
	While repaneling an office wall, a carpenter leaned of shelving and used the ladder as a work platfor which the top brackets had been removed, to beyond repair some of the inspected parts it conjumped to the floor, receiving only minor bruises.	rm. The shelving, from oppled over, damaging	
65-26 B	5-6-65 AL—Dow Chemical Co.	0	\$7,557
	While attempting to activate a product transfer list solution was sprayed out of a flanged union that had the contaminated employees were readily decorated for decontamination and for replacing contaminated	nad not been tightened. ontaminated. Cost was	
65-27 B	5-10-65 SR-E. I. du Pont de Nemours & Co.	0	\$33,600
	Process water (2400 lbs.) was lost when it leake sleeve.	d through an unseated	
65-28 B	5-16-65 SR-E. I. du Pont de Nemours & Co.	0	\$9,800
	Process water (700 lbs.) was lost when it leaked sleeve.	l through an unseated	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
65-29 B	7-20-65	AL-The Bendix Corp.	0	\$11,183
	combina	apons components were damaged in an overh- tion oven and refrigerator. Overheating apparer actioning automatic temperature control.		
65-30 A	7-7-65	SAN-Lawrence Radiation Laboratory, Livermore	1 exposed/injured	0
	reached radiation the right	n employee, assuming an X-ray machine we inside of it to change materials, he received exposure of 1,000 rem to the index, middle, at hand; second-degree burns developed and heat time injury of twelve days.	red an estimated and ring fingers of	
65-31 B	7-31-65	SNPO-N-Pan American World Airways, Inc.	. 1 exposed	0
	exposure	loyee was assigned an estimated external who of 3 rem after he attempted to unclog a valoperations, unaware that fuel element fragmentling.	cuum pipe during	
65-32 B	7-31-65	RL-General Electric Co.	0	\$75,000
	oil-fired	losion occurred in a boiler during an attem burner with a kerosene torch after the auto- ailed to function.		
65-33 B	7-19/30-6	65AL-Monsanto Research Co.	1 exposed	0
	radiation	loyee received an estimated external whole exposure of 5.8 rem while hand-carrying sources during radioactive trash recovery.		
65-34 B	May 65	OR-Union Carbide Corp., Nuclear Div.	1 exposed	0
	oxides t	loyee, whose assignment involved the fluoring of uranium hexafluoride, received a cumulative (an accrued annual exposure of 25 rem)		
65-35 B	8-23-65	RL-Battelle-Northwest	0	\$76,800
	occurring the built contaming body but not spre-	m contamination spread followed an exp g in a glovebox when cleaning fluid ignited. To ding immediately. Prompt showering easily nation. One employee received 10% of a max rden (bone) of plutonium 239 by inhalation. C ad outside the building. About 90% of the cos mination.	en employees left removed all skin imum permissible contamination did	
65-36 B	8-25-65	OR-Union Carbide Corp., Nuclear Div.	1 injured	\$7,915
	machinir was dam	emoval of the front of a large nitrogen d ng of a lithium part, lithium residue dust igni naged. A fireman fell 7' to the concrete floor received a broken rib and other less serious injur	ted. The machine while fighting the	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
65-37 B	8-27-65 Four tra	CH—Argonne National Laboratory nsformers were damaged by lightning.	0	\$35,000
65-38 A	9-9/13-6	5 ID—Government	5 exposed	0
	curies of thyroids shipmen	eight shipment of methyl iodide containing if iodine 131 leaked. Iodine 131 depositions of sixty-four people known to have been in t. Five of them received estimated thyroid do 1.9 rem, respectively.	were found in the contact with the	
65-39 B	9-13-65	SAN-Lawrence Radiation Laboratory, Livermore (Operational Incident)	0	\$30,000
	as he at	tic bag, containing a plutonium metal m-plated pieces, burst into flames when touche tempted to place it in a metal container. The ag only; cost was for decontamination.	ed by an employee	
65-40 B	9-5-65	SR-E. I. du Pont de Nemours & Co.	0	\$7,300
		r material was used in the decontamination of ting the expense of recleaning the exchanger.	a heat exchanger,	
65-41 B	8-27-65	CH-Argonne National Laboratory	0	\$8,000
	Lightnin cubicle.	g caused the destruction of a breaker and	the burning of a	
65-42 A	9-29-65	RL—Battelle Northwest	0	\$895,000
	Fission activated contains loss of l contaming the read	ess tube failed, releasing fission products into product activity spread within the contain diventilation containment. Personnel were unament vessel for a period of 12 hours. The reaction pressure. The cost is based on the equipmented beyond further use and the expense of dector system and containment shell. Personne ormal administrative limits.	nment vessel and able to reenter the ctor scrammed on nent and materials econtamination of	
65-43 B	1965	OR-Goodyear Atomic Corp.	8 exposed	0
	to urar depositio	erforming their regular duties in the conversion nium hexafluoride, eight employees receive ons resulting in estimated 12-month accrued lur 22, 21, 20, and 16 rem.	ed uranium lung	
65-44 A	9-15-65	RL—General Electric Co.	1 exposed/injured	i 0
	"ON" at thumb a inside t estimate	loyee, unaware that the X-ray emission spect and the shutter was stuck on "OPEN", received and three fingers of the right hand as he wip the sample chamber. The radiation dose to d to be 80,000 rem. This resulted in a lost-than amputation of a portion of the employee's income.	X-ray burns to the bed moisture from the fingers was time injury of 100	

No. ¹ - Type ²	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
65-45 B	10-13-65 SAN-Lawrence Radiation Laboratory, Berkeley	y 0	\$9,149
	An explosion and fire occurred in a mechanically faulty veat an outdoor switching station. The majority of the cost repairing the regulator.		
65-46 B	5-8-65 RL-Battelle-Northwest	0	\$7,000
	Failure, due to fatigue, of a $1/2''$ stainless steel tubing line loss of approximately 400 lbs. and the degrading of 1,02 water.		
65-47 B	8-2-65 NV—Reynolds Electrical & Engineering Co., Inc.	0	\$7,000
	An 80' crane boom fell backward across the top of the smashing the house and buckling the boom.	e crane house,	
65-48 B	8-25-65 AL—Mason & Hanger-Silas Mason Co., Inc., Burlington, Iowa	0	\$52,537
	A hail storm damaged steam line insulation, broke windo in sheetmetal of engineering equipment and autos, and da buildings.		
65-49 B	10-15-65 AL—Dow Chemical Co.	10 exposed	\$17,057
	An attempt to unclog a plutonium machining coolant rignited plutonium metal, resulting in the contamination of of the building and parts of another. Ten employees recexposures from .017 to .119 microcuries of plutonium waccrued annual dose to the lung of 112, 110, 83, 44, 42, 216 rem.	a major portion eived inhalation hich produce an	
65-50 B	10-12/21 AL-Los Alamos Scientific Laboratory	3 exposed	0
	While removing fuel pin handling rods and reflect metallurgical study) from the remains of a partially distributed employees received estimated external whole-boardiation exposures of 4, 3.8 and 3.6 rem over a nine-day partially distributed in the contraction of the contraction	antled reactor, dy cumulative	
65-51 B	10-23-65 AL-ACF Industries, Inc.	0	\$41,000
	Fire in a plating laboratory, caused by an electrical flammable fume exhaust duct material at that location rapidly through the duct system, igniting several tank exponents of tank consoles.	on, and spread	
65-52 B	10-30-65 RL—General Electric Co.	0	\$7,200
	During an aluminum jacket dissolution in a dissolver, reaction involving ammonia and/or hydrogen occurred with heater, through which these gases were accidentally vented which continued for three hours, totally destroyed the heater.	thin an electric l. The reaction,	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
65-53 B	9-30-65 A	L–Sandia Corp.	0	\$11,037
		p test, a pilot flew too low over the conged structures in the area.	trol area. A sonic	
65-55 B	11-9-65 A	L—Dow Chemical Co.	0	\$23,253
	used in a g furnace in a spread to a required sk	on and fire occurred when acetone fumes a glovebox paint-stripping operation, contact another part of the glovebox line. Plutonia adjacent rooms and the second floor. To kin decontamination; none received sign posures. The cost was for decontamination	ted a hot muffle im contamination welve employees gnificant internal	
65-56 B	Oct A	L-Los Alamos Scientific Laboratory	2 exposed	0
		ining irradiated reactor reflector pins, two external whole-body quarterly radiation exp		
65-57 A	12-23-65 S	AN-Stanford Linear Accelerator Center (Statewide Steel Co., subcontractor)	1 fatality 1 injured	0
		concrete plank fell, seriously injuring or other to death.	ne employee and	
65-58 B	12-26-65 C	H—Argonne National Laboratory	0	\$22,600
	hydrogen ap equipment a	on, resulting from the ignition of a hydroge oparently evolved from nickel-iron batterie airlock joining a reactor building and a fuel material was involved.	s, occurred in the	
65-59 B	Oct S Dec. 65	AN-Lawrence Radiation Laboratory, Berkeley	1 exposed	0
		orming routine startup operations at an eccived an estimated external whole-body of 3 rem.		
65-60 B	9-13 & A 17-65	L-Los Alamos Scientific Laboratory	0	\$5,400
	Repeated lig	ghtning strikes damaged transformers.		
65-61 B	10-3-65 II	D—Phillips Petroleum Co.	1 injured (Navy)	\$18,540
	over into h	er, attempting to avoid hitting a private can is lane, swerved the bus. It went over an its side. A Navy employee received frac k injury.	embankment and	

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
65-62 B	3-19-65 AL-Dow Chemical Co.	1 exposed	\$1,306
	When a glove failed in a glovebox, releasing p received a lung deposition of $0.042~\mu c$ of plu expected an accrued 12-month exposure of decontamination of facilities.	tonium, from which is	
65-63 B	May 65 OR-Puerto Rico Nuclear Center	1 exposed	0
	During the construction of a room adjoining received an estimated external whole-body cumul of 7.5 rem.		
65-64 B	11-23-65 SR-E. I. du Pont de Nemours & Co.	0	\$19,500
	A cooling coil in a vessel developed a leak and solution from a tank to enter the cooling water spressurized. The cost was for cleaning the system	ystem when the coil was	
65-65 B	11-27-65 AL—Dow Chemical Co.	0	\$47,000
	Roofing destroyed by high winds.		
66-1 B	1-5-66 RL—General Electric Co.	0	\$7,200
	An estimated 420 pounds of uranium solution waste through a milling tank overflow, cause normally closed supply line valve.		
66-2 B	1-29/30 SR-E. I. du Pont de Nemours & Co.	0	\$56,000
	Waterlines, draintraps, water-jacketed equipment were frozen when the temperature dropped to 1899.	, and fire sprinkler lines 6°F., the lowest since	
66-3 A	1-12-66 SNPO-Pan American World Airways	1 fatality	0
	An employee died of third-degree burns over 1009 the result of inadvertent ignition of gasoline and in preparation for disposal in a burn pit.		
66-4 A	1-11-66 NV—Reynolds Electrical & Engineering Inc.	g Co., 1 fatality	0
	A miner died thirteen days after being struck on falling rock. His death was caused by respiratory myelitis of the cervical cord caused by the injury.	failure due to transverse	
66-5 B	1-21-66 RL-Douglas United Nuclear	0	\$52,449
	A furnace explosion occurred in a boiler during response capability of the combustion control fuel-air ratio during changing boiler loads. Odistortion to the boiler's refractories and exteri Tests were being conducted because of a previou 65-32-B).	s to maintain a proper Considerable stress and for case were sustained.	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
66-6 B	2-2-66	CH-Atomics International	1 exposed	0
	transfer tu	byee picked up an irradiated fuel sample innel. The radiation exposure, estimated at a fithe middle phalanx of the fingers of the left	58 rem, occurred to	
66-7 A	2-14-66	OR-National Lead Co. of Ohio	1 injured	\$294,826
	when an of 10-ton cy was neglighospitalized inhalation significant	of uranium hexafluoride, estimated at 3,3 operator inadvertently unscrewed the valve folinder during a routine startup operation. It is to be complete, who received an inhalated for six days; other personnel who received exposures were treated at the dispensary radiation exposures. Material loss, \$278,826 pp, \$21,000.	From the head of a Equipment damage tion exposure, was varying degrees of y. There were no	
66-8 B	3-18-66	BH-Brookhaven National Laboratory	0	\$11,600
	explosion liquid hyd	main hydrogen flow through the purificular occurred at the inlet to the adsorber coil. Irogen contents of the chamber were dump safety vent system.	. Immediately, the	
66-9 A	Between 3/25 & 3/28-66	OR-Union Carbide Corp., Nuclear Div. (Operational Incident)	0	\$277,000
		approximately 50,000 pounds of mercury close a valve isolating the temporary support		
66-10 B	3-15-66	SR-E. I. du Pont de Nemours & Co.	1 exposed	0
		yee received an estimated radiation exposure while using a contaminated pipet.	of 29.5 rem to the	
66-11 B	Jan Mar. 66	SAN-Lawrence Radiation Laboratory, Berkeley	2 exposed	0
	during no	nbers of a bubble chamber crew received rmal operations. Their estimated external quexposures were 4.6 and 3 rem.		
66-12 B	4-1-66	SR-E. I. du Pont de Nemours & Co.	0	\$20,049
	A forest fi	ire destroyed 178 acres of pine and hardwood	d trees.	
66-13 B	1-24/ 2-24-66	AL-Los Alamos Scientific Laboratory	1 exposed	0
	radiation	byee received an estimated external whole exposure of 5.1 rem (according to his film baum processing.		

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
66-14 B	4-6-66	NV—Reynolds Electrical & Engineering Co., Inc.	0	\$11,600
		load caused the top section of the mast on a dig the mast.	rill rig to buckle,	
66-15 B	4-17-66	SR-University of Georgia	0	\$6,000
	the ther	ccurred when a drying oven overheated. Faulty mostat sensing element, causing it to indicate an ture and call for additional heat. Damage was origin.	erroneously low	
66-16 B	Jan Mar. 6	SAN—Stanford Linear Accelerator Center	1 exposed	0
	quarterly	uning an RF circulator, an employee received radiation exposure to the left foot of 300 rem 35 kv. There was no evidence of erythema.		
66-17 A	5-1-66	AL-Mason & Hanger-Silas Mason Co., Inc., Burlington, Iowa	1 fatality	0
		loyee died from crushing injuries to chest and lehicle collision while driving a Government-owner		
66-18 B	4-14-66	AL-Sandia Corp. (Bermite Powder Co., subcontractor)	0	\$6,956
	the inhil	oin rocket grains that had been removed from biting process were being processed, a flash fire luminum core rubbing against the propellant.		
66-19 B	4-21/22	NV-EG&G, Inc.	1 exposed	0
	sources.	loyee carried home in his pants pocket four They were on his person about 12 hours. d dose to the skin of the left thigh of 70 rem.	small cobalt 60 He received an	
66-20 A	5-26-66	AL-Chaney & Hope (Ditmars & Boxley, subcontractor)	1 fatality	0
	surfaces	ainters were engaged in spray painting the of a water storage tank, one painter stepped to on the tank top, and fell 35' onto the bottom of	ackward into an	
66-21 B	6-6-66	OR-Union Carbide Corp., Nuclear Div.	0	\$5,500
	to one operatio	of undetermined cause, occurred in a laboratory hood and a section of ductwork because on of a sprinkler head, a fire damper in the exh e protection controls.	of the successful	

No. ¹ - Type ²	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
66-22 B	Apr NV—Lawrence Radiation Laboratory June 66	1 exposed	0
	While participating in the "high-grading," or recradioactive samples from drill cores at post-shot employee received an estimated quarterly radiation exto the left hand.	t drilling sites, an	
66-23 B	5-20-66 SR-E. I. du Pont de Nemours & Co.	0	\$22,600 ⁵
	A weld failure on a container in a gloveport hood partitium gas through a stack to the atmosphere.	permitted release of	
66-24 A	6-24-66 SAN-Lawrence Radiation Laboratory, Berkeley (Halbach & Flynn, subcontraction)	1 fatality ctor)	0
	An employee was killed when the dirt loader he was o and crushed him.	perating overturned	
66-25 A	6-17-66 NY-Government	1 fatality	0
	Two employees were involved in a single-car accident; later as the result of brain and chest injuries; the minor injuries.		
66-26 B	6-27-66 OR—Union Carbide Corp., Nuclear Div.	0	\$40,000
	An explosion (cause undetermined) occurred in a n followed by a lower-intensity explosion in an oil defrom the compressor. Two men five and ten feet from failure of the compressor received no bodily injuries. cost was for the repair of damaged equipment.	emister downstream the point of major	
66-27 B	6-24-66 CH—Argonne National Laboratory	0	\$7,200
	A trailer containing electronic equipment, being mo crane, was dropped. Both the trailer and the equipment		
66-29 B	6-2-66 RL-Isochem, Inc.	0	\$19,746
	During the repair of an air circulation valve, approxing high-level radioactive waste solution were spilled on employees, wearing protective clothing, were sprayed the solution, but were readily decontaminated.	to the floor. Three	
66-30 A	6-10-66 NV—Reynolds Electrical & Engineering Co.	. 1 fatality	0
	An employee died on July 16 of a pulmonary emb complication of injuries (compound fracture of the r of the right shoulder, scalp lacerations) received o bucket fell on him during the filling of sandbags.	right ankle, fracture	
66-32 B	6-5-66 CH-Atomics International	0	\$50,000
	Approximately 21 gallons of sodium leaked from heater and burned. There were no significant expos sodium combustion products, and no significant fallow	ures to the released	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
66-33 B	Apr June (AL-Los Alamos Scientific Laboratory	1 exposed	0
		ployee received an estimated quarterly extended a comparison of 3.4 rem while dissolving samples		
66-34 B	4-15-66	AL-Los Alamos Scientific Laboratory	1 exposed	0
		loyee received an estimated whole-body tritium le loosening flange bolts on a container in a vacu		
66-36 A	9-22-66	AL-Timmons, Butt & Head, Inc. (Ray E. Johnson Co., subcontractor)	1 fatality	0
	The emp	moving a steel stanchion contacted an 11,00 ployee guiding the stanchion into place died a stanchion the electric shock he received.		
66-37 B	9-23-66	RL-Isochem, Inc.	0	\$13,443
	the eleva	n 5 grams of concentrated plutonium nitrate so ator floor when a product receiver assembly over the inner container came off. Cost was for decontainer	verturned and the	
66-38 A	9-23/24	RL-Douglas United Nuclear	0	\$15,904
	river via	mately 100,000 lbs. of sodium dichromate wer a process sewer due to an improperly installed as designed to stop the flow when the storage ta	float mechanism,	
66-39 A	10-12-66	6 AL-J. R. Brennand Construction Co. (Triple A Electric Co., subcontractor)	1 fatality	0
	An elect	rician was electrocuted while working alone on	a transformer.	
66-40 B	7-9-66	NV-Reynolds Electrical & Engineering Co., Inc.	0	\$8,410
		er leaking into the control panel of a generat Wiring insulation ignited, damaging switchgear		
66-41 A	6-6/19-6	6 CH-University of Minnesota	1 exposed	0
		vorking in a linear acceleration facility an empt d a reading of 50 rem whole body.	oloyee's film badge	
66-42 B	7-21/ 10-18	CH—Argonne National Laboratory -66	1 exposed	0
	target 1	ngaged in the removal, repair, maintenance, an manipulators, an employee received an est ody cumulative radiation exposure of 3.2 rem.		

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
66-43 B	10-21-66 AL-Monsanto Research Corp.	0	\$19,100
	An undetermined small quantity of plutonium 238 v double-contained vessel, nearly full of drybox sieved dispersing a quantity of the waste material into the lat		
66-44 B	10-12-66 OR-Goodyear Atomic Corp. (Operational Incident)	0	\$51,745
	A lubricating oil failure occurred in a cell during newslew was probably closed inadvertently. Repair of \$50,925; offstream losses, \$820.		
66-45 B	12-20-66 NV—Reynolds Electrical & Engineering Co Inc. (Operational Incident)	., 0	\$50,000
	Experimental activities created sufficient ground a trailer, containing TV equipment and cables, of combustible shock mounts came to rest against the h gasoline-powered generator. The shock mounts are caught fire.	f its mounts. The ot exhaust pipe of a	
66-46 B	12-9-66 BH—Brookhaven National Laboratory	0	\$8,300
·	A rubber cooling water hose on an experimental causing water to spray on two main magnets. A shacross the bus connections of one of the main magnets from dignited. Most of the damage was charring due to electrical damage was charring due to electrical damage.	ort circuit occurred gnets. Polyethylene lust and water, was	
66-47 B	11-17-66 NV—Reynolds Electrical & Engineering Co Inc.	., 0	\$6,500
	A hydrocrane, mounted on a truck was involved in The driver was unharmed. Truck damage \$3,500; cra		
66-48 A	10-26-66 AL—Sandia Corp. (Operational Incident)	0	\$189,800
	A transport plane crashed and burned at Santa complete loss of cargo, consisting of the last shipn support the rocket eclipse program. The crew escaped	nent of material to	
67-1 B	2-16-67 AL-Monsanto Research Corp. Mound Laboratory, Miamisburg, Ohio	0	\$16,465
	Abandoned storage vessels inside a stainless steel giflushed with 7-9 N nitric acid to recover plutonium operation, the air monitor alarmed, and the odor of detected. Shortly thereafter, a puddle of dark liquid solution) was seen on the floor under the glovebox leaked from one of the storage vessels into the glove onto the floor of the room. Contaminated personnel (three) were readily showering; the cost was for decontamination of the st	nitrate. During this of nitric fumes was (plutonium nitrate a. The solution had box well and thence decontaminated by	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
67-2 B	3-3-67	SR—E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$71,000
	caused th plunger ja	nectioning of the plunger on the upper shield e loss of 3,300 pounds (412 gallons) of lummed and would not return to the latchering pressure.	neavy water. The	
67-4 B & 67-11 B	Jan.– Mar. 67	AL—The Dow Chemical Co., Rocky Flats Division, Golden, Colorado	3 exposed	0
	concrete a three proc shielding plutonium required n The th	ox containing a fluorinator was located in an and water-well neutron shielding. At times it tess technicians to perform work of a routine area. During this period, an excessive a and americium residues contained with noving. The process technicians received estimated extradiation exposures of 3.4, 3.2, and 3.2 rem, residues.	was necessary for e nature inside the accumulation of tin the glovebox ternal whole-body	
67-5 A	3-11-67	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	1 fatality	0
	operations of both the was compactor the train. between conductor The cothat autop	nductor was decapitated and his body mutil- osy was impossible. Since there were no eyew	or was out of sight itching movement ection where the ther movement of lantern was lying d, he found the atted to the extent	
67-6 B	of the acci	ident could not be determined. SAN—University of California, Lawrence Radiation Laboratory, Livermore, Califor	1 exposed	0
	fluorescen aperture a achieved of replaced. ' determine made. This p technician was on, in the machin The ma	technician was making modifications on a race tube. The procedure required starting wand gradually enlarging it until the proper rad on the sample. To accomplish this, the X-raff, the aperture removed, enlarged slight! The machine was then turned on and the expd. This process was repeated until the proper procedure had been carried out several after removing the aperture, noticed that the machine was producing X-ne off and notified his supervisor. Suchine was not equipped with an interlock to the X-ray tube was moved from its normal possearch technician received an estimated radio the right hand. There were no clinical symptems.	new type of X-ray with a very small iation pattern was y tube power was y by filing, and posure pattern was er adjustment was times when the he red X-ray light rays. He switched turn the generator sition.	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
67-7 B	3-15/20	SAN—University of California, Lawrence Radiation Laboratory, Livermore, Califo	0 ornia	0
	curies) wa destination Evidence disengage,	ck shipment of a depleted iridium 192 source is found to have above-normal radiation levels in. A spring clip held the source in position indicates that a jolt during shipping can permitting the source to be displaced to an unvibrations while in transit.	upon arrival at its in the container. used the clip to	
67-8 A	4-5-67	AL-The Dow Chemical Co., Rocky Flats Division, Golden, Colorado	1 fatality	0
	standing of radiator, h the tractor	byee was servicing a tractor mounted on on the tractor track. As he stepped back for the fell approximately seven feet to the ground or or the lowboy, and landed on his hands an imployee who came to his assistance that his	rom checking the 1, without striking d left hip. He told	
	The em he had su and it app blood pres	aployee was taken to the hospital where it was stained a fractured femur. Corrective surger eared that he would have an uneventful reco- ssure began dropping and on the fifth day he pulmonary embolism secondary to injury	ry was performed very; however, his died. The cause of	
67-9 B	4-10-67	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	1 exposed	0
	was to int After irra discharged water leve resulted in tube in su back throu wire with protected The rea	was being irradiated to determine the flux paroduce the wire into the reactor through standiation, it was withdrawn by the drive through a tube ending six feet under the el. On this occasion, malfunction of the a portion of the irradiated wire being caught a way that it could be removed only by rugh the drive mechanism box. The reactor for one hand and coiled it with the other, from contamination by two pairs of rubber glactor foreman received an estimated radiation of the hands. There were no clinical symptoms	inless steel tubing. mechanism and disassembly basin drive mechanism ht in the discharge manually pulling it oreman pulled the His hands were loves. n exposure of 250	
67-10 A	4-14-67	RL-J. A. Jones Construction Co. Richland, Washington	1 fatality	0
	back towaline" throbegan to equipment and croud and should	cess of moving a motor crane, an equipment and the clamshell bucket, was pulling the slaugh the bucket sheaves and roller. As the topple, another crew member yelled a warr toperator, instead of jumping aside, put his hed down. The overturning assembly struck der, driving him to the ground, the arm of the oss his chest.	ck in the "closing bucket assembly ning; however, the nand over his head thim on the neck	

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
67-10 A— Cont.	Although the victim was given mouth-to-mouth cardiac massage, closed chest, he was pronounced dead of a doctor. The cause of death was ruptured aorta at pulmonary emphysema bilateral.	upon the arrival	
67-12 B	Jan AL—The Dow Chemical Co., Rocky Flats Mar. 67 Division, Golden, Colorado	1 exposed	0
	A process operator performed routine work in a pluto foundry. Two factors created high exposure potentials: belt conveyor system was replaced by an improvised system, making it necessary for the employee to be plutonium charges and castings along a glovebox line, abnormally high amounts of material containing americant the process operator received an estimated extequarterly radiation exposure of 3.2 rem.	1) an inoperative chain conveyor andpass massive and 2) handling um-241.	
67-13 A	4-10-67 AL-Sandia Corp., Albuquerque, New Mexico	1 fatality	0
	A painter was applying clear wood sealer to the sloping a missile shelter. He had finished all but a small portion the roof, which was 14 feet high at the eave edge. Appar onto a freshly sprayed area since there were footman sealer on the concrete floor slab which extended 30 in eave line. Those coming to his assistance found him lyin the concrete and the remainder of his body on the groun. The painter died six days later of a fat embolism pelvis and arm.	n when he fell off ently, he stepped iks smeared with niches beyond the g with his feet on ad.	
67-14 B	4-4-67 SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$11,0005
٧	During welding operations, an electric welder malfunctifailure of a seal tube which resulted in the release of tritistack to the atmosphere.		
67-15 B	3-12-67 NV-Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	0	\$65,000
	A fire occurred in an electronics equipment storage both the equipment and the trailer. The fire is believ caused by a heater overheating when a circulating fan sta	red to have been	
67-16 B	5-5-67 AL—Mason & Hanger-Silas Mason Co., Inc. Amarillo, Texas	0	\$594
	An AEC-owned truck, transporting 1,800 pounds of which was radioactive material, was involved in an privately-owned passenger car. The two couriers in the truck were not injured. I privately-owned car, its sole passenger, was only slight was no damage to the cargo. The cost was for truck repa	accident with a The driver of the ly injured. There	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
67-17 B	6-14-67	BH-Brookhaven National Laboratory Upton, New York	0	\$10,600
	moved. shackled slings ha	de Graaff accelerating tube, in its positioning Four slings were attached and those on eithe together. Later, two employees, unaware to d not been lashed together, proceeded with the s cradle, fell 15 feet to the floor, and was damage	r side of the tube that the shackled lift. The tube slid	
67-18 A	5-25-67	SNPO-C-Westinghouse Astronuclear Laboratory, Astronuclear Core Operation Cheswick, Pennsylvania	1 fatality ons,	0
	employe catch it. articles retrieve into the (exclude Resus	ician working on a leaching furnace platform of the to throw him a brush to clean the platform. Later, he handed another employee a rod us from the furnace. It was surmised from this the brush with the rod and, this failing, that furnace annulus and was overcome by the d by argon gas) before he could climb out. Socitation efforts were made; however, there was soffice gave the cause of death as asphyxiation.	m, but he did not sed for retrieving that he tried to he climbed down to lack of oxygen so no response. The	
67-19 B	6-2-67	AL—Mason & Hanger-Silas Mason Co., Inc. Burlington, Iowa	0	\$50,000
	22 poun immedia from the was the	he remotely-controlled operation of a 20-inched of high explosives detonated, causing seve te area, with nearby areas receiving moderate se blast and/or flying missiles. The probable caushearing or frictional action of high explosives the press.	re damage to the superficial damage use of the incident	
67-20 A	6-9-67	SAN—University of California, Lawrence Radiation Laboratory, Livermore, Califo		0
	lane as h and felt He and a it to see the truck It wa contact He d diagnose	ling to the scene of a grass fire, a police officer, he passed a pickup truck, heard a crash and the san impact. He immediately stopped the police a fireman, who had seen the police car stop and what the policeman wanted, found a second fire, badly injured. Is not known what caused the second firem with the police car. Itied in the hospital about an hour later. It das a basal skull fracture and a broken necker consisted only of a shattered windshield and re-	shattering of glass, e car and got out. was going toward reman lying under an to come into His injuries were c. Damage to the	
67-21 B	5-14-67	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$49,179
	for the	tive liquid waste was stored in an underground to concentrate entered the storage tank through g from the top of the tank to approximate to the control of the tank to approximate the control of the con	a shielded riser,	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
67-21 B- Cont.	pipe entervalve near concentrate forced its vapprox were release concentrate	and. Access plugs were sealed with mastic competed the riser horizontally below ground and to the center of the riser. When the riser became crystals below the inlet line, the liquid floway through the access plugs. Imately 13 curies of radioactive liquid waste, a sed to plant streams but sampling showed to plant streams but sampling showed to standards were not exceeded in streams but cost was for decontamination of ground	erminated with a me plugged with ow reversed and primarily cesium, hat radioactivity beyond the plant	
67-22 B	6-8-67	SAN—Stanford Linear Accelerator Center Stanford, California	0	\$17,211
		neter magnet was severely damaged by overheunit was inadvertently connected to the wron		
67-23 A	6-21-67	RL—General Electric Co., Richland, Washington	0	\$185,000
	coolant pubeing inad normally o closed the although s	curred in the heat exchanger cell of a reactory curred in the heat exchanger cell of a reactory curred in the following oil, source of fuel for the following the return line was not reopened previous day. The exact source of ignition was everal possibilities were considered. Damage with of the cell area, with some smoke damage year.	ire, ignited after ent area when a after having been a not determined, was confined to a	
67-24 A	6-30-67	NV—Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	2 fatalities	\$40,000
	deep, an u shaft in ex to stop or asphyxiatin The exc of materia	e preparation of a cavity at the bottom of a nexpected surge of water and muck (broken accessive volume. The men and equipment avair control the surge until it had run its coung one miner. cess muck covered the weep (drain) pipes with 1. Without being able to pump the water or drowned a second miner.	rock) entered the lable were unable rse, burying and h about four feet	
67-25 A	7-8-67	NV-Holmes & Narver, Inc., Johnston Atoll, Hawaii	1 fatality	0
	which were Employee Employee needed, the Employee floor. His shelving.	byees were retrieving the last two doors from a re stored vertically with the last door leaning. A raised the doors to an upright position, on B steadied them. As Employee A started to the doors suddenly shifted off balance and to B, crushing his head against shelving behind he hard hat was found wedged between the cause of death was anoxia, stagnant, due the ge and multiple skull fractures.	g against a wall. e at a time, while remove the doors oppled over onto im. He fell to the e doors and the	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
67-27 A	7-17-67	ID-Howard S. Wright & Associates, Idaho Falls, Idaho	1 fatality	0
	as a rad provided horizont walers as support. on a rib. right had landing for the complete approximation of the complete appro	struction of a reactor ring (a concrete wall to iation shield) was in progress. Although are, a carpenter elected to climb down into al ribs, spaced 12 inches apart, as "ladder rung se "handrails." He placed his hands on the to His partner stated that he believed the carp. When this happened, the waler (not securely and moved. He instantly let go and fell, appeared downward. Carpenter was conscious when reached by compared the paralyzed from the neck down. He dinately 36 hours later as the result of the murd injury received.	the ring, using the gs," and the vertical p of the walers for enter's foot slipped fastened) under his roximately 15 feet, o-workers, although led in the hospital	
67-28 B	6-22-67	AL-The Bendix Corp., Kansas City, Missou	nri 0	\$11,575
	caused a	e of voltage control equipment at the mun n overvoltage, resulting in the damage or dest nt at the contractor's plant.		
67-29 B	6-9-67	NV-Reynolds Electrical & Engineering Co. Inc., Mercury, Nevada	, 0	\$17,700
	attempts	er portion of the upper section of a drill rig n were being made to free a drilling assembly l 2,180 feet, with the top portion at approxim	odged in a hole at a	
67-30 B	7-1-67	SR—E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$7,500
	in an ele	electrical connection, or similar fault, is believectrical arc, causing the wiring and control during to be charred and burned beyon	evices within an air	
67-31 B	6-18-67	SR—E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$22,000
	plant, the displaced were in determination	periodic inspection of a high-pressure tower ne bottom 21 trays were found to be dar d completely and had fallen to the bottom of place but bent downward. The cause of the ded but it was known that several steps ory to hydrostatic testing were performed.	maged. Some were f the tower. Others ne damage was not in the procedure	
67-32 B	Apr June (AL—The Dow Chemical Co., Rocky Flats Division, Golden, Colorado	3 exposed	0
	glovebox three en	erforming their routine duties, one on an ax, one in a fluorinator area, and one in an ox mployees received estimated external what exposures of 3.7, 3.4, and 3.1 rem, respective	kide dissolving area, ole-body quarterly	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
67-34 B	July- AL Aug. 67	University of California, Los Alamos Scientific Laboratory, Los Alamos, New Mexico	1 exposed	0
	100-curie) from ethods, become received an estrunk, head, a	helped unload cobalt-60 sources (two mashipping cask. Although using ause of inadequate shielding and distantimated external quarterly radiation exposent eyes of 5.9 rem. The bulk of the dost lder and by the right side of the head.	remote-handling ce, the employee sure to part of the	
67-35 B	8-22-67 RL	—Battelle Memorial Institute, Pacific Northwest Laboratory, Richland, Washi	0 ngton	\$9,800
	caught on a condoor to the washing deviced	craneway door, hinged at the top, was rane which had been parked too close. The vinch broke under the extra strain and, size, the heavy door slammed shut. The location crane door and crane hoist motor.	ne cables from the ince there was no	
67-36 A	9-3-67 AL	-Mason & Hanger-Silas Mason Co., Inc. Amarillo, Texas	0	\$1,872,000
	per hour and other structu	and hailstorm, with winds in the range of hailstones the size of oranges, caused e ral damage to numerous buildings, di warehouse wall, leveled security fencing, e.	xtensive roof and isrupted utilities,	
67-37 B	6-5-67 NV	-Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	0	\$14,756
	line in a hois heater and wa operating and	hreaded brass fitting permitted oil to leak thouse. The oil dropped onto a hotplate is ignited. The major portion of the damag d control system. Damage to the hois partially melted fiberglass insulation facin	e and/or portable se was to the hoist sthouse consisted	
67-38 B	9-15-67 AL	-The Bendix Corp., Kansas City, Missouri	0	\$13,590
	apparatus was	malfunction occurred while a special being tested, destroying the apparatus. Aln, no specific condition was found while incident.	though numerous	
67-40 B	July- AL Sept. 67	The Dow Chemical Co., Rocky FlatsDivision, Golden, Colorado	7 exposed	0
	plutonium wa contained 11 from decay processed in a however, soon reported high	uranium-plutonium-molybdenum alloy is used in reactor fuel element fabricatio .5% plutonium-240, 1.4% plutonium-24 of the latter. It was expected that the about the same manner as normal pluto a after volume production of castings was gamma readings. Swipes taken from the radioactivity had an americium content a	n. The plutonium 1, and americium e alloy could be nium production; reached, monitors glovebox bottom	

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
67-40 B Cont.	parts per million. Investigation revealed that temperature of 1275 degrees centigrade was sele americium which coalesced on molds and crucible su operations, such as removing castings from americium-rich particulates throughout the glovebox. employees performing routine duties received unexy radiation. The seventh exposure occurred in the fluor chemical recovery operations where the neutron back high. The six employees received estimated whole-body exposures of 3.8, 3.4, 3.3, 3.1, 3.1, and 3.1 rem, reseventh 3.4 rem.	ctively volatilizing arfaces. Subsequent molds, scattered Because of this, six pected amounts of ination area of the ground is normally quarterly radiation	
67-41 B	8-10-67 NV-Holmes & Narver, Inc., Amchitka, Alas Strong winds demolished a house trailer.	ska 0	\$6,500
67-42 B	8-11-67 NV—Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	, 0	\$8,000
	While "walking" a backhoe up a hill, the operator los to the malfunction of the braking mechanism. The backwards, rolled down a 50-foot embankment, to times, and was demolished. The operator jumped obackhoe went over the embankment.	backhoe, traveling arning over several	
67-43 B	11-14-67 RL—Atlantic Richfield Hanford Co. Richland, Washington	1 exposed	0
	An employee, wearing protective clothing, used extermost of the steps for taking a sample of highly radioa tank; however, he screwed the caps on the shielded hand. The presence of high-level contamination on the sleeve of the employee's coverall went undetected for exact manner in which the cuff became contaminate determined. The employee received an estimated exposure of 3 wrist.	sample carriers by the cuff of the right or 44 minutes. The ated could not be	
67-44 B	11-17-67 RL-ITT Federal Support Services, Inc. Richland, Washington	0	\$5,124
	A diesel locomotive collided with a cask car during codue to the inattention of the diesel's engineer. The cothe locomotive; the cask car was not damaged. A sw minor injury (knee cut) when he was thrown against door at the time of impact.	st was for repairing itchman received a	
67-45 B	11-16-67 RL—Battelle Memorial Institute, Pacific Northwest Laboratory, Richland, Wash	0 nington	\$25,000
	During a test to simulate sudden loss of reactor cooland vessel shifted, causing damage to structural suinstrumentation, and miscellaneous auxiliary equipmersulted from inadequate design of structural supports.	ipports, catwalks, nent. The accident	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
67-46 B	9-29-67	AL—The Dow Chemical Co., Rocky Flats Division, Golden, Colorado	0	\$10,246
	removed of the p to the v storage level of rubber rubber area.	e automatic stabilization process (ASP) equipmed from a drybox system. Prior to a paint spraying biping was to be removed, except the main supply arious levels of the ASP box and the main drain tank. By mistake, a section of the supply line lead the box was removed. The end of the pipe was stopper and taped. When the spraying proceeding blew out, releasing contaminated liquid in amination was confined to the drybox area; the mination.	g procedure, all headers leading line back to the ing to the upper plugged with a lure began, the to the adjacent	
67-47 B	10-1/11 15-67	- SR–E. I. du Pont de Nemours & Co. Aiken, South Carolina	1 exposed	0
	in a dive housing the quar where ex The	erforming routine maintenance duties, such as re- ersion box, removing scaffolding from a "hot" shot cable on a "hot" crane, a rigger received an expo- reterly limits. Since the rigger's duties took him in exposure was possible, its source could not be pinput rigger received an estimated quarterly skin exposure 10.8 rem.	p, and replacing sure in excess of ato several areas ointed.	
67-48 B	11-12-6	7 NV-Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	0	\$18,535
		of a hydraulic lifting ram caused a drill rig mast t t and other parts of the drill rig.	o fall, damaging	
67-49 B	11-26-6	7 SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$24,000
		of a nylon tube (installed for test purposes on a lug in a reactor) led to a loss of 1,600 pounds of h		
67-50 B	12-24-6	7 BH—Brookhaven National Laboratory Upton, New York	0	\$15,000
	trailer	probably originating in electric wiring, occurred in of a 30-inch bubble chamber facility. The ced piping and wiring were damaged.		
67-51 B	12-9-67	SAN-Gulf General Atomic Inc., San Diego, California	0	\$10,563
	was con unit, al	of electrical origin occurred in an instrumentation occurrated in the upper right hand area of the heal though instrumentation and data acquisition and to heat and heavy smoke damage.	ting and cooling	

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
67-52 B	Dec. 67 SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	4 exposed	0
	Shortly after beginning curium solution proceduce became abnormally high at the glovebox contains pumps and continued to rise. The next day, one can leak and preventive maintenance was started. Start containing two inches of lead, was installed at the reduce body exposure. Several hours after the replaced, a leak was observed at a connector in the was replaced and the leak stopped. The greate exposures received by four employees was attributed at the replacement and repair. The four employees received estimated hand one 28 rem to the right hand and 75 rem to the left hand.	sing the solvent recycle of the pumps developed Supplemental shielding, face of the glovebox to be defective pump was the new pump. The line of the hand butable to their taking of the recycle pumps.	
67-53 B	12-14-67 NV-Government	0	\$37,067
	Cargo (drilling equipment) on board a barge begulf of Alaska, was lost during a storm involving and 8-to-12-feet-high waves.		
67-56 B	10-15-67 SAN-Atomics International, Canoga Pa California	ark, 0	\$8,478
	A series of offsite brush fires damaged materials	in a salvage yard onsite.	
68-1 B	1-10-68 AL-Mason & Hanger-Silas Mason Co., I Amarillo, Texas	nc. 0	\$57,763
	Chemical high explosives (16.5 pound remotely-controlled pressing operations. The explained to ignition temperature either by being pile metal surfaces or by heat resulting from friction labeled Light fixtures, hoists, air-conditioning ductword of building were damaged or blown away.	plosives were probably nched between moving between metal surfaces.	
68-2 B	1-11-68 SNPO—C—Westinghouse Astronuclear Laboratory, Pittsburgh, Pennsylvan	0 nia	\$48,810
	An electrical fault resulted in arcing and burnth spacer ring. This permitted the escape of hot gas combustible material in the test cell. Damage cor of the test cell expandable walls and roof beam electrical control, and pneumatic transmission line pieces of various test support equipment.	which ignited adjacent nsisted of the total loss is, some loss of power,	
68-3 B	2-9-68 CH-Argonne National Laboratory, Idal Idaho	ho Falls, 0	\$24,191
	During the replacement of a valve in the second system, a "freeze seal" failed, releasing approximations sodium in a reactor facility boiler plant controccurred about 20 minutes after a fan, used to between the open pipe and flowing sodium, he	simately 80 gallons of rol room. The release maintain a freeze seal	

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
68-3 B— Cont.	permit welding the replacement valve. The sodium, is pressure of approximately 13.5 pounds per square temperature of 509 degrees Fahrenheit, streamed out of body, and almost immediately ignited. Portions of the error were either destroyed or severely damaged by the also smoke and heat damage to the remaining equipment the ceiling and walls. The three men working on the replacement of the minor burns. The cost was for cleaning, repairing equipment.	inch and at a f the open valve equipment in the efire. There was ent, as well as to	
68-4 B	1-12/13-68 SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$11,823
	A loss of 550 pounds of heavy water occurred because connection was not sufficiently tight for pressure operations.		
68-5 B	2-17-68 NV—Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	0	\$11,970
	During truck transportation, a vacuum circulation pun when the chains holding it came loose, allowing it to fa which was traveling over a rough road.		
68-6 B	1-25-68 NV-Holmes & Narver, Inc., Amchitka, Alaska	. 0	\$14,428
	A crane was damaged when it overturned while lifting its 70-ton maximum capacity.	a load exceeding	
68-7 B	3-4-68 ID-Idaho Nuclear Corp., Idaho Falls, Idaho	0	\$1,300
	Equipment was removed from a railroad car and transfer trucks to a warehouse. Almost four weeks later, it was the equipment was contaminated. The contamination was confined to the warehouse, the trackside unloading car washing site, and the two onsite trucks. The decontamination of these areas. There was no personne	s discovered that (uranium oxide) area, the railroad e cost was for	
68-8 B	3-13-68 RL—Battelle Memorial Institute, Pacific Northwest Laboratory, Richland, Washin	0 gton	\$34,000
	An electrical short circuit and the resulting power electrical switchgear damaged two breakers extensively went out and the building ventilation stopped, all per the building, and the emergency crew went into ac necessary steps to preclude any contamination spread. curtailed for two and one-half days while repairs were be	When the lights sonnel evacuated tion, taking the Operations were	
68-9 B	3-24-68 SNR—General Electric Co., Knolls Atomic Pov Laboratory, Schenectady, New York	wer 0	\$25,200
	Approximately 9,400 square feet of plastic covering damaged by ice formation and high winds.	equipment were	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
68-10 B	4-1-68	AL-Sandia Corp., Albuquerque, New Mexico	0	\$9,707
	arcing resultin breaker	trical fault occurred in a motor control center, cau between the bus-bars and conductors inside t g in the destruction of the 1,600-, 1,000-, a sections of the center and heat and smoke ng 19 sections.	he center, and nd 300-ampere	
68-11 B	4-3-68	AL—Monsanto Research Corp., Mound Laboratory, Miamisburg, Ohio	2 exposed	\$41,881
	and one others, minor I knocked explosion being docontrol cutoff. The system respirate However (.295 µc.	box drying oven explosion blew out plastic shield e-half inches thick) on four gloveboxes, ruptured and broke or displaced ceiling panels. Flying lacerations, abrasions, and contusions on three do their respirators off or out of position. The on was the ignition of the flammable vapors entried within the oven, which overheated when to contacts stuck. The oven did not have a high-ten the three injured employees received plutonium or had been knocked off or out of position by the or, only two received lung burdens in excess of the december of the contacts of the contacts of the contacts and the contacts of the contac	I fronts of four debris inflicted employees and e cause of the litted by gloves he temperature perature safety -238 lung and on after their the explosion. 016 microcurie	
68-12 B	Jan Mar.	SAN—University of California, Lawrence 88 Radiation Laboratory, Berkeley, Californi	1 exposed	0
	five cur leader of internal reduce group le and corn He r	a series of experiments involving an atomic beam ies of cesium-137 were deposited in the machine inchecked the machine's vacuum system and decolead shield, which was replaced by a brass-clad outgassing from the lead. During a subsequent exader spent considerable time around the machine rect a small but persistent leak in the vacuum system eceived an estimated external whole-body quarterle cording to his film badges.	nterior. A group ntaminated the l lead shield to experiment, the trying to locate em.	
68-13 B	Jan Mar.	OR-Union Carbide Corp., Nuclear Division Paducah Gaseous Diffusion Plant Paducah, Kentucky	2 exposed	0
	uranium to preve drain pa proximi	after the start of a program to wash 80 cylin residue, it became apparent that additional shield ent splashing and to reduce beta radiation from thans. While installing the shielding, two mechanicity to the residue and received estimated quarterly to the skin of 36 rem and 24 rem, respectively.	ling was needed e surface of the s came in close	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
68-15 B	3-8-68	SNPO-N-University of California, Los Alamos Scientific Laboratory, Jackass Flats, Nevada	0	\$9,911
	flatcar c avoid co The derailed and load	n diesel electric locomotive lost braking traction verrying a 50-ton load. The locomotive was purposellision with another locomotive. two operators, who jumped from the locomotive, received only minor injuries. The derailed locomotive disustained little damage; however, portions of the verely damaged.	ely derailed to before it was notive, flatcar,	
68-16 B	1-24-68	OR—The Rust Engineering Co., Oak Ridge, Tennessee	0	\$5,005
	the ancl	hydraulically-controlled crane gantry was lowered nor pin holes failed to align, although the indicate wed that the pins were in place. The boom was dant four feet onto a railroad track.	or in the crane	
68-17 B	4-29-68	NV—Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	0	\$30,000
		wo diagonal braces failed from overstress, a drill a damaging the mast and the carrier.	rig mast broke	
68-18 B	Mar. 68	NY-Government	l exposed	0
	which fi 50-million screwcay the pipe conical paper or placed of the radia The	a three-day period, an employee was engaged in earliter papers were electrostatically discharged by pourie strontium titanate source contained in a vertipp closure. With the cap removed, the source was been at a position such that beta rays were emitted pattern. Periodically, the employee, using forceps, in the source and, after a short interval, retrieved it for retrieved a filter paper, the upper part of his boation field for two or three seconds. employee received an external beta ray exposure in, as indicated by his film badge.	lacement on a cal pipe with a low the top of l upward in a placed a filter. Each time he dy was within	
68-19 B	6-23-68	BH-Brookhaven National Laboratory Upton, New York	0	\$12,000
		tive transformer joint overheated, resulting in fire ver supply transformer and burned the insulation an		
68-20 B	6-20-68	AL-Sandia Corp., Albuquerque, New Mexico	0	\$55,673
	semitrail caught f mountai The con	outer and electronic test equipment were loaded in ler van as a part of its cargo. En route, the right fire because of the excessive amount of braking a in road, igniting the wooden floor and plywood w inputer and equipment were damaged; however, so ble and is back in service.	rear dual tires necessary on a alls of the van.	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
68-21 B	6-7-68	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$11,500 ⁵
		welding operations, the failure of a seal tub of tritium gas through a stack to the atmosphere.		
68-22 B	6-22-68	RL-Douglas United Nuclear, Inc. Richland, Washington	0	\$66,000
	the cood determine had becontaining	or was scrammed by a flow monitor which sholing water in one process tube. Subsequented that a temperature sensing bulb from a temporary process to the subsequence of the process of the sensing slightly enriched uranium, and that cooling appletely blocked.	ent investigation perature detector to a process tube	
68-23 A	8-17-68	OR-Mid-South Pavers, Inc., Oak Ridge, Tennessee	1 fatality	0
	from the back an approximate the to death known nights were back as the back and the back are to be a second to	road grader operator became conscious of a che exhaust of a road roller following at some did saw the roller at the edge of the road tilternately 45 degrees. The driver was standing up path of the rotating machine, which rolled over the actual accident cause was not determined that the operator had been losing sleep becarith a hospitalized member of the family, and it e dozed momentarily.	stance, he looked ed to an angle of and then jumped and crushed him d; however, it was suse of sitting up	
68-24 A	8-19-68	RL—Hatch Drilling Co., Richland, Washington (subcontractor to J. A. Jones Construction)		\$1,720
	upward, When t disappea Resci about ei	a drilling operation, a cave-in began below grou carrying the driller's helper into the hole in an the driller rushed to the hole, the helper tred beneath a crater 15 deep wide and six feet one operations were started immediately. The light hours later at the 22-foot level, head down death by asphyxia.	upright position. had completely leep. body was located	
68-25 B	8-16-68	RL-Battelle Memorial Institute, Pacific Northwest Laboratory, Richland, Washi	0 ngton	\$7,170
	primary followin adjustmo plastic v	water (approximately 5,500 pounds) leaked system when, in returning the system's gas preg repair work, an operator made an error in the ent. The water leaked out of an opening tempowhile a permanent blank was being fabricated. The water was recovered, it was degraded.	ssurizer to normal sequence of valve orarily sealed with	
68-26 B	7-22-68	AL-Monsanto Research Corp., Mound Laboratory, Miamisburg, Ohio	1 exposed	\$350
	highly c	r research chemist inhaled airborne polonium wontaminated distillate container from a gloveboned how this occurred while he was wearing	ox line. It was not	

No.1 · Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
68-26 B Cont.	expected	The initial uptake was estimated as 2.1 microconto to produce an accrued 12-month dose to Contamination was contained within the laboration	the kidney of	
68-27 B	8-5-68	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$6,445
	cars atta	of a defective part in a railroad switch, a loco ched) was derailed. After traveling 155 feet, in position on the track bed. Both the locomotive.	it stopped in an	
68-28 B	8-6-68	NV-EG&G, Inc., Weapons Test Division, Las Vegas, Nevada	0	\$9,300
	During a equipment	n rainstorm, water flooding into a bunker dar nt.	naged electronic	
68-29 B	8-30-68	ID-Idaho Nuclear Corp., Idaho Falls, Idaho	0	\$6,783
	malfunct the cool subseque the remo	for diesel generator overheated when a cioned. This was specifically due to the accumula lant surge tank float control valve from control failure of the valve. A contributory cause we tote alarm system to indicate the overtempera detected was warpage of the cylinder head valve gaskets and seals. On two later occasions, cracked covered.	ation of debris in prosion and the ras the failure of ture. The initial seat inserts, and	
68-30 B	7-2-68	SAN-University of California, Lawrence Radiation Laboratory, Livermore, California	0 rnia	\$5,904
	transford change b	power supplier rectifier shorted, because of loos mer tap change board, the insulation was ignited. solts and associated wires were destroyed, with and burned carbon deposits throughout the	The transfer tap extensive smoke	
68-32 A	9-4-68	NV-Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	1 exposed	0
	cobalt-60 directly monitor rem righ rem righ	of the physics monitors received hand radiation education of container and its contents when they handle instead of using remote-handling tools as instructed an exposure estimated at 655 rem ± 4 at hand. The second monitor's exposure (23 real thand) did not exceed reportable limits. No clients been observed.	ed the container ructed. The first 5% left hand, 54 em left hand, 10	
68-33 A	11-14-68	NV-Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	1 fatality	\$23,160
	minutes	compressor booster aftercooler ruptured violer after the booster compressor was started and discharge pressure was purposely increased fro	d within seconds	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
68-33 A— Cont.	a valve on of about ignited fir (explosion) caused prinaftercooler aftercooler A mediaftercooler	inch to 1,200 pounds per square inch by the only discharge line. The rupture was a 7,000 pounds per square inch generated by the (explosion) occurring within the after of the explosion of the beautiful by an improperly adjusted lubric at temperature extremes, and overlability. The control of the beautiful by an improperly adjusted lubric at temperature extremes, and overlability. The control of the beautiful by an improperly adjusted lubric at temperature extremes, and overlability is protective grill, and a blast of high-protective grill	caused by a pressure by a spontaneously tercooler. The fire pooster compressor, ator, operating the lubrication of the a section of the	
68-34 A	12-10-68	OR—Union Carbide Corp., Nuclear Divisior Y-12 Plant, Oak Ridge, Tennessee	n 1 exposed	0
	unit had dependence unit was to could be man adjustment turned a collimate turned to immediate! By a to positioning longer that of the expectation of the expectatio	tior to the exposure, the safety interlock been bypassed to facilitate an experie on manual control. While performing a laterned on and off manually three times shade; however, after turning it on the four ent, the unit, operating at 60 kvp and 5 off. Not realizing the unit was on, an experient the beam path and manipulated two restart the unit, he saw that it was by shut it off and reported the incident. The immed observation of several repetitions to operations, the length of the exposure of five seconds; more likely three seconds. A posure was precluded since the beam was entated. Any movement of the fingers thanges of two or three orders of magnitudes of clinical evidence of injury, the exposure 0000 rem to the thumb and index finger.	iment, resulting in a ter experiment, the so that adjustments of the time and making in milliamperes, was erimenter positioned metal shims. As he still operating. He of the collimator-was estimated as no an accurate estimate extremely small and would have caused ade. Since, however,	
68-35 B	11-29-68	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	1 exposed	0
	with a sam in a conta removed, a and survey by plant pl The bo	nance mechanic accidentally punctured his pler needle used for plutonium 238 nitrate minated injury. The mechanic's plastic sure tourniquet was applied to his finger, and red. An estimated 90% of the deposited pluty burden in the employee is estimated at bone exposure in 1969 was 27 rem.	e solutions, resulting uit was immediately I the wound flushed atonium was excised by was instituted.	
68-36 B		ID-Idaho Nuclear Corp., Idaho Falls, Idah		\$20,200
	down and	ion involving the burning of enriched fue examination revealed that a hole approxim had been melted through the first-stag	ately three inches in	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
68-36 B— Cont.	the burner from the bu Removal alpha cont consisted o decontamin According was unaccording.	hroud surrounding the burner. This hole per contents, including uranium-235 and alumentarior. It of insulation without contamination contamination of the chemical engineering of \$13,000 for the loss of the uranium-23: ation. In the period of the uranium inventory studies, 1311 grame counted for following the incident and and repair activity.	nina bed material ntrols resulted in laboratory; costs 5 and \$7,200 for as of uranium-235	
68-37 B	10-14-68 A	AL-The Dow Chemical Co., Rocky Flats Division, Golden, Colorado	1 exposed	0
		ee inhaled plutonium oxide (.02 microcurie drum. His estimated annual exposure to lur		
69-1 A	3-13-69 N	W-Wasatch Electric Co., Salt Lake City, Utah	1 fatality	0
	working or wearing rub the three-pl the linemar tie wire on contact with not protect breaking the ground heart massa the heart-lu	en were standing on an uninsulated aeria a four-wire, three-phase, 4,160-volt symber gloves rated for, and tested for, 10,000 hase conductors had rubber insulating hoses a reached under the crossarm with his right the conductor and the insulator when the his right arm about three inches above his ed by the glove. The other lineman knock e contact with the wire. The aerial platforn immediately and mouth-to-mouth resuscing instituted. After the arrival of the ambuing resuscitator was applied, and cardiac mass with oxygen given for approximately ten representations.	stem. Both were devolutions. Each of a installed. One of arm to place the tie wire came into elbow, which was seed his arm loose, m was lowered to tation and closed lance and doctor, ssage and artificial	
69-2 B	1-8-69 A	AL—Monsanto Research Corp., Mound Laboratory, Miamisburg, Ohio	1 exposed	0
	disconnecte purging gas which becamployees	ntenance work, a pipefitter (without proted a teflon line from a hydrogen fluoride value, contaminated with plutonium 238. The ame contaminated, were readily decont inhaled detectable amounts of plutonium 2 estimated annual lung exposure of 29 rem (.	ve, releasing argon the adjacent areas, aminated. Three 38, one of whom	
69-3 B	Jan F	RL—Battelle Memorial Institute, Pacific Northwest Laboratory, Richland, Washi	0 ngton	\$51,000
	Earth-filled thaws.	dams were washed out as the result of floo	oding during snow	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
69-4 B	3-18-69	NV-EG&G, Las Vegas, Nevada NV-Government AL-University of California, Los Alamos Scientific Laboratory, Los Alamos, New Mexico	0 0 0	\$35,000 \$11,200 \$21,700
	confined there wa	occurring in an electronics laboratory and of mainly to the trailer ceiling in the laboratory s heat and smoke damage throughout the traile mounted to \$11,200; the balance of the cost was nt.	y area; however, r. Damage to the	
69-5 B	2-26-69	NV-Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	0	\$37,000
	A drill ri	g tipped over while the guylines were being tight	ened.	
69-6 B	4-23-69	AL—The Dow Chemical Co., Rocky Flats Division, Golden, Colorado	1 exposed	0
	that he lead to counts of detailed for each carefully body county for the county	ng a minor incident, the body count for an ernad a plutonium-239 lung burden. Additional behowed that the exposure was not of recent of examination of the employee's work history we contamination incident in which he had be examined, all persons who had worked with unt, and his supervisors questioned, there was rewhen the exposure was received. The estimated is .065 microcuries. The annual lung exposure is	ioassays and body origin. Although a as made, crossfiles en involved were him were given a no indication as to amount of Pu in	
69-7 A	5-11-69	AL—The Dow Chemical Co., Rocky Flats Division, Golden, Colorado	1 exposed	\$45,000,000
	nuclear evidence lathe tur and one caused t laminate could ha injuries t .021 mi accumul	refire occurred in a plant which produces plut weapons. The origin of the fire, as indicate, was a glovebox storage cabinet containing pyromings of plutonium pressed into disks three in inch thick. The heat from the burning plutonium he storage cabinet, which was constructed mornaterial and plastic, to char and generate flammate been ignited by burning plutonium. There we from the fire or the firefighting, although one fire crocuries of plutonium, which was expected ative annual dose to the lung of 20 rem.	ted by available ophoric chips and ches in diameter in metal evidently stly of cellulosic hable gases which were no lost-time irefighter inhaled to produce an	
69-9 A	6-10-69	NV-Holmes & Narver, Inc., Las Vegas, Nevada	1 fatality	0
	undergro cables, w the cavit tip and	on were performing survey services in a mind bund. They were working on a platform, sus- within a 20' diameter by 36' high cavity, approxi- by bottom. One cable became detached, causing two of the men to fall to the cavity bottom. The obtail where one was released after examination	pended by four mately 25' above the platform to ey were taken to	

No.1 - Type2	Date Field Office ³ - Contractor Exposures	AEC Property Damage
69-9 A— Cont.	about 39 hours later from severe brain and brain stem injuries and compressed fracture of the skull.	
69-10 A	6-16-69 CH-Schless Construction Co., Batavia, Illinois 1 fatality (subcontractor to Daniel, Urbahn, Seelye, and Fuller)	0
	A carpenter was fatally injured when he fell 11 1/2 feet through a floor opening at the site of a proposed stairwell from which a temporary covering had been removed. No one saw the carpenter or anyone else remove the cover nor did anyone see the carpenter fall. He was found lying on the concrete floor of the basement beneath the opening. The cause of death was a basal skull fracture.	
69-11 B	6-19-69 RL—Battelle Memorial Institute, Pacific 1 exposed Northwest Laboratory, Richland, Washington	0
	Because his attention was distracted, an operator entered an X-ray cubicle while the X-ray machine was on and was exposed to the primary beam. He received an estimated radiation exposure of 12 rem to the eyes and 8 rem to the whole body.	
69-12 A ("A" because of press release)	7-30-69 AL—The Dow Chemical Company, Rocky Flats 0 Division, Golden, Colorado	\$20,000
	Two chemical operators screened plutonium residues from a previous fire, separating the fine material from the larger pieces. The fine material was placed in a can and sealed with plastic tape. The can was then placed inside two plastic bags and transferred to the storage area about 6 p.m. Around 11 p.m., a fire occurred. Friction during the screening or transfer of the residues probably initiated oxidation resulting in the eventual ignition of unstable plutonium compounds and/or plutonium metal fines within the can. The smoke and flame were produced from ignition of the plastic bag containers, the source for the ignition of the bags being the heat from the can containing the burning plutonium. The two chemical operators were found to have inhaled or ingested plutonium (estimated to be from 0.15 to 0.99 microgram*), which was expected to be eliminated by normal body mechanisms.	
	*nonreportable	
69-13 A	8-8-69 RL-Battelle Memorial Institute, Pacific 1 exposed Northwest Laboratory, Richland, Washington	0
	A scientist was accidentally exposed to 8 KeV X-rays from the primary beam of an X-ray diffraction unit when he went behind the machine propped open the port with a piece of lead, and spent approximately fifteen minutes performing various measurements. When he returned to the front of the unit, he noticed X-rays were being counted by the proportional counter and realized the machine had been on when he was behind the unit. The scientist received an estimated dose of 1,700 rem to the fingers of the left hand, 50 rem to the right eye, and 2,400 rem to the skin of the upper left arm.	

No.1 - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
69-14 B	8-9-69	ID-Government	0	\$25
	privately-	transporting two casks of spent reactor fuel- owned car. The right rear mudguard of the the there was no damage to the shipment.		
69-15 B	6-12-69	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$37,506
	by a nor leading from the leading from vehicle level of a All activition.	mately 20 millicuries of airborne radioact curium-244) were released via an exhaust state theasterly wind across the roof of a building from the main entrance of the building to a particular particular on the roof was 4×10^7 les inside the area fence 1.5×10^4 d/m/100 activity outside the area was approximately 5 ty was contained within the plant's boundary were no radiation exposures. The cost was for	ck and were spreading and along a line king lot. d/m/100 cm ² and 0 cm ² . The highest 000 d/m/100 cm ² .	
69-18 A	10-23-69	NV—Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	1 fatality	\$3,500
	accidenta of a 1,04 2-7/8"-di shaft end the shaft his head	th of a radiation instrument technician is a release of a 120-foot section of pipe, which 40-foot shaft, where it violently crumpled upameter pipe crumpled, one large loop of it was closure and into a side station where two me elevator. The loop of pipe struck the technagainst an acetylene bottle with the result that man suffered a minor puncture wound in his wire.	a fell to the bottom con impact. As the as forced out of the on were waiting for nician and knocked at he died instantly.	
69-19 A	12-10-69	NV-Reynolds Electrical and Engineering Co Inc., Las Vegas, Nevada	ö., 1 fatality	0
	heard a n thought ' helper's alongside ostensibly he did so same tin blazed, a actions, powerling only were After helper, h was avail an exame	ig helper was walking near a truck-mounted oise which sounded like air escaping from a ti was hydraulic fluid running out from beneath signal, the truckdriver stopped the truck, die the truck to where the helper was standing to look under the truck for the source of the put his hand against or near a brace on ne, the helper heard a "pop," the left rearm the truckdriver fell over backward. Obtained the truckdriver fell over backward. Obtained the truckdriver fell over backward the contact of the company visible in the wide-open, isolated to working. unsuccessfully attempting to resuscitate the aving no radio, drove approximately one mile able, to summon help. The truckdriver was prining physician while en route to the hospitate of death was cardiac arrest resulting from electric death of the contact of the hospitate of death was cardiac arrest resulting from electric death of the contact of the hospitate of death was cardiac arrest resulting from electric death of the contact of the hospitate of death was cardiac arrest resulting from electric death of the contact of the hospitate of death was cardiac arrest resulting from electric death of the contact of th	re and saw what he he the truck. At the ismounted, walked g, and leaned over, he leaking fluid. As the drill rig. At the retires flashed and viously, from their cted a 34,500-volt area in which they he truckdriver, the le to where a radio ronounced dead by a man ambulance.	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
69-20 A	12-26-69	AL-EG&G, Amarillo, Texas	0	\$200,000
	occurred radioactiv damage w pressuriza well as the adjacent to ther dam pounds, for the different control of the differe	on of approximately 108 pounds of a plastic in a remotely-operated 20-inch diameter in the materials were involved and no one was in the materials were involved and no one was in the materials. The press and other equipment when the roof and blowout wall. The blowout was were extensively damaged. The roofs mage was sustained when fragments, some we call through the roofs. It is interest cause of the accident was that an of the plate," which seals the pressure vessel.	isostatic press. No jured but extensive t in the bay, hoists, ere demolished, as walls and roofs of were damaged and eighing hundreds of	
69-21 B	11-6/7-69	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$32,000
	processed inadverter	aste solution (approximately 8200 pounds) for neptunium-237 and plutonium-238 recontly transferred to an underground waste live in the stream supply to a transfer jet.	very, was lost when	
70-1 A	1-23-70	NV-Reynolds Electrical & Engineering Co. Inc., Mercury, Nevada	, 1 fatality	0
	tender on above the normal procage were then to be who were emerging opening s sitting-like cage was cage tend	ienced miner and cage tender were assigned a two-cage elevator, one cage of which we other. The cage tender had informed the rocedure would be followed and that person to be unloaded first at the lower level and e raised to unload him and the material. Acce waiting for the cage at the lower level, the from the descending lower cage when the top struck his hard hat. The descending cage of the position before the cage could be stopped, then raised by signals to a point level with ler was removed. The autopsy report states and traumatic injuries.	ras rigidly attached top lander that the connel in the upper the lower cage was cording to witnesses the cage tender was p frame of the door crushed him into a After stopping, the the landing and the	
70-2 B	1-16-70	AL-Zia Company, Los Alamos, New Mexic	ю 0	\$28,521
	and load a to the bo	boom on a mobile crane collapsed while being large concrete mass (44,775 lb.) upon a traition, the trailer and the roof of a building updamaged. One person was slightly injured.	ler. Besides damage	
70-3 A	2-2-70	NV-Holmes & Narver, Subcontractor (McKenzie Construction, Inc.) Las Vegas, Nevada	1 fatality	0
	was struc when the	ping unchain a load of pipes from a flatbed to keep the by one or more sections of pipe which re- last chain was released. Three co-workers victim, throwing off the pieces of pipe that	olled off the trailer immediately ran to	

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
70-3 A— Cont.	They determined that he was seriously injured an When the doctor arrived, he pronounced the victim and chest injuries.		
70-4 B	1-8/11-70 SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$38,200
	Water supply lines, drainlines and traps, water-ja heating and coiling coils, instruments, gages, and fire in numerous plant locations during a period temperatures, unusual and unexpected in the area.	sprinkler lines froze	
70-5 B	12-69/ RL-Battelle Memorial Institute, Pacific 3-70 Northwest Laboratory, Richland, Wash	0 hington	0
	During routine sampling of wildlife near the 100-K coat Hanford, waterfowl were found to contain uphosphorous. Analyses indicated that the highest material found in the waterfowl were 0.14 microcur been determined that this resulted from food and reactor cooling water trenches on the project.	nusual amounts of concentrations of ies per gram. It has	
70-6 A	3-10-70 AL—Government	2 fatalities	0
	While traveling on official business in a private airplane employees were killed when the plane crashed.	ne, two Government	
70-7 A	3-28-70 NV—Reynolds Electrical & Engineering Co. Inc., Mercury, Nevada	, 1 fatality	0
	An ambulance was responding to an accident. The firs in the rear of the ambulance preparing equipment for At a speed of over 70 m.p.h., the ambulance developed The driver glanced through the rearview mirror and sitting on the jump seat. A short time later, the driver noise. When he looked again into the rearview mirror falling through the right, rear, side door. It is technician inadvertently released the door lock or the open due to vibration or mechanical failure. His pavement, killing him instantly.	or treating patients. ed a severe shimmy. saw the technician heard an unfamiliar , the technician was presumed that the nat the door sprung	
70-8 A	3-23-70 AL-Sandia Corp., Albuquerque, New Mexi	co 0 (fatality not AEC)	0
	A 13-year-old boy darted across a highway and was ki an automobile driven by a contractor employee.	lled when struck by	
70-9 B	3-22-70 RL-Battelle Memorial Institute, Pacific Northwest Laboratory, Richland, Wasi	0 hington	\$95,000
	An estimated 1,000-curie strontium 90 release of attempted measurement of the liquid level in a strostorage tank. A portable manometer system (tempora for liquid level measurement) was being used du upgrading the normal tank instrumentation. A leak gallery end of a tygon tube to the manometer	ontium 90 product ary instrumentation ring a program of at or near the pipe	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
70-9 B— Cont.	leak in the ty purge air, wh the adjacent solution ente which empti- Radiation lev pipe gallery. strontium 9	elution to be pumped from the storage targen tube by an airlift action created by the ich is expelled through a line deep in the line to which the manometer tube was the pipe gallery floor drain and the into an open ditch leading to an open of 500 rad/hour at three or four into Water samples taken from the pond result of 1.7 x 10 ⁻³ µCi/r and recovery efforts are estimated at \$95,	ank purge air. This e tank, bubbled up as connected. The ne chemical sewer, pen 25-acre pond. ches existed in the ached a maximum nl. The costs of	
70-10 A	4-18-70 RI	—Atlantic Richfield Hanford Co. Richland, Washington	1 exposed	0
	MeV-maximu radioactive v received seve	ee was accidentally exposed to b m) when he attempted to recap the vaste (cerium-144 and promethium-144) re burns due to estimated doses of 2,500 and and 2,000 rem to small areas of the rig	cask from which was flowing. He rem to the fingers	
70-11 A	6-11-70 NV	/-Holmes & Narver, Inc., Johnston Atoll	1 fatality	0
	approximatel	ee was found dead on the bottom y 15 feet of water near the salt water parently drowned while scuba diving. Ressful.	intake of Johnston	
70-12 A	4-9-70 CF	I—National Accelerator Laboratory (Subcontractor - D & E Maintenance) Batavia, Illinois	1 fatality	0
	equipment. joists, partial Styrofoam p carpenter fei Styrofoam approximatel	being converted into a storage space. The second floor level consisted essentilly covered with loose lumber and plywanels had been installed on the undersided from the second floor level through beiling to a concrete surface 9 feet y 11 hours later in the hospital, the cause the emorrhage resulting from the fall.	ally of open floor wood. A ceiling of de of the joists. A a portion of the below. He died	
70-13 A	5-4-70 SF	C–E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$124,523
		ontaining 20 grams of curium-244 and a mistake to the waste system.	americium-243 was	
70-14 B	3-10-70 SF	C–E. I. du Pont de Nemours & Co. Aiken, South Carolina	1 exposed	0
	decontamina waste (curiur rate meter al obtained assi the personne burdens of c	for inadvertently released airborne tion room environment while removing m-244) from the decontamination chamber armed and alerted him to the presence of stance to remove his outer protective cled decontamination room. The operator urium-244 (.6 microcuries, which was exive annual dose to the bone of 90 rem).	g solid radioactive eer. An alpha count f alpha activity. He othing and went to received 6.5 body	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
70-15 B	6-10-70	AL-Los Alamos Scientific Laboratory Los Alamos, New Mexico	0	0
	contamir	r used to transport radioactive material w nated (cobalt-60) in excess of 0.5 mrem/hou I levels up to 21,839 dpm/100 cm ² .		
70-16 B	4-9-70	CH-Argonne National Laboratory, Argonne, Illinois	0	\$59,000
	reactor control blown on throughout The conformal for one s	reactor thru-hole (an experimental tube which pore) was overpressurized, the seal plug in the enut and the loose contamination inside of the tubout the reactor building in the form of a finely tamination was confined to the interior of the small spot on the concrete just outside the from ped and cleaned.	d of the tube was be was distributed y-divided powder. b building, except	
70-17 A	7-25-70	AL-Government	4 injured	*
	skidding clipped a while th	C driver, in an attempt to avoid an unidem vehicle, lost control of his own vehicle during a second oncoming vehicle. The AEC vehicle rate clipped vehicle was struck broadside by a piver was not seriously injured but four othe zed.	a rainstorm, and n off the roadway bickup truck. The	
	*estimate	not received		
70-18 B	6-4-70	AL-Government	0	\$10,000
	a checko set. In the release v	chanics were working in an F-27 cockpit, revvingout procedure. The wheels were in their chock neir operations, one of the mechanics inadverte which caused the plane to jump the chocks. The of the aircraft were seriously damaged.	s with the brakes ntly hit the brake	
70-19 A	7-2-70	NV-Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	1 fatality	\$1,575
	truck wh	loyee was killed when he was thrown from the cich he was driving. Apparently, he lost control of speed and it left the highway and rolled over	of the vehicle at a	
70-20 A	8-24-70	CH-University of Wisconsin, Madison, Wisconsin	1 fatality (non-chargeable)	0
	bomb ex Low-ene was cove the build	cher at the University of Wisconsin was fatall xploded at 3:42 a.m., CST, in the university physics equipment (AEC-owned) was dampered by insurance. Licensed radioactive material ling at the time of the explosion, but there was we material.	y's Sterling Hall. aged but the loss s were on hand in	

No.1 - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
70-21 B	9-8-70	NV-Reynolds Electrical & Engineering Co., Inc., Mercury, Nevada	0	\$40,000
		ng rig was damaged when a bridle (wire line) u e drilling mast broke.	sed to raise and	
70-22 A	8-6-70	SAN—Lawrence Radiation Laboratory Livermore, California	0	\$165,000 ⁵
	discharg radioact vegetatio found e	dental release of tritium occurred when automatied the gas through a 100-foot-high exhaust sivity were found at locations on the site and at the n near Altamont, a few miles from the site. No adsewhere offsite. There were no personnel expression was not contaminated.	tack. Traces of ree locations on activity has been	
70-23 A (press release)	10-1-70	RL—Westinghouse Atomic Development Co. Richland, Washington	0	0
	stack fil none w	erium-cesium contamination resulted from a rou ter in the 300 area. Over 200 employees' shoes w ere found to be contaminated. Walkways and down; no radioactivity was found in surveys b	ere checked and roadways were	
70-24 A	10-7-70	AL-Los Alamos Scientific Laboratory Los Alamos, New Mexico	0	(Loss is classified)
	heat sta (LASL) freezer during Septeml failed to made of and about success, disposal so great	le of radioactive tritiated salt, used as a calorin ndard) in research, was lost at Los Alamos Scien. The sample capsule, enclosed in a plastic bag, with other similar-appearing capsules. It was in an inventory on June 1, 1970, but was reported by 1970, after a routine inventory. An expectation of the commercial salvage yard, the commercial lates out 7,000 cubic feet of the radioactive disposal Despite the fact that the appropriate part of site was excavated and searched, the amount of compared to the size of the cylinder that absolute made that the sample is not in the area.	tific Laboratory was stored in a its proper place red missing on chaustive search rches have been undry facilities, site, all without the radioactive overburden was	
70-25 B	9-9-70	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	1 exposed	0
	removin dose is normal	ployee received a skin exposure of 34.5 rem ig cell covers in a high-level caves section. The probably too high since the technician's TLD backness location under his outer coveralls during the leg near his ankle, very close to the highly-contains the second se	whole-body skin lge fell from the is job, lodging in	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
70-26 B	9-12-70	NY—Plasma Physics Laboratory Princeton, New Jersey	0	\$51,050
	September an attempt the main secondary cubicles. The seconds ker in the 416 three units the 138 ktripped op loss was defined at the seconds was defined at the second sec	ed power outage was conducted at the labor 12, 1970. After completing the scheduled to twas made to restore normal power. Immed 138 kV circuit breaker, a short circuit side of the power system in the 4160. The fault was not cleared by the protective recuit breaker, but rather remained on for affore the breaker was manually opened. The 0-V switchgear cubicle caused the resulting of switchgear. This damage could probable to circuit breaker on the incoming service then to clear the fault condition. Roughly have to replacement costs of the three switchgwas labor cost.	maintenance work, diately after closing occurred on the V circuit breaker relays tripping the approximately 30 electrical flashover fire and damage to y have been less if line had properly alf of the \$51,050	
70-27 A	11-20-70	ID—Arrington Construction Company (lump-sum) Idaho Falls, Idaho	1 fatality (non-chargeable)	0
	was helpin removed for lowered co other end two boom of the fou pins, due	nent operator was killed instantly when a cra g to disassemble dropped and struck him. To rom the crane and half of it was on a truck ampletely to a horizontal position; tielines we of the boom. The worker was removing p sections together at the junction point. Up r pins, the boom sections 'hinged' about to the fact that the boom ends were being sed the boom sections to drop suddenly and	The boom had been to bed, but was not were holding up the ins which held the bon removal of two the remaining two ag supported. This	
70-28 A	11-25-70	HQ/NV—Government/Reynolds Electrical & Engineering Co., Inc.	3 fatalities	0
	two AEC 1 Lake Mead small aircra	k Service plane (operated by a USPS pilot) personnel and a REECo employee to survey I, Nevada area. While flying at low altitude aft was suddenly forced into the water by a , causing the plane to break up on impact a ly survivor.	terrain around the over the lake, the strong down-draft	
70-29 A	11-17 - 11-18- 70	SAN-Lawrence Radiation Laboratory (Sandia Laboratories employee) Livermore, California	1 exposed	0
	1) the left little finge following	sistant received an accidental overexposure thumb (480 rem), 2) the left forefinger (370 er (150 rem) when he handled experin exposure to 23- and 16-MeV alpha partic clotron. No clinically observable damage wohysician.	rem), and 3) right mental Cu targets les from the LRL	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
70-30 A	11-9-70 S	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$511,833
	shutdown assembly w material dro the roor was released functioned	room became contaminated during a rewhen an antimony-beryllium source rod as being lifted out of the reactor by a copped into a pan underneath the crane, relen. Confinement filters contained the radid through the building stack. The reactor cas designed and all radiation was contained to personnel exposures resulted from the incompared to the contained of the contained of the contained to personnel exposures resulted from the incompared to the contained to the	I separated as the trane. Some of the easing radioactivity oactivity and none confinement system I within the reactor	
70-31 B	June- (Nov. 70	OR—Oak Ridge National Laboratory Oak Ridge, Tennessee	1 exposed	0
	during the contaminati employee : requiring o climbing ag radioactive	ee was assigned to the job of loading plutor period of June to November. For ion spread in late June, urine samples showed high initial readings but then nly periodic sampling. When the urine ain in mid-November, the employee was work. It is estimated that he received a of Pu-238 in his lung, resulting in a 75 result	ollowing a minor staken from the dropped to levels levels commenced restricted from all pproximately .072	
71-1 A	1-20-71	AL—Sandia Laboratories	0	<\$100.00
(press release)	upon enrou no damage	arrying a shipment of spent reactor fuel ate to Idaho Falls, Idaho. There were no injust to the shipment, and no release of radioacted as a Type A due to the publicity involved	juries to the drivers, etivity. The incident	
71-2 A	2-4-71	OR-University of Tennessee	1 exposed	0
	inadvertent 8,000-curie The whole-	on of safety interlocks permitted a reserve ly enter a variable-dose-rate irradiation cobalt-60 source was in position to irradiation body exposure was estimated to be 260 reserves estimated to be up to 1,200 reserves.	facility while an diate seed samples. em, while the hand	
71-3 A	2-4-71	SNSO-N–Pan American	1 fatality	0
	pickup true the roadwa the hospita	c-pipefitter was fatally injured when he ck he was driving as it entered a curve. They, rolled over, and threw him from the veril, the victim was pronounced dead due to the provided had not been used.	he vehicle then left chicle. On arrival at	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
71-4 A	2-13-71	AL—Mason & Hanger-Silas Mason (Amarillo)) 1 fatality	0
	apparently	cian, working from a hole-drilling mast, we slipped from the mast and grabbed a hot we loose and he fell to the bed of the truck, strangle iron.	rire. Other workers	
71-5 B	1-20-71	AL—Dow Chemical Co.	1 exposed	0
	container, a	mpt to remove a canned plutonium buttoma process operator was exposed to americal not wearing a respirator and, as a result, I lung burdens.	ium-241. The em-	
71-6 A	3-31-71	RL & ID	0	0 6
(press release)	including experienced Ohio. Invest a dragging but monitor	car loaded with 74 DOT containers of uran seven containers of low enriched uranger of the car enroute from H stigation indicated that the cause of the fire brake shoe. Seven of the containers were a bring revealed no significant readings and that and safety of the public.	ranium elements, anford to Fernald, was sparking from ffected by the fire,	
71-7 B	3-31-71	ORUnion Carbide Nuclear Division	0	\$37,000
	thorium w steam. The	on occurred in an arc melting furnace under water leaked into a melt cup and we re were no overexposures or injuries to personant the furnace; there was no fire or building on.	vas converted into onnel. Damage was	
71-8 B	JanMar. 1971	OR-Union Carbide Corp., Y-12 Plant	1 exposed	0
	approxima during the numerous	quarterly processing of film dosimeters protegy 11 rem. The employee who had we first quarter was a radiographer's aide and radiographic machines during this period mediately to determine which of the radioginvolved.	orn the dosimeter had worked around. Investigation was	
71-9 A (press	5-18-71	ID-Idaho Nuclear Corp.	4 minor exposures	\$2500.00
release)	Engineerin experimen from its	radiation levels prompted an early morning Test Reactor Building when a port t tube, which was being removed from the containment cask and triggered the build our workers received estimated radiation to 4.2 rem.	ion of an in-pile reactor, protruded ling's safety alarm	

No. ¹ - Type ²	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
71-10 A	5-19-71 OR—Goodyear Atomic Corp.	0	\$440,000
	The Portsmouth Gaseous Diffusion Plant experie X-344 Feed Plant when a propane tank ow ruptured. Apparently, a leak developed in the land was ignited by an undetermined source. The of the tank heated the cylinder sufficiently to its contents. Extensive damage occurred to the building. There was one minor injury as a result of	base of the LPG cylinder e resulting fire at the base cause the combustion of e floor and walls of the	
71-11 A	6-13-71 AL-Los Alamos Scientific Lab.	1 fatality	0
	A LASL physicist died in the crash of an Air F Pacific Ocean 700 miles southwest of Haw participating in a DOD data gathering mission classified. The Air Force discontinued its search several days and it was therefore assumed that alkilled.	vaii. The employee was, the nature of which is ch for the wreckage after	
71-12 B	6-15-71 ID—Dow Chemical Co.	0	0
	A fire started in a trailer shipment of drummed a from Dow Rocky Flats to the Idaho Burial extinguished due to lack of oxygen; none of and there was no spread of contamination from drums. Preliminary investigation indicated that ignition were smoking materials and spontaneous material left in the van. No evidence of either a debris. There were no injuries or exposures results.	Ground. The fire self- the drums was breached in the material within the two possible sources of ous ignition of a foreign material was found in the	
71-13 B	6-30-71 SR-E. I. du Pont de Nemours & Co.	1 exposed	0
	A technical assistant at the Savannah River Labor exposure to the tip of his left thumb estimated over one square centimeter. The exposure occu was working with a capillary focus X-ray diffract	to be 175 rem averaged arred while the employee	
71-14 B	7-10-71 NV—Holmes & Narver, Inc. Johnston Atoll	0	\$75,108
	An LCM boat and its cargo being tow Semisopochnoi Island were lost when the LC started taking on more water than the pumps were evacuated and an attempt was made to to Amchitka. When the LCM capsized and the was abandoned.	CM sunk. After the boat so could handle, personnel ow the crippled boat back	
71-15A	7-13-71 AL-Los Alamos Scientific Laborator	ry 0	\$15,774
(press release)	A small amount of plutonium 238 was release the CMR building hot cell laboratory during the SNAP capsule. The escape of material apparent the flexible booting used to seal one of the personnel who were in the area were exa- contamination and inhaled or ingested plutonic that acceptable limits were exceeded.	ne disassembly of a transit tly resulted from a leak in remote manipulators. All mined for residual skin	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
71-16 B	July 1971	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	1 exposed	0
	badges : 23.59 r and nor	otine reading of Health Physics Thermolumin for the month of July 1971, revealed that an elem exposure. Pocket chamber readings, area must work patterns do not indicate that he could be of this magnitude.	mployee received monitor readings,	
71-17 A (press	8-18-71	AL—Mason & Hanger-Silas Mason Co., Inc. Amarillo, Texas	0	\$20,000
release)	occurred in a 50 the maunexpectould letter the mat	losion of approximately 15 pounds of experied in Building 11-17 of the Pantex Plant. The explication of the Pantex Plant is experied in Building 11-17 of the Pantex Plant. The explication of the Pantex Plant is experied in the solution of the produced, its temperature checked. Three technicians realized that the temperature of the determination, and since there were no factorial, they evacuated the building. AEC loss was ding and to equipment. Nonradioactive material	plosion took place s being drawn. As started to rise perature increase cilities for cooling due to damage to	
71-18 A	8-22-71	AL-Dow Chemical Co.	2 exposed	\$70,000
(press release)	containi shelf. The by the respirate	ployees received exposures to the lung when a sing plutonium metal turnings ruptured and fe he exposures estimated at 15 MPLB and 7.4 M inhalation of radioactive particulate prior fors. AEC loss was due to decontamination and which could not be decontaminated.	Il from a storage PLB, were caused to donning their	
71-19 B	7-31-71	NV-Reynolds Electrical & Engineering Co.	0	\$28,000
	suffered	co-37 Drill Rig which was operating at the structural damage to the mast when the capacit d while the rig was pulling on a stuck pipe.		
71-20 A (press	9-16-71	OR—Union Carbide Corporation Nuclear Division	4 hospitalized 8 minor injuries	<\$25,000
release)	ORNL hospital were dis	cooled circuit breaker exploded at the Y-12 and Y-12 employees. Although four of tized, all were doing well 24 hours after the incisengaging the 13.8 kV circuit breaker when it expressional with hot burning oil and metal project.	he injured were ident. Electricians applications,	
71-21 A	10-19-71	CH-Pinner Electric Co.	1 fatality ⁷	0
	when he fell to the	ult of "horseplay," a general electrical foreman e contacted a static wire at the top of a high-t he ground. The incident occurred as the forema ans were returning to work after an extended lur	ension tower and n and three other	
71-22 A	10-21-71	NV—Halliburton	1 fatality	0
	wheel o	nt service employee was crushed while disconn n a cement bin trailer when the trailer shifted be was caught between the trailer and the tractor	l. Apparently the	

No. ¹ - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
71-23 B	9-28-71	AL-Monsanto Research Corp., Mound Lab.	1 exposed	0
	routine was wortempora full-face	n physicist received a lung deposition of plutor changing of a solution mixer motor in a gloveborking in an access corridor behind the glovebry tenting used for the job. He wore a plastic smask. A preliminary lung count indicated the enately 1.6 MPLB of plutonium (24 rem).	x. The employee ox, outside the lit and an Acme	
71-25 B	10-24— 25-71	ID-RL-Aerojet Nuclear Co.	0	\$345
	be conta	n "Rover" cask which was shipped from ID to iminated upon arrival. Preliminary radiation sure of smearable beta-gamma contamination to 3	veys revealed the	
71-26 B	12-03-71	NV-Holmes and Narver, Inc. Johnston Atoll	2 injured	\$92,939
	being lo the doci the supe	hoist was dropped into approximately 35 feet of aded onto a barge when the crane which was on the k tipped over. The crane operator received multivisor suffered a fractured arm and leg. Damag raluated and salvage methods are being considered.	perating close to tiple bruises and e to the crane is	
71-27 A	12-05-71	RL-Atlantic Richfield Hanford Co.	1 fatality	0
	downed Mountai	nant in the security patrol was electrocuted whe power line. The employee had been summoned, which is near the ARHCO site, to investigately the power line's arcing on the ground.	d to Rattlesnake	
71-28 A	12-07-71	SAN-Stanford Linear Accelerator Center	0	\$45,000
(press release)	Accelera oscillato	mbs were detonated in the injector sector of the ator, one in the main trigger generator and or r. There was no damage to the main tunnel ar turn-on should not be affected.	ne in the master	
71-29 B	12-3-71	SR-Government	0	\$96,000
	and wi	vernment pine forest was extensively damaged nd. The property loss is due to damaged trative costs in salvaging the timber as possib	pine trees and	
72-1 B	1-23-72	OR-Government	0	0
	derailed there w	xcars carrying classified material and a dorn at Woodlawn, Illinois. There was no damage to ere no injuries to the escorts. The cargo wa ent cars, inspected and continued enroute two d	AEC cargo and stransferred to	

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
72-4 A	2-8-72 AL—Dow Chemical Co.	0	\$20,000
(press release)	A small explosion occurred in the incinerator glove employee punctured an aerosol can of spray adhesive material being sorted. The pressure buildup in the line bag and the inlet filter thus permitting the relection contamination. The explosion also caused a small combustibles within the line which was extinguactivation of a fixed CO ₂ extinguisher system. Whole on a number of employees indicate no exposures above	blew off a take-out ease of radioactive fire in the sorted uished quickly by body counts taken	
72-5 A	2-14-72 NV—Government	0	0
(press release)	A railroad shipment from Hattiesburg, Miss. to the found to be slightly contaminated upon arrival at t Base, Nev. The contamination was due to a small supposedly empty tanks. A small amount of conta onto the wooden planks of the railroad car. The maxin in contact with the wooden planks was 0.4 mrem/hr. release posed no danger to the public.	he Nellis Air Force eak in one of two minated liquid fell mum radiation level	
72-7 A	3-3-72 SNR-General Electric Co., Knolls Atomic Power Lab., Schenectady, N.Y.	1 fatality 1 injured	0
	Two employees were involved in the crash of a recommercial flight as they were returning on official York City to Albany.		
72-8 A	3-17-72 RL—Douglas United Nuclear		
	It was reported that the widow of a former DUN emptor a widow's pension. It is alleged that her husband caused by asbestos. He was an insulation worker, estimate the before his health forced him to retire.	died of lung cancer	
72-9 A	4-3-72 OR—Union Carbide Corp. Nuclear Div.	0	\$6,000
(press release)	A small amount of radioactive contamination was spreareas of the Y-12 Plant Development Laborator contamination was a small, unencapsulated disk of powas being used in experiments. No contamination lebioassays performed on 11 employees were low excemployee who worked directly with the source. He exposure will be less than the annual permissible dose.	y. Source of the plonium 210 which ft the building and ept for that of the	
72-10 B	3-25-72 OR—Government	0	0
	Two boxcars carrying classified material and a dorr four miles south of Jellico, Tenn. There was no damage there were no injuries to the escorts. The boxcars we accessible by truck where the cargo was transferred. It to the facility of origin and reloaded for shipment by re-	e to AEC cargo and re pulled to a point t was then returned	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
72-11 A	4-11-72 ID-	-Aerojet Nuclear Corp.	0	0
(press release)	when radiatio and sealed. S into a normal tube received hose was rigge	smantling of an experiment, several more newels continued to rise, the reactor factource of the radioactivity was the leaked by clean lead tube. One employee who attain estimated exposure of 2 rem gammed over the top of the lead tube, radiation sotopes involved had a short half-life.	ility was evacuated age of fission gases tempted to seal the a. When a vacuum	
72-12 A (press	1-11-72 ID-	-Government	3 serious & 12 minor injuries	\$3,500
release)	AEC contract negotiate a dr the poor visit	re snow storm at the NRTS, an AEC to or collided with a stalled truck. The truck ift of snow which was partially blocking bility, the bus driver failed to see the but to avoid a collision.	k had attempted to g the road. Due to	
72-13 A (press	2-3-72 ID-	-Aerojet Nuclear Corp.	1 injured	0
release)	suspended by the platform	was replacing metal siding on a facility a mobile crane when, due to slippage of dropped approximately five feet. The the employee to the platform, thus fract	of the crane brake, sudden stopping	
72-14 A	5-2-72 SR	–E. I. du Pont de Nemours & Co.	1 fatality	0
	multiple rib f between a re employee had used to move	rvices engineer suffered shoulder and ractures, and a severe liver laceration who between the loader and four empt stepped between the loader and the ce the cars and when the cars kept roldied as a result of these injuries on May 3.	ty coal cars. The cars to free a cable ling, the accident	
72-15 B	5-7-72 SR-	-E. I. du Pont de Nemours & Co.	0	\$26,000
	this site was b	ved a radio transmitter building and all eing rented by the contractor to accommorological data. The recording equipment basis.	odate sensors used	
72-16 A	5-19-72 AL	-Ross Aviation	9 fatalities	
	after takeoff f	te to the Los Alamos Scientific Laborato From the Albuquerque International Airpwere fatally injured.		

No.1 - Type2	Date Field Office ³ - Contract	or Injuries ⁴ - Exposures	AEC Property Damage
72-17 B	3-25-72 ID—Aerojet Nuclear Corp.	0	\$49,200
	In the course of initiating core power Experiment and establishing initial conditions blowdown experiment on the system, all 1 of the 14 low-power heaters in the core were	itions prior to conducting a 5 high-power heaters and one	
72-18 A	5-19-72 RL—General Electric, Co.		
	Employee who died of lung cancer left a no result of a radiation exposure incident.	te stating that his death was a	
72-19 B	6-9-72 OR—Government	0	
	Leakage of natural uranium oxide during when a small quantity of the UO ₃ was number of drums of this material were be enroute the cars were humped. One of the punctured by a piece of metal on the floor spilled onto the floor leaked out the boxcar no health hazard to the public.	found outside the boxcar. A eing shipped and somewhere e drums broke loose and was r. Some of the powder which	
72-20 A	6-27-72 NV—Reynolds Electrical & Engin	eering Co. 1 fatality	
	A miner was killed instantly when he was rock. The employee was working on a scaftunnel when the slab fell on him.		
72-21 B	6-29-72 ID-Allied Chemical Corp.	0	
	A section of a state highway within contaminated when a 5-gallon plastic contastic solution (U-235) fell from the back of a procontamination were 2 to 3 mR/hr and 20,0 of the solution which spilled were absorbed evaporated. The residual contamination was	ainer of a low-level acid wash ickup truck. Highest levels of 000 c/m alpha. The 2½ gallons d by the asphalt and quickly	
72-22 A	6-22-72 AL—Sandia Laboratory	0	\$187,686
	AEC equipment valued at \$165,000 to \$200 Research Corporation premises in Baltimo heavy flood waters from Hurricane Agnes.		,
72-23 B	6-30-72 OR—Union Carbide Corp., Nuclea	ar Div. 1 exposed	
	A welder received an internal exposure and about the mouth when a uranyl nitrate attempting to unplug by heating with a temployee was treated for burns at the Oak home. The significance of the uranium countil the welder returned to work six days torso and his coveralls were found to be corgans were estimated at 5 rem to the lung 80 rem to the bone.	recycle line, which he was orch, suddenly ruptured. The Ridge Hospital and then sent ntamination was not realized after the incident. His upper ntaminated. Doses to the body	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
72-24 B	7-25-72	OR-Goodyear Atomic (GAT)	1 injured	0
	2½-ton Chilicot severe la	owned by Transportation Services, Inc., an cylinders of UF ₆ overturned on a sharp curve, Ohio. No other vehicles were involved. accrations on the forehead. The cylinders were was released.	ve on a detour near The driver received	
72-25 B	7-17-72	OR-Government	0	\$180
	Fernald, for inspe	hipment containing 72 drums of normal U Ohio, to Paducah, Ky., was found to be dam ection. The cargo had shifted during transit cambers used for shoring. A small material spill v	naged when opened using failure of the	
72-26 B	8-5-72	SAN-Atomics International	0	\$70,000
	primary brought and drai	n spray type fire occurred at an instrument sodium line at the Sodium Component Test under control in approximately 30 minutes ining the system and through the use others. Operations were delayed approximately	Installation. It was by depressurizing f three MET-L-X	
72-27 B	8-28-72	ID-Allied Chemical Corporation	0	0
	with con regulation that the	fuel shipment from Fort Greeley, Alaska, a tamination on internal surfaces of the vehicle ns. The shipment itself was free of contamina contamination was not caused by that shipme as involved.	e in excess of DOT ation. It is believed	
72-28 B	9-6-72	AL-Dow Chemical Co.	1 exposed	0
	leaked th	aployees were exposed to radioactive material arough holes in a faulty glove on a glovebox. Hoyee will receive an internal exposure in exposure in exposure was no significant surface contamination.	It is estimated that cess of the annual	
72-30 B	8-19-72	CH-Brookhaven National Laboratory	0	\$45,000
	magnet s	rical failure in the motor rotor occurred wit upply resulting in a forced shutdown of the to remove the equipment and send it to	accelerator. It was	
72-31 A	9-26-72	NV	0	0
(press release)	Amchitka	es Airlines passenger aircraft was damaged a when it struck four strobe lights near the e the 25 individuals aboard were injured.		

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
72-32 A	10-3-72	RL/OR-Government	0	0
(press release)	oxide ir assistanc	Four boxcars each containing 50 to 60 tons of slightly depleted uranium oxide in 55-gallon drums derailed near St. Paul, Minn. A radiological assistance team from Elk River inspected the shipment and found the drums intact.		
72-33 A	10-17-72	CH-Argonne National Laboratory	2	\$25,000
(press release)	10 gram the three and a b exposure	explosion occurred in a glovebox which containe s of material (98% uranium oxide and 2% pluto e employees involved, two were injured; one recoump on the head and another was cut on the es received by these three employees are below reair and soil samples indicated that no material less received by these three employees are below reair and soil samples indicated that no material less received by these three employees are below reair and soil samples indicated that no material less received by these three employees are below reair and soil samples indicated that no material less received by these three employees are below reair and soil samples indicated that no material less received by these three employees are below reair and soil samples indicated that no material less received by these three employees are below received by the second received by these three employees are below received by the second received received by the second received received by the second received rec	nium oxide). Of elived facial cuts e hand. Internal eportable limits.	
72-34 B	11-5-72	ID-Allied Chemical Co.	0	0
	contamir 173.397. d/m/100	fuel shipment from Ft. Worth, Texas, arrived an nation on the load-bearing surfaces in excess of The trailer had seven spots of contamination, cm ² , beta-gamma, and two spots, 5,000 to 3 ha. The contamination was not caused by that shipself.	DOT regulation 3,000 to 6,000 1,000 d/m/100	
72-36 B	9-18-72	OR-Union Carbide Corp., Nuclear Div., Paducah Gaseous Diffusion Plant	0	0
	revealed failed an	on of a truck shipment of a surplus screw reactor that temporary closure mechanisms used during that a spill of radioactive material from the road had occurred.	ing transit had	
72-37 B	4th Qtr.	AL-Los Alamos Scientific Lab.	1 exposed	0
	An empl while we the insul	oyee received a whole body exposure of 5.43 remorking on the Phermex machine. It is believed that or suring extensive radiation checks and tests duced X-rays which caused the exposure.	that sparking of	
72-38 A	12-16-72	AL-Mason & Hanger-Silas Mason Co., Inc.	1 injured	0
	grinding	ne shop employee received a head injury while wheel. There were no witnesses, but apparently end of the grinding wheel struck the employee	the shaft failed	
73-2 A	1-4-73	CH-Argonne National Lab.	1 fatality	0
	trouble-s amplifie	engineer was electrocuted during the cours thooting operations on high-voltage, high-power equipment in the ZGS Ring Building. Attempt were not successful and he was pronounced deital.	radiofrequency ots to revive the	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
73-3 A	1-10-73	CH-National Accelerator Lab.	1 fatality	-
	attempti 200 Bev jumper forward	o (subcontractor to NAL) employee was fing to start a compactor located in a trench site. A four-wheel drive vehicle was driven in wires could be connected. A short time late into the trench and pinned the deceased agoloyee died approximately 6 hours later due	across a road on the to the excavation so or, the vehicle rolled ainst the compactor.	
73-4 A	1-11-73	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	1 fatality	
	across a leg of the broke, the	enic was fatally injured while helping to roll set of railroad tracks in the locomotive reparate he platform was moving over the second thus causing the platform to topple. The fall assed on the head. Apparently, death was in aries.	air shop. As the last track, a caster stem ling platform struck	
73-7 A	1-7-8-73	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	0	\$393,000
	A sleet a	and ice storm damaged timber in the SRP pine	e forests.	
73-12 A	2-2-73	AL-Dow Chemical Co.	1 injured	and the same
(press release)	work are ignited, The pers the inhapparatu suffered were less	employees were working in supplied air suiters when a paper composition filter in a composition filter in a composition filter in a composition to the sonnel evacuated the areas immediately while alation of smoke that was coming through. During the evacuation, one employee fell a fractured skull. Whole body counts of the stan or only slightly higher than the minimpactive material was released to the environment.	amon air compressor working personnel. e seeking relief from ugh their breathing into a stairwell and employees involved turn detectable level.	
73-15 В	2-10-73	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina		\$95,000
		metal roof on a prefabricated metal building ation of snow. The building was used for sloment.		
73-16 A	2-12-73	SR-E. I. du Pont de Nemours & Co. Aiken, South Carolina	1 fatality	
	The emp	anic died from complications which resulted doyee suffered a fracture and dislocation of sital, he developed paralytic ileus and then p weeks after the fall.	a vertebra; while in	
73-17 B	3-13-73	AL-Mound Laboratory	1 exposed	Waterfor parallel
	following	contamination was detected on the hand g routine maintenance on a tritium waterline indicate a whole body exposure of approxima	in the SW building.	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
73-19 B	JanMar. 1973	ID-Allied Chemical Co.	1 exposed	
	1.1 rem	film badge pull for a pipefitter indicated beta. The exposure is believed to have of the waste calciner facilities.		
73-22 B	2-19-73	PNR-Westinghouse Electric Corp.	0	\$33,000
	overpress firebox.	back occurred during light-off of a boile sure on the burner side of the boiler, ca Apparently the flare-back was caused by owed an excess of fuel oil to accumulate in	using damage to the the delayed ignition	
73-23 A	1-73	SAN-University of California, LBL	0	\$212,000
	the LBL	slide damaged the Data Analysis and Bull. Remedial actions and cessation of heavy orward motion of the earthslide to approxima 13.	rains had slowed the	
73-26 B	4-14-73	SAN—Government	0	\$50
	5-ton, vanwhen the l stop on th	were transporting packages of radioactive type truck traveling west on I-40 near Lateft front tire blew out. The driver brought e left side of the road. A wheel rim traveled an oncoming car causing the property damage.	aguna, New Mexico t the truck to a safe d across the median	
73-27 A	5-2-73	OR-Goodyear Atomic Corp.	0	\$13,600
(press release)	attempting The leak w pounds of	of UF ₆ occurred in Building X-342 as to take a liquid sample of material from which lasted approximately 1/3 hour resulte material. The leak was stopped when one we with an emergency-valve plug.	a 10-ton cylinder. ed in the loss of 215	
73-30 B	5-21-73	ID—Allied Chemical Company	0	0
	arrived at	hipment by Tri-State truck from United I the ICPP with one particle of cobalt 60 of 16,000 d/m/100 cm ² . The trailor was defined to the company of the comp	on the trailer bed-2	
73-33 A	6-8-73 I	RL-Atlantic Richfield Hanford Co.	0	0
(press release)	tank 106 T The total 1 containing s strontium 9	vas informed by the contractor that a leak he in the T tank farm located in the 200 we oss of fluid to the ground was approximate approximately 40,000 curies of cesium 137, 00, 4 curies of plutonium and various fissiquid in the tank was removed from the 1	and occurred in the st area at Hanford. ely 15,000 gallons 7, 14,000 curies of the products. The	ū

No.1 - Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
73-34 A	6-15-73	CH-National Accelerator Laboratory	0	0
(press release)	Central Landscore Construction When vapor	and tar fire occurred during construction of aboratory and high rise office. Roof on Company were preparing to start up rs from an oil leak in one kettle ignited an and across the 2,100 square feet of the n	fers for Corbetta an oil-fired kettle d fire spread to the	
73-35 B	6-18-73	AL-Monsanto Research Corp.	1 exposed	\$300
	small amore factors cor which resu	yee received approximately 1.3 MPLB whom the of plutonium which was in a gloveboung point of air flow alted in the release of fine radioactive. Contamination was confined to the roof.	x. Evidently several w in the fume hood	
73-36 B	6-20-73	ID—Allied Chemical Company	0	0
	California, regulations had remov surface of up to 7 n identified. regulations was also caused by	fuel shipment from Atomics Internation arrived at the ICPP with contamination on the load-bearing surface of a flat-bed able contamination up to 4,000 d/m/100 d the cask and loose radioactive particles in the nr/hr. Cesium 137 and cobalt 60 were the In addition there were a number of other such as inadequate tie down of auxiliar contaminated. It is believed that the contaminated of the shipment. The surface of the shipment is a surface of the shipment of the shipment. The surface is a surface of the shipment of the shipment is a surface of the shipment.	in excess of DOT I trailer. The trailer cm² on the external he cask well reading he primary isotopes r violations of DOT ry equipment which tamination was not The tri-state trailer	
73-38 B	6-28-73	ID—Aerojet Nuclear Company	0	0
	the technicontamina regulations cesium 13	ripment from Battelle, Columbus Laborato ical area north (TAN) facilities of the lation in the recessed well of the trailor. The survey revealed smearable contaminated and Mn 54. The cask was contaminated adiological assistance was involved.	NRTS with general in excess of DOT nation identified as	
73-43 B	6-28-73	Headquarters	0	0
	gondola ca Palmerton, ore by bu apart spill Pennsylvar	arters division supervised the excavation a ars containing uranium ore from the Jim , Pennsylvania. The Commission had decid rial at Fernald, Ohio. While the cars were ling the uranium ore in a railroad yar nia. All the ore was retrieved, the damage and residue shipped to Fernald in another of	Thorpe mine near ed to dispose of the en route, one came d near Harrisburg, d car washed down	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
73-45 B)—Government	0	0
	plant to the responded as The AMTX	ailroad car carrying radiological waste from NRTS for burial was derailed. A radiologicand found no spread of contamination nor recar had two containers with a total of 70 ontained approximately 1 to 2 grams of mate	al assistance team lease of material. drums of waste.	
73-47 A (press	8-10-73 S	NR—General Electric Co., Knolls Atomic Power Lab., Schenectady, N.Y.	0	
release)	occurred du the vendor's This establis system used basin install sewer into a diate emerg	approximately 500 gallons of concentrating delivery by vendor. The spill took places truck to the sulfuric acid storage tank whed a syphoning effect which due to the pipe by the vendor allowed the acid to spill oned 5 years ago to retain such spills. The acid the and a small amount reached Glowegency actions included the erection of line acid. The creek returned rapidly to its	e as the pipe from yas disconnected. ping arrangement utside of a catch- id flowed from a see Creek. Imme- mestone dams to	
73-48 A	8-13-73 R	L—Government	0	\$50,000
(press release)	Although the destroy vege project being fighters was terrain. The AEC facility	ral lightning strikes started a fire on Rattle ere were no personnel or equipment in the etation which was part of a 100 sq. mile of conducted by Battelle Northwest. Initial hampered by the fire's remoteness from rost fire was at no time closer than approximate ities devoted to radiological waste that 7 miles from FFTF construction site.	area, the fire did ecological survey response by fire ads and the steep ely 8 miles from	
73-51 A	8-13-73 Al	L	0	0
	performed w allegation sta	d that a former employee of a construction ork at the Rocky Flats plant had contracted that the leukemia was a result of an "commetime between September 1962 and March	ed leukemia. The over flow" which	
73-53 A	9-17-73 A	L-Dow Chemical Co.	0	0
	Western Reso of the tritium Livermore La plant officials	els of tritium were found in Walnut Creel ervoir downstream from the Rocky Flats P n activity was material shipped to the plant aboratory in California in the spring of 197 s, the material was contaminated with trit plant process stream and plant waste water.	Plant. The source t from Lawrence 73. Unknown to ium, which then	
73-55 B	9-1-73 R	L-Atlantic Richfield Hanford Co.	0	\$35,950
	ignition of co	200 East Area Powerhouse resulted from oal in a storage bunker. The fire caused son but operations were not interrupted.		

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
73-56 A	9-24-73 CH	-Argonne National Laboratory, Argonne, Ill.	1 fatality	O
	tractor on the backwards ont	was found pinned under the rear who laboratory grounds. The tractor are the victim while he was examining the died in the hospital later that same of	pparently had rolled the attached mowing	
73-58 A	9-4-73 OR-	-Oak Ridge Associated Universities	2 exposed	0
	for diagnostic prepare a dose administered a uptakes of 19	tients were referred to the ORAU by I-131 uptake scans. The technician of 30 microcuries for each patient but dose of 284 microcuries. The 48 1% and 28% which correspond to exposure of 15 and 30 rad.	was instructed to due to human error hours scan showed	
73-59 A	10-5-73 OR-	-Union Carbide Corporation, Nuclear I	Div. 0	\$3,400
	gram quantitie discovered dur National Labo inventory of N of the inventor	oss of one nuclear accident dosimete s of plutonium, neptunium and del ing a routine health physics survey ratory. This occurrence prompted AD's in all installations under their juriy, three similar NAD's were unaccount tak Ridge Gaseous Diffusion Plant.	eted uranium, was at the Oak Ridge OR to require an sdiction. As a result	
73-60 A	10-20-73 OR-	-Union Carbide Corporation, Nuclear I	Div. 0	
	accident during When the cen	tal gas centrifuge model was virtual test stand operations at a centrifuge detrifuge model failed it damaged a nits and support pipings.	evelopment facility.	
73-61 B	9-12-73 SR-	E. I. du Pont de Nemours & Co.	0	Name of States
	Bureau of Star contaminated shipment was of of 24 smears v d/m, while the	ther carrying a loaded spent fuel cask indards reactor, Gaithersburg, Marylan above the DOT limits when the cask carried by a Tri-State Motor Transit Cowas over 5,000 d/m; the highest on the cask bottom was 41 hears were largely cobalt, ruthenium, 2	d was found to be was removed. The mpany. The average the side was 13,700 ,300 d/m. Materials	
73-63 A (press	10-14-73 AL-	-Mason and Hanger-Silas Mason, Co., In San Antonio, Texas	nc. 0	·
release)	employee. The employee had kept one sour Efforts to ret normally used	boys stole a brief case from the automore brief case contained three radioactive been using in a boy scout merit badge ce; the other sources were thrown rieve these sources were unsuccessful for drinking water or for swimmin two missing radioactive sources is below.	ive sources that the e program. One boy into a nearby lake. ul. The lake is not g. The quantity of	

No. ¹ · Type ²	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
73-64 B	11-14-73	RL-Atlantic Richfield Hanford Co. Richland, Washington	0	\$310,400
	radioact tank and 200 feet Hanford	chland Operations Office was informed by the ive waste solution had escaped from a 12-inch d spilled over the ground, covering an area of alt. The tank involved was located in the 200 W. Reservation. The area was secured and the spil to prevent the spread of contamination and to sposure.	riser in a waste bout 50 feet by est Area on the ill area covered	
73-67 A	11-21-73	NV-Reynolds Elec. & Eng. Co., Inc.	1 fatality	0
	two sec	actor employee was fatally injured when he was cations of 66-inch-diameter steel casings. One secoved by forklift rolled out-of-control and pinner a second section of casing. Probable cause of skull.	tion which was ed the deceased	
73-69 A (press	12-20-73	RL—Westinghouse Atomic Development Co. Richland, Washington	1 injured	
release)	a contai alcohol t	cal operator was injured while transferring a sam ner of hot sodium to an alcohol cleaning solu flashed. The employee received first and second of arm and chest. No radioactive material was invo	ution when the degree burns on	
73-70 B	12-26-73	CH-National Accelerator Laboratory	0	\$80,000
	Building welding Evident which amounts	occurred in the beam line extension of the Meso g. Preliminary information indicates the cause we operations being conducted inside the corrugaly the spark ignited the polyurethane foam insupenetrated the side wall of the building, prospectively of smoke and there was concern that this side some of the expensive electrical equipment in the	ras a spark from ted metal tube. lation. The fire, oduced copious moke may have	
74-3 A	1-16-74	RL—Battelle-Northwest	1 injured	0
	had clim complet from ab down w and thr injuries wearing	ployee who was working offsite for another Goverbed a meteorological tower to release several slacked this work and was on the way down the towout the 30 foot level. The employee hit a signal chich broke his fall at about the 10-15 foot level alow him clear of the concrete tower base. He and was temporarily, partially paralyzed. The his standard safety belt at the time of the acciding required that he tie himself off as he moved down	ernment agency k cables. He had ver when he fell able on the way bove the ground sustained neck employee was tent and normal	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
74-4 A	1-21-74	OR-Union Carbide Corporation Nuclear Division	0	0
	gross tr 100,000 a private the cyli pumped contami January 18 wher who had was fou	sturn to ORNL, a two-liter "empty" cylinder transferable tritium surface contamination of c/m/100 sq. cm. The cylinder had been ship e company for commercial use. The private coinder without contamination check, made out the tritium and returned the empty mation check to ORNL. The cylinder was received and was returned to the isotope sales depicted the either was surveyed and found contaminated. The distribution of the cylinder last were both sound to have high spots of tritium contaminated of sq. cm. The driver's urine tests were negative	of approximately pped from ORNL to mpany had received a pressure check, cylinder without a ceived by ORNL on partment on January the driver and trailer urveyed. The trailer ination up to 500	
74-8 A	2-18-74	HQ-N.Y. Health & Safety Lab.	1 exposed	0
	An employee was hospitalized for treatment of a swollen, blistered hand which resulted from a radiation exposure. The employee, a radiochemist, had been engaged in X-ray fluorescence analysis of metals and was removing a copper filter previously placed over the X-ray beam port when the exposure occurred. The radiation satety interlock circuit of the spectrometer had been inactivated and the employee did not believe the machine was operating. The employee received an exposure of 2,400 rad to 4,800 rad to the left hand and fingers resulting in serious injuries and 10 days lost time.			
74-10 A	2-25-74	SNR-General Elec. Co., Knolls Atomic Po Lab., Schenectady, N.Y.	ower 1 fatality	0
	Atomic property landfill	ear-old boy was fatally injured at the Kesselri Power Laboratory site. The boy, who was to y with two young friends, started a bulldoze area at the site and while he was operating the bank and overturned on him.	respassing on posted r parked in a remote	
74-19 B	3-28-74	ID—Tri-State Company	0	0
	measurin deliverin (Ohio) Ru-106.	State vehicle arrived at TRA-NRTS with ng 7 mr/hr on the floor of the closed trailing 19 empty ETR fuel element containers and Purdue University. Analysis indicated (i. It is not believed this fission product containshipment.	er van. Vehicle was from National Lead Ce-144, Cs-137, and	
74-27 A	5-2-74	SR-E. I. du Pont de Nemours & Co.	0	Classified
	resulted facility remaining Over 75 these sa	re of a stainless steel fiting in a process line in the release of approximately 50 grams stack. Stack monitors detected the activi- ing process material to be diverted to an eme- 60 environmental samples were collected and amples indicated activity above levels norma- els were not considered to be of concern from bint. Bioassay samples indicated no personnel	of tritium from the ity and caused the rgency holding tank. analyzed. Several of ally found; however, in a health and safety	

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
74-37 B	4-4-74 I	D-Allied Chemical Co.	0	\$82,500
	was discove pressure rel installation incorrect us tie-ins that which the subsequent decontaminate	avation of a construction site near the ICPP ared below a badly corroded and leaking 1 ief vent line. Although the line was part of and of material appropriate for the intendesse of this system with an associated vent appearmented backup of process waste through 12-inch vent line was drained) resulted in leak. Over 250 yd ³ of soil were leation operations. Less than 30 yd ³ ed to levels exceeding 25 rad/hr. The containsium-137 and strontium-90.	2-inch carbon steel of the original plant ed service, the later line and additional the stack drain (to the corrosion and removed during of this soil were	
74-43 A	7-15-74 A	AL—Los Alamos Scientific Laboratory	1 fatality	0
	electric sho a level of 3 source. The	al engineer was accidently electrocuted whick from a capacity bank and its support stra,400-5,000 volts, 18 OHz, a.c., from a low engineer was working on the control circumstance energized when the accident occurred.	ucture energized at impedence power	
74-45 A	7-13-74 I	RL—United Nuclear Industries	1 fatality	0
	hole in the about 10 is barricade in label on a badjacent to cover over properly plathe basement fracture of the employer	first floor of the building to the basement feet. It was concluded that the employed to a deactivated area of the building to expox of stock that had been placed in the cost a deactivated area. This action placed han opening in the floor. The cover, whaced, apparently shifted and allowed the ent below. The employee received a fracture clavicle and scalp and arm lacerations. On ee, while still in the hospital, died from conceived in the fall.	floor, a distance of ee stepped over a nable him to see a rridor immediately nim on a plywood ich had not been imployee to fall to of the right femer, October 13, 1974,	
74-50 B	7-31-74	OR—National Lead Co. of Ohio	1 exposed	0
	appeared the exposure from maximum Investigation cobalt-57 d March of 19 the residua	d Headquarters that based on prelimina nat a chemical operator at the Fernald plan om internally deposited depleted uranium permissible lung burden (MPLB) for n revealed that the employee received 0 uring an anemia test administered by his per 1973 and that subsequent to vivo counts were 1 cobalt-57. In vivo spectrum analysis is that no more than 50 percent of the MF	ry information, it nt sustained a lung in the range of 3-4 the past year. 0.5 microcuries of rsonal physician in re primarily due to indicated that the	

No.1 - Type2	Date Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
74-53 B	8-5-74 AL—Sandia Corp., Albuquerque, N A proof test utilizing 1.8 pounds of C4 expreinforced concrete, high pressure test cell in laboratory. The explosion resulted in the test blown off its hinges into the pressure laborat of overpressure caused damage to laboratory damage to the cell. Since the building had be before the test, no one was injured.	olosive was conducted in a the high pressure evaluation to cell steel blast door being ory. The subsequent release to equipment and structural	\$35,000
74-62 A	8-20-74 CH—Argonne National Lab. 4 injured This occurrence took place in the metallograph loading cell, a part of the Hot Fuel Examination Facility, during qualification testing which included leak testing with an argon atmosphere. A technician was observed lying on the floor of this loading cell by a second technician. The second technician called for assistance and entered the cell through the open access hatch to assist the first technician. An engineer technician, with the assistance of others, cut off four gloves at the rear of the cell to ventilate the cell and entered the cell through the top hatch to render assistance. They found both the first and second technician unconscious. The engineer technician also felt dizzy and was assisted from the cell after giving mouth-to-mouth resuscitation to the second technician. All three men, and a fourth man who injured his back in the rescue effort, were taken to the hospital. They were all discharged within 3 days with the full expectancy that there would be minimal residual effects.		0
74-66 A	9-24-74 AL—Zia Company, Los Alamos, New Mexico 1 fatality A contractor employee was seriously injured when the dump truck which he was driving overturned, pinning him under part of the truck bed. In addition, some of the hot asphalt material being carried in the truck bed was spilled on the employee. He sustained third degree burns over approximately 30 percent of his body, a broken leg, broken pelvis, and a ruptured bladder. On October 3, 1974, the employee died while still in the Bernalillo County Medical Burn Treatment Center.		0
74-74 A	A graduate research student received an expo the 3 mev proton beam of a Tandem Van de 0 in first and second degree burns over a 1 x 10 hand. The absorbed dose was estimated at 2.3 degree area, 4.6 x 10 ⁵ rads in the first degree a 10 ⁴ rads to the remainder of the exposed area	Graaff accelerator, resulting cm area on the back of the 3×10^6 rads in the second area, and $4.3 \times 10^3 - 4.3 \times 10^8$	0
74-75 A	12-2-74 OR—Union Carbide Corp., Nuclear Power at the Y-12 plant was interrupted becathe K-25 power distribution center. Power was but the chain of events resulting from the pactivated the electrical switchgear in the Malfunction of this equipment in turn resulte was contained in the switchgear room.	suse of a switching error at s restored within 1 minute, ower outage automatically Y-12 9201-4 Building.	\$170,000

No.1 - Type2	Date	Field Office ³ - Contractor	Injuries ⁴ - Exposures	AEC Property Damage
74-77 B	5-30-74	CH-Fermi National Laboratory	1 exposed	0
	-	orted to Headquarters that the film badge I that he received an exposure greater than 5 re	-	
74-79 B	12-29-74	Headquarters—Government	0	\$25,000
	13.8 KV building. of the owhile tedetermin	rical fault occurred in the 480 volt switchgear in 7/480 volt 1500 KVA load centers in the Ge Extensive damage to the switchgear resulted, an office building was without power for approximation of the electrical fault resulted from brother electrical contact assemblies on the draword of the electrical contact assemblies on the electrical contact as electric	rmantown office nd a large portion mately 15 hours led investigation eakage of one or	
75-1 B	1-13-75	SR-E. I. du Pont de Nemours & Co.	0	\$20,000
	Process I fire was running chloride breaching	courred in a plutonium feed preparation gloved. Development Laboratory of the Savannah River probably caused by a portable vacuum clear over a weekend. The fire had burned or melted bag covering a bag port in one end of the g the containment and opening the atmosphere of the room.	Laboratory. The ner that was left away a polyvinyl e glovebox, thus	

¹ Division of Operational Safety, USAEC Headquarters, Reference Number ² See appendix D ³ Abbreviations used for USAEC Field Offices:

AL	Albuquerque Operations Office
BH	Brookhaven Office
CH	Chicago Operations Office
GJ	Grand Junction Office
HA	Hanford Operations Office
НО	Headquarters
ID`	Idaho Operations Office
LAR	Lockland Aircraft Reactors Office
NV	Nevada Operations Office
NY	New York Operations Office
OR	Oak Ridge Operations Office
PNR	Pittsburgh Naval Reactors Office
RL	Richland Operations Office (Formerly HA)
SAN	San Francisco Operations Office
SNR	Schenectady Naval Reactors Office
SR	Savannah River Operations Office
SNPO-C	Space Nuclear Propulsion Office-Cleveland
SNPO-N	Space Nuclear Propulsion Office-Nevada

⁴ Lost-time injury as defined in American National Standards Institute ANS Z16.1-1967 Revision of Z16.1-1954-R1959) ⁵ These property loss figures are based on a current commercial cost of about 55φ per curie of tritium and therefore do not represent the actual classified loss figures.

⁶ Shipper assumed full liability for damage to the lading.

⁷This fatality is nonchargeable.

APPENDIX D CRITERIA FOR REPORTABLE INCIDENTS

APPENDIX D

CRITERIA

Criteria for the classification of radiation exposures and industrial accidents occurring through August 15, 1968, as Types A and B as contained in AEC Chapter 0502, "Reporting and Investigating Accidents and Radiation Exposures."

"TYPE A"

1. Radiation

- a. Exposure of the whole body of an individual to 25 rem or more of radiation; exposure of the skin of the whole body of an individual to 150 rem or more of radiation; exposure of the feet, ankles, hands, or forearms of an individual to 375 rem or more of radiation.
- b. Any unplanned release of radioactive material in concentrations which, if averaged over a period of 24 hours, would exceed 5000 times the limits specified for such materials in AEC appendix 0524, annex 1.
- c. Any release of radioactive material offsite where it is believed any member of the general population may have received an exposure greater than that set forth in AEC appendix 0524, II.2.
- d. Any accident in which an atomic or nuclear weapon (under the jurisdiction of AEC) is involved and where damage is inflicted to persons or private property.
- e. Any notice that an individual has received an estimated 25 rems or more of external whole-body radiation during a calendar year.
- f. Any injury or industrial illness following cumulative or massive exposure to internal or external ionizing radiation which might reasonably be expected to have caused the illness or injury and when so diagnosed by a physician competent in nuclear medicine.
- g. Allegations that persons previously employed by AEC or its contractors are disabled from injuries or diseases incurred as a result of radiation or exposure to toxic materials which are peculiar in kind or degree to atomic energy operations.

2. Injury or Death

- a. Any fatal or imminently fatal injury or illness of industrial origin associated with an AEC activity of an AEC or contractor employee or a member of the public in an accident or fire.
 - b. Any other injury or industrial illness of five or more persons in an AEC operation.
- c. Allegations that persons previously employed by AEC or its contractors died from or were injured as a result of their duties in atomic energy operations.

3. Loss

- a. Estimated loss or damage to Government property amounting to \$100,000 or more or estimated costs of \$100,000 required for cleaning, renovating, replacing, or rehabilitating structures, equipment, or property.
- b. Any apparent loss or theft of radioactive material in such quantities and under such circumstances that it is believed there may result a substantial hazard to the health and safety of individuals.

4. Public Interest

a. Any accident or radiation exposure of any kind which gives rise to an inquiry by members of the public or press, providing that after initial analysis by a field office, it is considered of sufficient importance to notify Headquarters.

- b. Any accident or radiation exposure of any kind which the field office manager believes to have public information significance or where a press release has been made either by the field office or AEC contractor.
 - c. Any incident where radiological assistance has been requested as defined in AEC chapter 0526.

"TYPE B"

1. Radiation Exposures

- a. Any radiation exposure which in one calendar quarter exceeds the following:
 - (1) 3 rem to the external whole body.
 - (2) 10 rem to skin of whole body or thyroid.
 - (3) 25 rem to the hands, forearms, feet, or ankles.
- b. Any radiation exposure which causes an individual's cumulative dose to exceed (N-18)5* rem whole-body penetrating radiation.
- c. Any internal body deposition of radioactive material where, on the basis of a small number of early biological assay results, the estimated exposure averaged over a period of one year will exceed the standards set forth in AEC chapter 0524.

2. Accidents

- a. Loss or damage to Government property of \$5,000 to 99,999 where costs are incurred for cleaning, renovating, replacing, repairing, or rehabilitating structures, equipment or property.
 - b. Any vehicle transporting radioactive material that is:
 - (1) involved in an offsite accident.
 - (2) found to be contaminated (beta-gamma radiation on the interior surface of the vehicle exceeding 10 millirem in 24 hours, or alpha contamination greater than 500 disintegrations per 100 square centimeters per minute) on arrival at an AEC facility.
- c. Any shipment of radioactive material that arrives at an AEC facility damaged to the extent that there is substantial reduction in effectiveness of the package.

CRITERIA

Criteria for the classification of radiation exposures and industrial accidents occurring beginning August 16, 1968, as Types A and B are contained in revised AEC Chapter 0502, "Notification, Investigation, and Reporting of Occurrences."

"TYPE A"

1. Incident (Accident)

- a. Any fatal or imminently fatal occupational injury or occupational illness involving an AEC or AEC contractor employee or a member of the public due to an accident or fire associated with an AEC or AEC contractor operation.
- b. Any other disabling injury or occupational illness of five or more persons as a result of one occurrence in an AEC or AEC contractor operation.
- c. Estimated loss or damage to AEC or other property amounting to \$100,000 or more or estimated costs of \$100,000 or more required for cleaning (including decontamination), renovating, replacing, or rehabilitating structures, equipment, or property.
- d. Any occurrence involving a nuclear weapon or device (under jurisdiction of AEC) where there is personal injury or damage to private property.
- 2. Loss of Material. Any apparent loss or theft of byproduct or other radioactive material in such quantities and under such circumstances that it could constitute a hazard to the health and safety of individuals. Where this involves the possible theft of Government property, the FBI shall be notified (for a decision as to acceptance of investigation jurisdiction).

^{*}N equals the age in years at last birthday.

3. Radiation Exposure

- a. A single or annual accumulated whole body exposure of an individual to 25 rem or more of radiation, a single exposure of the skin of the whole body of an individual to 150 rem or more of radiation, or a single exposure of the feet, ankles, hands, or forearms of any individual to 375 rem or more of radiation.
- b. Any release of radioactive material in concentrations which, if averaged over a period of 24 hours, would exceed 5000 times the limits specified for such materials in appendix 0524, II, B.
- c. Any release of radioactive material offsite where it is believed any member of the general population may have received an exposure greater than that set forth in appendix 0524, II, B.
- d. Any injury or occupational illness following exposure to internal or external ionizing radiation which might reasonably be expected to have caused the illness or injury and when so diagnosed by a physician competent in nuclear medicine.

4. Other

- a. Any occurrence which is likely to give rise to an inquiry by members of the public or press, if the field office manager involved considers the inquiry to be of sufficient importance to notify Headquarters.
- b. Any occurrence which the field office manager believes to have public information significance or where a press release has been made either by the field office or AEC contractor.
- c. Any allegation that persons previously employed by AEC or its contractors died from, or were injured as a result of, their duties in an AEC or AEC contractor operation.
- d. Any allegation that persons previously employed by AEC or its contractors are disabled from injuries or diseases incurred as a result of exposure to radiation or to toxic materials which are peculiar in kind or degree to atomic energy operations.
- e. Any radiological assistance occurrence. Notification and reporting of a radiological occurrence which is not also a Type A occurrence specified in 1., 2. or 3., above, shall be in accordance with the provisions of part V.

"TYPE B"

1. Incident (Accident)

- a. Loss or damage to AEC or other property of \$25,000 to \$99,999 where loss or costs are incurred for cleaning (including decontamination), renovating, replacing, repairing, or rehabilitating structures, equipment, or property.
 - b. Any vehicle transporting radioactive material that is:
 - (1) involved in an offsite accident.
 - (2) found, on arrival at an AEC or AEC contractor facility, to be contaminated (internal surfaces of vehicle) above the limits specified in section 173.397, "Contamination Control," of the Department of Transportation Regulation, 49 CFR 173.
- c. Any shipment of radioactive material that arrives at an AEC or AEC contractor facility damaged to the extent that there is substantial reduction in the effectiveness of the package.

2. Radiation Exposure

- a. Any radiation exposure to an individual which in one calendar quarter exceeds the following:
 - (1) 5 rem to the whole body.
 - (2) 30 rem to skin of whole body or thyroid.
 - (3) 75 rem to the hands, forearms, feet, or ankles.
- b. Any radiation exposure which causes an individual's cumulative dose to exceed 5(N-18)* rem whole-body radiation.
- c. Any internal uptake of radioactive material which on the basis of a small number of early assay data will result in a dose or dose commitment in excess of the pertinent annual standard set forth in chapter 0524.

^{*}N equals the age in years at last birthday.